

EXL Repairer Service Ltd

St Clare House, 30-33 Minories, London, EC3N 1DD

Full Report

Created: 18/12/2025

Assessment Number: XYZ123456

Summary Information

Claim

Authorisation Status: Authorised Date of Incident: 03/12/2025

Work Provider: TTH EXL Indirect Able to Authorise Repairs: TBA

Claim Reference: 2025/ABC/12345 Repairs Authorised?: TBA

Policy Number: VAT Status: Non Taxable

Other Reference: Repairer: Approved

Vehicle Details

Manufacturer: MERCEDES Model: SPRINTER 313 CDI WD

Engine: 1.6LTT 66KW Registration Number: ABC1234

Registration Year: 2012 Odometer: 24367 miles

Colour: White Build date: From J55678

Audatex System Using Manufacturer Times

Assessment Number: XYZ123456 Full Report

Repair Information

LABOUR Time Basis 10 WU=1HR.

Repair/Guide

Number	Description	Work Units
88-3231 01	R + R RIGHT MIRROR	3
88-3231 01	RENEW R/DOOR MIRROR (REMOVED)	4
INCLUDES: ASSEMBLE MIRROR		
1000	REPAIR UTILITIES ALLOWANCE	15
1000	CHECK AND QUALITY CONTROL	5
1000	CHECK AND PRECHECK	3
1000	CHECK TECHNICAL INFO	5
1000	CHECK AND VALET	13
1000	CHECK FINAL INSPECTION	5
1000	CHECK VEH DIAG PRE CHECK	10
1000	CHECK VEH DIAG POST CHECK	10
1000	CHECK AND ROAD TEST	5
1000	ALLOWANCE OLDER VEHICLE	10
1000	CHECK ADAS APPLICATION FEE	5
Total Work Units		93

Assessment Number: XYZ123456 Full Report

EXTRAS

Description	Price
E.P.A. Charge	GBP 30.00
Car Care Kit	GBP 10.00
Pas Uplift	GBP 40.00
Estimate Fee	GBP 70.00
Pre-Repair Cleaning Charge (Inc Sanitation Methods)	GBP 50.00
Personal Belongings	GBP 30.00
Environmental Levement	GBP 25.00
Energy Cost Supplement and Sustainability	GBP 25.00
Standard Vehicle Shut Down	GBP 80.00
Yard Charge	GBP 70.00
Repair Method Research Charge	GBP 100.00
Total Extras	GBP 536.00

NB- COLOUR CODED ITEMS/TRIM-PART NUMBERS MAY DIFFER

Claim Details: Insurer: EXL INSURER Insured: John Smith

Audatex System Using Manufacturer Times