The key code of ultrasonic ranging:
Begin
Trig←Low; Delay 2us;
Trig←High; Delay 10 us;
Distance←pulseIn(Echo,HIGH);
distance←distance*58;
END