





P6
KF2EDGR-3.5-2Pin

P7
Header
To LoadBoard









Attention!
Load board MUST isolate the PWM signals! Otherwise there are some strange things happening

Quad-Channel:
 $\pi 140(M/E)3x/ISO7040$
Triple-Channel: $\pi 130(M/E)3x$
Dual-Channel: $\pi 120(M/E)3x$
Single-Channel: $\pi 110(M/E)3x$

--> Mit PSU I/O immer +1 kanal:
 $\pi 160M60$

Last Modification: 07.06.2026	@4R3Nginereng 
Document: EVG_Controller.SchDoc	
Project: DALI_EVG_Controller.PrjPcb	
Variant: V0.2	





Last Modification:	07.06.2026
Document:	CH32V003.SchDoc
Project:	DALI_EVG_Controller.PrjPcb
Variant:	V0.2




C7...C10
Bypass-Caps für GND-LF

FB2/FB3/C2:
HF-Noise Filtering



DALI Receiver




DALI Sender

Last Modification:
07.06.2026
Document:
DALI_Phy.SchDoc
Project:
DALI_EVG_Controller.PrjPcb
Variant:
V0.2

@4R3Ngineering





System is designed to stay under 2mA standby current (can be measured via R27)

R27 doubles as inrush limiter

CMI321609X100KT has a maximum current rating of 25mA!
--> +3V3-D must not be loaded more than 25mA
NLV32T-100J-PF would be 150mA

Possible Alternatives for IC1:
LMR51410
LV2862Y

Last Modification:
07.06.2026
Document:
PWR.SchDoc
Project:
DALI_EVG_Controller.PrjPcb
Variant:
V0.2

@4R3Ngineering