



**GAA15CA203** 

# **Aviation Investigation Final Report**

Location: Hazleton, Pennsylvania Accident Number:

Date & Time: July 23, 2015, 19:00 Local Registration: N518JW

Aircraft: WELCH FLOYD L QUICKIE Q 2 Aircraft Damage: Substantial

**Defining Event:** Loss of control on ground **Injuries:** 1 None

Flight Conducted Under: Part 91: General aviation - Personal

### **Analysis**

The pilot reported that after the initial touch down the airplane had a "left turning tendency", veered off the runway to the left into deep grass, and nosed over.

The pilot reported there were no pre-impact mechanical failures or malfunctions with the airframe or engine that would have precluded normal operation. The airplane sustained substantial damage to the left main wing.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's failure to maintain directional control during the landing roll, which resulted in a runway excursion and nose over.

#### **Findings**

Personnel issues Aircraft control - Pilot

Aircraft Directional control - Not attained/maintained

### **Factual Information**

### History of Flight

Landing-landing roll	Loss of control on ground (Defining event)
Landing-landing roll	Runway excursion
Landing-landing roll	Nose over/nose down

#### **Pilot Information**

Certificate:	Private	Age:	28
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	4-point
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Without waivers/limitations	Last FAA Medical Exam:	April 21, 2015
Occupational Pilot:	No	Last Flight Review or Equivalent:	July 16, 2015
Flight Time:	(Estimated) 54 hours (Total, all aircraft), 0.5 hours (Total, this make and model), 9 hours (Pilot In Command, all aircraft), 25 hours (Last 90 days, all aircraft), 5 hours (Last 30 days, all aircraft)		

### Aircraft and Owner/Operator Information

Aircraft Make:	WELCH FLOYD L	Registration:	N518JW
Model/Series:	QUICKIE Q 2 Q2	Aircraft Category:	Airplane
Year of Manufacture:	2005	Amateur Built:	Yes
Airworthiness Certificate:	Experimental (Special)	Serial Number:	001
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	March 9, 2015 Condition	Certified Max Gross Wt.:	1000 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	85.1 Hrs as of last inspection	Engine Manufacturer:	REVMASTER
ELT:	C91 installed, not activated	Engine Model/Series:	2100D
Registered Owner:		Rated Power:	75 Horsepower
Operator:		Operating Certificate(s) Held:	None

Page 2 of 4 GAA15CA203

### Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KAVP,930 ft msl	Distance from Accident Site:	24 Nautical Miles
Observation Time:	22:54 Local	Direction from Accident Site:	29°
<b>Lowest Cloud Condition:</b>	Few / 7500 ft AGL	Visibility	10 miles
Lowest Ceiling:		Visibility (RVR):	
Wind Speed/Gusts:	5 knots /	Turbulence Type Forecast/Actual:	/ None
Wind Direction:	350°	Turbulence Severity Forecast/Actual:	/ N/A
Altimeter Setting:	29.93 inches Hg	Temperature/Dew Point:	26°C / 9°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Hazleton, PA (HZL )	Type of Flight Plan Filed:	None
Destination:	Hazleton, PA (HZL )	Type of Clearance:	None
Departure Time:	18:30 Local	Type of Airspace:	Class G

### **Airport Information**

Airport:	HAZLETON RGNL HZL	Runway Surface Type:	Asphalt
Airport Elevation:	1603 ft msl	<b>Runway Surface Condition:</b>	Dry
Runway Used:	28	IFR Approach:	None
Runway Length/Width:	4898 ft / 100 ft	VFR Approach/Landing:	Full stop;Traffic pattern

## Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	40.986389,-75.986946(est)

Page 3 of 4 GAA15CA203

#### **Administrative Information**

Investigator In Charge (IIC): Vanover, Jackie

Additional Participating Persons: HARRY SOUDAS; FAA; Allentown, PA

Original Publish Date: September 11, 2015

Note: This accident report documents the factual circumstances of this accident as described to

the NTSB.

Investigation Docket: <a href="https://data.ntsb.gov/Docket?ProjectID=91671">https://data.ntsb.gov/Docket?ProjectID=91671</a>

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

Page 4 of 4 GAA15CA203