

# Seagen (Chibuzor B5, B1) - Installation Report # 17299 - 12/2/2021

| Reference # | Room               | Item<br>Quantity | Item to be fastened                   | Kit #       | Kit name                                                             | Kit price | Extension | Install<br>Labor | Extension |
|-------------|--------------------|------------------|---------------------------------------|-------------|----------------------------------------------------------------------|-----------|-----------|------------------|-----------|
| 403746      | B1 S110            | 1                | Freezer to Wall (Not in place yet)    |             |                                                                      |           | 0.00      | 0.00             | 0.00      |
| 403745      | IN-114             | 1                | Dbl Stack Incubator to Wall           | W.7HPBSS.4  | (4) Push Button StrutSTRAPs ,w/7" plate and 3301 bracket for stopper | 226.60    | 226.60    | 78.75            | 78.75     |
| 403748      | (Z) Administration | 1                | Project management and deployment fee | SU.ADMIN.10 | 10% on site admin fee on labor charge per invoice                    | 0.00      | 0.00      | 50.00            | 50.00     |

QuakeHOLD! Industrial, Inc.  
420 South 96th street, unit 4  
Seattle, WA 98108  
206-445-2738 Tom Woertz

Total Products: \$226.60  
Total Labor: \$128.75  
Freight: \$30.17  
Total Tax: \$39.71  
Seagen (Chibuzor B5, B1) - Grand Total: \$425.23

Water Pipe and/or other services behind obstructions: Under this agreement, it is the responsibility of Company to supply QUAKEHOLD INDUSTRIAL the location of any piping or rebar post tension cabling that could be obstructed from normal means of detection such as pipes behind metal studs or in concrete slab post tension cable for any and all work areas under contract of services. QUAKEHOLD INDUSTRIAL will coordinate with facilities staff to ensure all workers of QUAKEHOLD INDUSTRIAL are aware of any services or impediments that will affect the placement of our seismic fastening systems.