




嵌入式系統設計概論與實作

曾煜棋、吳昆儒

National Yang Ming Chiao Tung University



Last week

□ 嵌入式應用

- 距離資訊 (ex: 倒車雷達...)
- 溫溼度資訊 (ex: 空氣清淨機, 寶寶攝影機...)

□ Raspberry Pi

- GPIO introduction
- Python
- 超音波: HC-SR04
- 溫溼度: DHT-11




Ultrasonic

DHT-11





Thermometer + Hygrometer



This week


- 嵌入式應用: 人體活動偵測
 - 加速度、陀螺儀...等
- GY801 (I2C sensor)
 - 3-axis Accelerometer, Gyroscope, magnetometer and pressure
 1. ADXL345 : Accelerometer
 2. L3G4200 : Gyroscope
 3. HMC5883 : Magnetometer
 4. BMP085 : Pressure







Outline


- 嵌入式應用: 人體活動偵測
 - 加速度、陀螺儀...等
- GY801 (I2C sensor)
 - 3-axis Accelerometer, Gyroscope, magnetometer and pressure
 1. ADXL345 : Accelerometer
 2. L3G4200 : Gyroscope
 3. HMC5883 : Magnetometer
 4. BMP085 : Pressure






GY-801 (10 DoF sensor)


Compass (HMC5883L)




Gyro (L3G4200D)




G-sensor (ADXL345)








Pressure (BMP085)






How MEMS Accelerometer, Gyroscope, Magnetometer Work





Sensor - Accelerometer




When you move the sensor, the distance (**capacity**) is changed.


We **use capacity to calculate acceleration**.




Sensor - Gyro




When you rotate the sensor, Coriolis Force change the distance (**capacity**).
We **use capacity to calculate Angular velocity (角速度)**.




Sensor - Magnetometer



基於磁場變化
(a)電壓隨著霍爾效應發生變化



基於磁場變化
(b)MR元件的電阻發生變化



基於磁場變化
(c)利用脈衝電流檢測線圈電壓




Magneto Resistance 磁阻效應感測器


cost compassing and magnetometry. The HMC5883L includes our state-of-the-art, high-resolution HMC118X series magneto-resistive sensors plus an ASIC containing amplification, automatic degaussing strap drivers, offset cancellation, and a 12-bit ADC that enables 1° to 2° compass heading accuracy. The I²C



Sensor - Pressure



當 $R_3/R_1 = R_G/R_2$ 時，電橋平衡，檢流計無電流通過。
對於電流是否經過非常敏感，可以獲取頗精確的測量。



表面擴散雜質形成電阻橋電路(Wheatstone bridge)，
施加壓力產生的變形會影響電阻值，進而來計算壓力(氣壓)。



Piezo-Resistive 壓阻式感測器


The BMP085 is based on piezo-resistive technology for EMC robustness, high accuracy and linearity as well as long term stability.




↓ 這個念square喔!!

What is I2C?

- I2C全名為Inter-IC，它是一種半雙工同步多組設備匯流排，只需要兩條信號線：串列資料線 (SDA) 及串列時脈線 (SCL)。




- 在傳送資料過程中共有三種類型信號，分別是：開始信號、結束信號和應答信號。
 - 開始信號：SCL為高電位時，SDA由高電位降為低電位，開始傳送資料。
 - 結束信號：SCL為高電位時，SDA由低電位升為高電位，結束傳送資料。
 - 應答信號：收到 8bit 資料後，向發送資料的IC發出特定的低電位脈衝
- 資料讀取方式：
 - 當 SCL 由低電位升為高電位時，讀取 SDA 的資料。



Enable I2C on Raspberry Pi

- Enter the command : **sudo raspi-config**
 - Select **5 Interfacing Options**



```
Raspberry Pi 3 Model B Rev 1.2



Raspberry Pi Software Configuration Tool (raspi-config)

1 Change User Password Change password for the 'pi' user
2 Network Options Configure network settings
3 Boot Options Configure options for start-up
4 Localisation Options Set up language and regional settings to match your
5 Interfacing Options Configure connections to peripherals
6 Overclock Configure overclocking for your Pi
7 Advanced Options Configure advanced settings
8 Update Update this tool to the latest version
9 About raspi-config Information about this configuration tool

<Select> <Finish>
```

Connect I2C sensor

- VCC Pin 1 (3.3V), Red line
- GND Pin 9 (Ground), Black line
- SCL Pin 5 (SCL), Yellow line
- SDA Pin 3 (SDA), Green line



fritzing

The resistors are build-in on circuit. (you can skip them)



Check I2C sensor

- Install I2C tool to check the state:

- **sudo apt-get install i2c-tools**

- Command 1

- **sudo ls -al /dev/*i2c***


```
pi@raspberrypi:~$ sudo ls -al /dev/*i2c*
crw-rw---- 1 root i2c 89, 1 Mar 7 03:39 /dev/i2c-1
```

- Command 2

- **sudo i2cdetect -y 1**

Show the I2C address

```
pi@raspberrypi:~$ sudo i2cdetect -y 1
      0  1  2  3  4  5  6  7  8  9  a  b  c  d  e  f
00: -- -- -- -- -- -- -- -- -- -- -- -- -- -- -- --
10: -- -- -- -- -- -- -- -- -- -- -- -- -- -- -- --
20: -- -- -- -- -- -- -- -- -- -- -- -- -- -- -- --
30: -- -- -- -- -- -- -- -- -- -- -- -- -- -- -- --
40: -- -- -- -- -- -- -- -- -- -- -- -- -- -- -- --
50: -- -- 53 -- -- -- -- -- -- -- -- -- -- --
60: -- -- -- -- -- -- 69 -- -- -- -- -- -- -- --
70: -- -- -- -- -- -- 77 -- -- -- -- -- -- -- --
```



Check I2C sensor – part2

- If no I2C device

- Command 1


- sudo ls -al /dev/*i2c*

```
pi@raspberrypi:~$ ls -al /dev/*i2c*
ls: cannot access /dev/*i2c*: No such file or directory
```

- Command 2


- sudo i2cdetect -y 1


```
pi@raspberrypi:~/gy801$ sudo i2cdetect -y 1
      0  1  2  3  4  5  6  7  8  9  a  b  c  d  e  f
00: --
10: --
20: --
30: --
40: --
50: --
60: --
70: --
```



Outline

- 嵌入式應用: 人體活動偵測
 - 加速度、陀螺儀...等
- GY801 (I2C sensor)
 1. 3-axis Accelerometer, Gyroscope, magnetometer and pressure
 2. ADXL345 : Accelerometer
 3. L3G4200 : Gyroscope
 4. HMC5883 : Magnetometer
 5. BMP085 : Pressure






1. Accelerometer (ADXL345)

□ ADXL345



- Chipset : ADXL345
- Power : 3 ~ 5V
- Protocol : I2C/SPI
- Range : $\pm 2g$ 、 $\pm 4g$ 、 $\pm 8g$ 、 $\pm 16g$


Parameter	Test Conditions	Min	Typ ¹	Max	Unit
OUTPUT RESOLUTION	Each axis				
All g Ranges	10-bit resolution		10		Bits
$\pm 2 g$ Range	Full resolution		10		Bits
$\pm 4 g$ Range	Full resolution		11		Bits
$\pm 8 g$ Range	Full resolution		12		Bits
$\pm 16 g$ Range	Full resolution		13		Bits
SENSITIVITY	Each axis				
Sensitivity at X_{OUT} , Y_{OUT} , Z_{OUT}	All g -ranges, full resolution	230	256	282	LSB/ g
	$\pm 2 g$, 10-bit resolution	230	256	282	LSB/ g
	$\pm 4 g$, 10-bit resolution	115	128	141	LSB/ g
	$\pm 8 g$, 10-bit resolution	57	64	71	LSB/ g
	$\pm 16 g$, 10-bit resolution	29	32	35	LSB/ g
Sensitivity Deviation from Ideal	All g -ranges		± 1.0		%
Scale Factor at X_{OUT} , Y_{OUT} , Z_{OUT}	All g -ranges, full resolution	3.5	3.9	4.3	mg/LSB
	$\pm 2 g$, 10-bit resolution	3.5	3.9	4.3	mg/LSB
	$\pm 4 g$, 10-bit resolution	7.1	7.8	8.7	mg/LSB
	$\pm 8 g$, 10-bit resolution	14.1	15.6	17.5	mg/LSB
	$\pm 16 g$, 10-bit resolution	28.6	31.2	34.5	mg/LSB
Sensitivity Change Due to Temperature			± 0.01		%/°C



1. Accelerometer (ADXL345)

□ Output Response and Orientation






1. Accelerometer code

- Sample code results:

```
pi@raspberrypi:~/gy801$ python lacc.py
ACC:
x = 0.498 m/s2
y = -0.306 m/s2
z = -10.343 m/s2
x = 0.051G
y = -0.031G
z = -1.055G
x = 0.000
y = -8.000
z = -270.000
```



1. Accelerometer code: define address

```
bus = smbus.SMBus(1); # 0 for R-Pi Rev. 1, 1 for Rev. 2


EARTH_GRAVITY_MS2      = 9.80665 # m/s2

# the following address is defined by datasheet
ADXL345_ADDRESS        = 0x53 # I2C address

ADXL345_BW_RATE         = 0x2C # Data rate and power mode control
ADXL345_POWER_CTL       = 0x2D # Power-saving features control
ADXL345_DATA_FORMAT     = 0x31 # Data format control
ADXL345_DATAX0          = 0x32
ADXL345_DATAX1          = 0x33
ADXL345_DATAY0          = 0x34
ADXL345_DATAY1          = 0x35
ADXL345_DATAZ0          = 0x36
ADXL345_DATAZ1          = 0x37
# ----- 

# set value
ADXL345_SCALE_MULTIPLIER= 0.00390625    # G/LSB. 1/256 = 0.00390625
ADXL345_BW_RATE_100HZ   = 0x0A            # 0A = 0000 1010
ADXL345_MEASURE          = 0x08            # 08 = 0000 1000
```

When accessing I2C sensor, we have to write code based on datasheet. 21



1. Accelerometer spec.

REGISTER MAP

Table 19.

Address		Name	Type	Reset Value	Description
Hex	Dec				
0x32	50	DATAX0	R	00000000	X-Axis Data 0
0x33	51	DATAX1	R	00000000	X-Axis Data 1
0x34	52	DATAY0	R	00000000	Y-Axis Data 0
0x35	53	DATAY1	R	00000000	Y-Axis Data 1
0x36	54	DATAZ0	R	00000000	Z-Axis Data 0
0x37	55	DATAZ1	R	00000000	Z-Axis Data 1

Register 0x32 to Register 0x37—DATAX0, DATAX1, DATAY0, DATAY1, DATAZ0, DATAZ1 (Read Only)

These six bytes (Register 0x32 to Register 0x37) are eight bits each and hold the output data for each axis. Register 0x32 and Register 0x33 hold the output data for the x-axis, Register 0x34 and Register 0x35 hold the output data for the y-axis, and Register 0x36 and Register 0x37 hold the output data for the z-axis. The output data is twos complement, with DATAx0 as the least significant byte and DATAx1 as the most significant byte, where x represent X, Y, or Z. The DATA_FORMAT register (Address 0x31) controls the format of the data. It is recommended that a multiple-byte read of all registers be performed to prevent a change in data between reads of sequential registers.



1. Accelerometer code: read/write byte data

```
def write_byte(self, adr, value):
    bus.write_byte_data(self.ADDRESS, adr, value)

def read_byte(self, adr):
    # read_byte_data: read one byte from "self.ADDRESS", offset "adr"
    return bus.read_byte_data(self.ADDRESS, adr)

def read_word(self, adr, rf=1):
    # rf=1 Little Endian Format, rf=0 Big Endian Format
    if (rf == 1):
        # read two byte data. ex: addr 50 and 51
        low = self.read_byte(adr)
        high = self.read_byte(adr+1)
    else:
        high = self.read_byte(adr)
        low = self.read_byte(adr+1)

    # combine "high" and "low" byte together.
    # shift "high" to left by 8 bits, then put "low"
    # like this: HHHH HHHH  LLLL LLLL
    val = (high << 8) + low

    return val
```

Convert 16bit to 2's complement

```
def read_word_2c(self, adr, rf=1):
    # adr = register address. ex: set "0x32", then "adr" is equal to 50
    val = self.read_word(adr, rf)

    if(val & (1 << 16 - 1)):
        return val - (1<<16)
    else:
        return val
```




1. Accelerometer code: write value to specific address

```
# Register 0x2C: BW_RATE
self.write_byte(ADXL345_BW_RATE, ADXL345_BW_RATE_100HZ)
# write value= 0xA = 0000 1010
# D3-D0: The default value is 0xA,
# which translates to a 100 Hz output data rate.

# Register 0x2D: POWER_CTL
self.write_byte(ADXL345_POWER_CTL, ADXL345_MEASURE)
# write value: 0x8 = 0000 1000
# D3=1: set 1 for measurement mode.

# Register 0x31: DATA_FORMAT
self.write_byte(ADXL345_DATA_FORMAT, self.df_value)
# write value=0000 1000
# D3 = 1: the device is in full resolution mode,
# where the output resolution increases with the g range
# set by the range bits to maintain a 4 mg/LSB scale factor.
# D1 D0 = range. 00 = +-2g
```



1. Accelerometer code: write value to specific address

```
# Register 0x2C: BW_RATE
self.write_byte(ADXL345_BW_RATE, ADXL345_BW_RATE_100HZ)
# write value= 0x0A = 0000 1010
# D3-D0: The default value is 0x0A,
# which translates to a 100 Hz output data rate.
```

Register 0x2C—BW_RATE (Read/Write)

D7	D6	D5	D4	D3	D2	D1	D0
0	0	0	LOW_POWER	Rate			

LOW_POWER Bit


D3D2D1D0 = 1010

A setting of 0 in the LOW_POWER bit selects normal operation, and a setting of 1 selects reduced power operation, which has somewhat higher noise (see the Power Modes section for details).

Rate Bits

These bits select the device bandwidth and output data rate (see Table 7 and Table 8 for details). The default value is 0x0A, which translates to a 100 Hz output data rate. An output data rate should be selected that is appropriate for the communication protocol and frequency selected. Selecting too high of an output data rate with a low communication speed results in samples being discarded.

Output Data Rate (Hz)	Bandwidth (Hz)	Rate Code	I _{DD} (μA)
3200	1600	1111	140
1600	800	1110	90
800	400	1101	140
400	200	1100	140
200	100	1011	140
100	50	1010	140
50	25	1001	90
25	12.5	1000	60



1. Accelerometer code: write value to specific address

```
# Register 0x2D: POWER_CTL  
self.write_byte(ADXL345_POWER_CTL, ADXL345_MEASURE)  
# write value: 0x08 = 0000 1000  
# D3=1: set 1 for measurement mode.
```

Register 0x2D—POWER_CTL (Read/Write)

D7	D6	D5	D4	D3	D2	D1	D0
0	0	Link	AUTO_SLEEP	Measure	Sleep	Wakeup	

D3 = 1



Measure Bit

A setting of 0 in the measure bit places the part into standby mode, and a setting of 1 places the part into measurement mode. The ADXL345 powers up in standby mode with minimum power consumption.



1. Accelerometer code: write value to specific address

```
# Register 0x31: DATA_FORMAT
self.write_byte(ADXL345_DATA_FORMAT, self.df_value)
# write value=0000 1000
# D3 = 1: the device is in full resolution mode,
# where the output resolution increases with the g range
# set by the range bits to maintain a 4 mg/LSB scale factor.
# D1 D0 = range. 00 = +-2g
```

Register 0x31—DATA_FORMAT (Read/Write)

D7	D6	D5	D4	D3	D2	D1	D0
SELF_TEST	SPI	INT_INVERT	0	FULL_RES	Justify	Range	

FULL_RES Bit

When this bit is set to a value of 1, the device is in full resolution mode, where the output resolution increases with the g range set by the range bits to maintain a 4 mg/LSB scale factor. When the FULL_RES bit is set to 0, the device is in 10-bit mode, and the range bits determine the maximum g range and scale factor.

D3 = 1

D1D0 = 00

Table 21. g Range Setting

Setting		g Range
D1	D0	
0	0	$\pm 2\text{ g}$
0	1	$\pm 4\text{ g}$
1	0	$\pm 8\text{ g}$
1	1	$\pm 16\text{ g}$


1. Accelerometer code: read X/Y/Z raw data



```
# RAW readings in LSB
# Register 0x32 to Register 0x37:
# DATAx0, DATAx1, DATAy0, DATAy1, DATAz0, DATAz1 (Read Only)
def getRawX(self) :
    self.Xraw = self.read_word_2c(ADXL345_DATAx0)
    return self.Xraw

def getRawY(self) :
    self.Yraw = self.read_word_2c(ADXL345_DATAy0)
    return self.Yraw

def getRawZ(self) :
    self.Zraw = self.read_word_2c(ADXL345_DATAz0)
    return self.Zraw
```



1. Accelerometer code: convert unit

Parameter	Test Conditions	Min	Typ ¹	Max	Unit
SENSITIVITY	Each axis				
Sensitivity at X _{OUT} , Y _{OUT} , Z _{OUT}	All g-ranges, full resolution ±2 g, 10-bit resolution	230	256	282	LSB/g
		230	256	282	LSB/g

```
ADXL345_SCALE_MULTIPLIER= 0.00390625      # G/LSB. 1/256 = 0.00390625
self.Xcalibr = ADXL345_SCALE_MULTIPLIER
SCALE_MULTIPLIER = 1/SENSITIVITY

# Register 0x31: DATA_FORMAT
self.write_byte(ADXL345_DATA_FORMAT, self.df_value)
# D1 D0 = range. 00 = +-2g

# RAW readings in LSB
# Register 0x32 to Register 0x37:
# DATAX0, DATAX1, DATAY0, DATAY1, DATAZ0, DATAZ1 (Read Only)
def getRawX(self) :
    self.Xraw = self.read_word_2c(ADXL345_DATAX0)
    return self.Xraw

# G related readings in g
# This function is similar to filter. combine current value with previous one.
# plf = 1 means it only uses "current reading"
def getXg(self,plf = 1.0) :
    self.Xg = (self.getRawX() * self.Xcalibr - self.Xoffset) * plf \
        + (1.0 - plf) * self.Xg
    return self.Xg
# The offset unit is g.

# Absolute reading in m/s2
def getX(self,plf = 1.0) :
    self.X = self.getXg(plf) * EARTH_GRAVITY_MS2
    return self.X
```





Discussion 1

- 1. Based on the requirements, set correct value in the sample code
 - Output data rate: 100Hz
 - Range: +-2g
 - Convert LSB to G (by using SCALE_MULTIPLIER)

```
# set value
ADXL345_SCALE_MULTIPLIER= ???
ADXL345_BW_RATE_100HZ    = 0x??
ADXL345_MEASURE          = 0x???
```

- 2. Continuously measurement (infinite loop)
- 3. Calibrate your sensor (see next page)




Discussion 1 (cont.)

- Theoretically: x,y,z report (0,0,1) when static
- Actually:

COM6 - PuTTY

```
pi@raspberrypi:~/gy801$ python laccwu.py
x = -0.125 G, y = 0.070 G, z = 1.035 G
x = -0.125 G, y = 0.070 G, z = 1.035 G
x = -0.125 G, y = 0.070 G, z = 1.035 G
x = -0.125 G, y = 0.062 G, z = 1.000 G
x = -0.121 G, y = 0.062 G, z = 1.000 G
x = -0.121 G, y = 0.062 G, z = 1.000 G
x = -0.121 G, y = 0.062 G, z = 1.000 G
x = -0.129 G, y = 0.074 G, z = 1.031 G
x = -0.129 G, y = 0.074 G, z = 1.031 G
```





- Measure your static reading, then feedback to code

```
self.Xoffset = 0.0
self.Yoffset = 0.0
self.Zoffset = 0.0
```




Quiz 1

- Based on the result of discussion 1, calculate the norm of acceleration $|a|$
 - Formula:
 $|a| = \sqrt{x^2 + y^2 + z^2}$




Application: step detection



Quiz 1

- Hint: Use python to calculate pow and sqrt

```
import numpy  
x = 4  
  
y = pow(x,2)  
# y=16  
  
z = numpy.sqrt(x)  
# z=2  
  
print y  
print z
```




```
(COM4) [80x24]  
連線(C) 編輯(E) 檢視(V) 視窗(W) 選項(O) 說明(H)  
pi@raspberrypi:~$ python norm_a.py  
16  
2.0  
pi@raspberrypi:~$
```



Quiz2: Roll, Pitch, Tilt

□ Calculate posture:

- Use normalized accelerometer reading G_p
- Calculate: Roll, Pitch




(from AN3461.pdf)

$$\text{Roll: } \tan \phi_{xyz} = \frac{G_{py}}{G_{pz}}$$

$$\text{Pitch: } \tan \theta_{xyz} = \frac{-G_{px}}{\sqrt{G_{py}^2 + G_{pz}^2}}$$



Figure 3. Definition of Coordinate System and Rotation Axes



Math in Python

□ Trigonometric functions

□ `math.acos(x)`

- Return the arc cosine of x, in radians.


□ `math.atan2(y, x)`

- Return $\text{atan}(y / x)$, in radians. The result is between $-\pi$ and π . The vector in the plane from the origin to point (x, y) makes this angle with the positive X axis. The point of `atan2()` is that the signs of both inputs are known to it, so it can compute the correct quadrant for the angle. For example, $\text{atan}(1)$ and $\text{atan2}(1, 1)$ are both $\pi/4$, but $\text{atan2}(-1, -1)$ is $-3\pi/4$.

□ Angular conversion


□ `math.degrees(x)`


- Convert angle x from radians to degrees.



Brief summary


- What can we obtain from accelerometer?
 - 1. Movement along with xyz-axis
 - Unit: byte, G, or m/s²
 - 2. Posture (Roll, Pitch)
 - Unit: Radians or Degree





Outline

- 嵌入式應用: 人體活動偵測
 - 加速度、陀螺儀...等
- GY801 (I2C sensor)
 1. 3-axis Accelerometer, Gyroscope, magnetometer and pressure
 2. ADXL345 : Accelerometer
 3. L3G4200 : Gyroscope
 4. HMC5883 : Magnetometer
 5. BMP085 : Pressure







2. Gyroscope (L3G4200D)

□ Features

- 3-Axis angular rate sensor
- Supports I2C and SPI communications
- Three selectable scales:
250/500/2000 degrees/sec (dps)
- High shock survivability
- Embedded temperature sensor -40 to +185 °F
(-40 to + 85 °C)
- Embedded power-down and sleep mode
- 16 bit-rate value data output
- 8-bit temperature data output



Pull-up to be added when I2C interface is used




2. Gyroscope code

- Sample code results:

```
COM6 - PuTTY  
pi@raspberrypi:~/gy801$ python 2gyrowu.py  
(raw) X = 0.560 dps, Y = -0.560 dps, Z = -0.044 dps  
(angle) X = 0.000 deg, Y = -0.000 deg, Z = -0.000 deg  
pi@raspberrypi:~/gy801$ █
```

2. Gyroscope code: define address, convert unit



```
7   L3G4200D_ADDRESS      = 0x69
8   L3G4200D_CTRL_REG1    = 0x20 # CTRL_REG1 (20h)
9   L3G4200D_CTRL_REG4    = 0x23 # CTRL_REG4 (23h)
10  L3G4200D_OUT_X_L     = 0x28 # X-axis angular rate data.
11  L3G4200D_OUT_X_H     = 0x29 # The value is expressed as two's complement.
12  L3G4200D_OUT_Y_L     = 0x2A
13  L3G4200D_OUT_Y_H     = 0x2B
14  L3G4200D_OUT_Z_L     = 0x2C
15  L3G4200D_OUT_Z_H     = 0x2D

68
69      # FS=250dps, Sensitivity = 8.75 mdps/digit
70      self.gain_std = 0.00875
71
72      # 0x20: CTRL_REG1, write 0x0F = 0000 1111
73      self.write_byte(L3G4200D_CTRL_REG1, 0x0F)
74      # DR1-DR0 = 00; BW1-BW0 = 00 -> 100Hz, Cut-off=12.5
75      # PD, Zen, Yen, Xen = 1111
76
77      # 0x23: CTRL_REG4, write 0x80 = 0000 1000
78      self.write_byte(L3G4200D_CTRL_REG4, 0x80)
79      # BDU=continuous update; BLE=Data LSB
80      # FS1-FS0=00 -> 250 dps
81
82      self.setCalibration()
83
84  def setCalibration(self) :
85      gyr_r = self.read_byte(L3G4200D_CTRL_REG4)
86
87      self.gain = 2 ** (gyr_r & 48 >> 4) * self.gain_std
```



2. Gyroscope code: write value to specific address

```
71
72     # 0x20: CTRL_REG1, write 0x0F = 0000 1111
73     self.write_byte(L3G4200D_CTRL_REG1, 0x0F)
74     # DR1-DR0 = 00; BW1-BW0 = 00 -> 100Hz, Cut-off=12.5
     # PD, Zen, Yen, Xen = 1111
```


CTRL_REG1 (20h)

Table 20. CTRL_REG1 register

DR1	DR0	BW1	BW0	PD	Zen	Yen	Xen
-----	-----	-----	-----	----	-----	-----	-----

Table 21. CTRL_REG1 description

DR1-DR0	Output Data Rate selection. Refer to Table 22
BW1-BW0	Bandwidth selection. Refer to Table 22
PD	Power down mode enable. Default value: 0 (0: power down mode, 1: normal mode or sleep mode)
Zen	Z axis enable. Default value: 1 (0: Z axis disabled; 1: Z axis enabled)
Yen	Y axis enable. Default value: 1 (0: Y axis disabled; 1: Y axis enabled)
Xen	X axis enable. Default value: 1 (0: X axis disabled; 1: X axis enabled)



2. Gyroscope code: write value to specific address

```
76 # 0x23: CTRL_REG4, write 0x80 = 0000 1000  
77 self.write_byte(L3G4200D_CTRL_REG4, 0x80)  
78 # BDU=continuous update; BLE=Data LSB  
79 # FS1-FS0=00 -> 250 dps
```

CTRL_REG4 (23h)

Table 30. CTRL_REG4 register

BDU	BLE	FS1	FS0	-	ST1	ST0	SIM

Table 31. CTRL_REG4 description

BDU	Block Data Update. Default value: 0 (0: continuous update; 1: output registers not updated until MSB and LSB reading)
BLE	Big/Little Endian Data Selection. Default value 0. (0: Data LSB @ lower address; 1: Data MSB @ lower address)
FS1-FS0	Full Scale selection. Default value: 00 (00: 250 dps; 01: 500 dps; 10: 2000 dps; 11: 2000 dps)
ST1-ST0	Self Test Enable. Default value: 00 (00: Self Test Disabled; Other: See Table)
SIM	SPI Serial Interface Mode selection. Default value: 0 (0: 4-wire interface; 1: 3-wire interface).

2. Gyroscope code: convert raw data to degree



```
1 # read raw data
2 def getRawX(self):
3     self.Xraw = self.read_word_2c(L3G4200D_OUT_X_L)
4     return self.Xraw
5
6 # similar to filter. combine current value with previous one.
7 # plf = 1 means it only uses "current reading"
8 def getX(self,plf = 1.0):
9     self.X = ( self.getRawX() * self.gain ) * plf + (1.0 - plf) * self.X
10    return self.X
11
12 # convert dps to angle. LP = loop period.
13 # Degree per second * second = degree
14 def getXangle(self,plf = 1.0) :
15     if self.t0x is None : self.t0x = time.time()
16     t1x = time.time()
17     LP = t1x - self.t0x
18     self.t0x = t1x
19     self.Xangle = self.getX(plf) * LP
20     return self.Xangle
```



Discussion 2


- 1. Based on the requirements, set correct value in the sample code

- Data rate: 100Hz, cut-off = 12.5
 - Full Scale selection = 250 dps
 - Set Sensitivity for 250 dps (by using SCALE_MULTIPLIER)

```
# set value
self.gain_std = ??      # dps/digit


self.write_byte(L3G4200D_CTRL_REG1, 0x??)
self.write_byte(L3G4200D_CTRL_REG4, 0x??)
```

- 2. Continuously measurement (infinite loop)



Brief summary

- What can we obtain from gyroscope?
 - 1. rotation (angular velocity)
 - Unit: byte, DPS (Degree per Second)
 - 2. rotated angle (integral “angular velocity” to “angle”)
 - Unit: degree. You can convert it to rad.






Discussion 3

- We can obtain $a_x/a_y/a_z$ from accelerometer.
How to calculate the distance?

$$\mathbf{s}(t) = \mathbf{s}_0 + \mathbf{v}_0 t + \frac{1}{2} \mathbf{a} t^2 = \mathbf{s}_0 + \frac{\mathbf{v}_0 + \mathbf{v}(t)}{2} t$$

$$\mathbf{v}(t) = \mathbf{v}_0 + \mathbf{a} t$$

$$v^2(t) = v_0^2 + 2\mathbf{a} \cdot [\mathbf{s}(t) - \mathbf{s}_0]$$



```
12      # convert dps to angle. LP = loop period.
13      # Degree per second * second = degree
14      def getXangle(self,plf = 1.0) :
15          if self.t0x is None : self.t0x = time.time()
16          t1x = time.time()
17          LP = t1x - self.t0x
18          self.t0x = t1x
19          self.Xangle = self.getX(plf) * LP
20          return self.Xangle
```


Hint: In Gyro sample code, it convert dps to angle.



Sensor fusion

- Accelerometer is good in long term.
- Gyroscope is good in short term.
 - Use Complementary filter to integrate them
 - Enhanced rotation angle

accelerometer rate gyro





$$\theta \approx \int (\text{angular rate}) dt$$

- not good in long term
due to integration

$$\theta \approx \sin^{-1} \left(\frac{\text{accel. output}}{g} \right)$$

- only good in long term
- not proper during fast motion






Quiz3: Sensor fusion

- Calculate angle based on accelerometer and gyroscope
 - Complementary filter: Enhanced rotation angle


$$\text{Angle} = 0.98 * (\text{angle} + \text{gyroData} * dt) + 0.02 * \text{accData}$$




$$\boxed{\text{CF_Angle}[t] = 0.98 * (\text{CF_Angle}[t-1] + \text{gyroData}[t] * dt) + 0.02 * \text{accData}[t]}$$




We can get **Roll, Pitch** from accelerometer.



When rotating the sensor, we can get **Angular velocity**.





Quiz3: Sensor fusion

- Complementary filter: Enhanced rotation angle

$CF_Angle[t] = 0.98 * (CF_Angle[t-1] + gyroData[t] * dt) + 0.02 * accData[t]$
(from digikey's website)

$$pitch[t] = (pitch[t-1] + Xangle_{gyro}[t]) * 0.98 + pitch_{acc}[t] * 0.02$$

$$roll[t] = (roll[t-1] + Yangle_{gyro}[t]) * 0.98 + roll_{acc}[t] * 0.02$$

```
# convert dps to angle. LP = loop period.  
# Degree per second * second = degree  
def getXangle(self,plf = 1.0) :  
    if self.t0x is None : self.t0x = time.time()  
    t1x = time.time()  
    LP = t1x - self.t0x  
    self.t0x = t1x  
    self.Xangle = self.getX(plf) * LP  
    return self.Xangle
```

$$\text{Roll: } \tan \phi_{xyz} = \frac{G_{py}}{G_{pz}}$$

$$\text{Pitch: } \tan \theta_{xyz} = \frac{-G_{px}}{\sqrt{G_{py}^2 + G_{pz}^2}}$$



Summary

- Practice Lab (accelerometer, gyroscope)
- Write down the answer for discussion
 - Discussion:
 - 1&2: Based on the requirements, set correct value in the sample code
 - 3: How to calculate distance from accelerometer
 - (放code截圖就可以了)
 - Deadline: Before 11:59, 4/3
- Write code for Quiz 1 - 3 (infinite loop),
then demonstrate it to TAs
 - (X/Y/Zoffset should be measured)
 - Quiz1: Calculate the norm of acceleration $|a|$
 - Quiz2: Roll, Pitch, Tilt
 - Quiz3: Sensor fusion (pitch, roll with complementary filter)
 - Deadline: Before 15:10, 3/27
 - Late Demo: Before 15:10, 4/10