



SERVICE BULLETIN

No.SB-13-001

Subject

Description of F803

Model

LXE10E100F (DECOSIIIf), LXE10E100G (DECOSIIIg)

Notice

Logic and display for "F803" has been changed since LXE10E100F (DECOSIIIf).

Description

Controller (Software Version)		DECOSIIIf, g (2551 or later)	DECOSIIIe, d (2512, 24A8 or later)
	Alarm	F803	F803
Possible cause		 Contact point of Phase Correction Contactor (PCC) melted Contact point of Compressor Contactor (CC) melted Terminals of compressor disconnected (Comp. current not detected during Comp. ON condition) E107 (EV opening error) detected twice Both evaporator fan motors stopped abnormal Two of HPT, LPT and DCHS failed 	1) Contact point of Compressor Contactor (CC) melted 2) Terminals of Compressor disconnected (Comp. current not detected during Comp. ON condition) 3) E107 (EV opening error) detected twice 4) Both evaporator fan motors stopped abnormal 5) Two of HPT, LPT and DCHS failed
	Current Indication	F803	F803
	Alarm Record Scroll	F803 and Fd01 - Fd05	F803
Display		Fd01: F803 caused by above 1) Fd02: F803 caused by above 2) Fd03: F803 caused by above 3) Fd04: F803 caused by above 4) Fd05: F803 caused by above 5)	
	Record on trip report	F803	F803