VIETNAM NATIONAL UNIVERSITY HO CHI MINH CITY HCM UNIVERSITY OF TECHNOLOGY FACULTY OF MECHANICAL ENGINEERING - MECHATRONICS DEPARTMENT



ME3011

Design Project Report

Submitted To:Submitted By:Nguyen Tan TienNguyen Quy KhoiAsst. Professor1852158Faculty of MechanicalCC02EngineeringHK192

Acknowledgements

I would like to give a special thank to Prof. Nguyen Tan Tien, my supervisor to instruct me and fix my report to meet industrial standard.

Abstract

In machine design, every machine element must be calculated in a systematic matter. In this course, students are provided with essential skills to formulate almost every dimension manually, thus further improving their engineering skills before engaging the high-energy, fast-paced workforce.

When a machine element is being developed, it must satisfy some key engineering specifications such as being able to operate under designated lifespan, low cost and high efficiency. Other aspects are less important but also determined the overall design of the element include compactness, noise emission, appearance, etc.

To optimize the process of machine design, the general principles are considered as follows:

- 1. Identify the working principle and workload of the machine.
- 2. Formulate the overall working principle to satisfy the problem. Proposing feasible solutions and evaluating them to find the optimal design specifications.
- 3. Find force and moment diagram exerting on machine parts and characteristics of the workload.
- 4. Choose appropriate materials to make use of their properties and improve efficiency as well as reliability of individual elements.
- 5. Calculate dynamics, strength, safety factor, etc. to specify dimensions.
- 6. Design machine structure, parts to satisfy working condition and assembly.
- 7. Create presentation, instruction manual and maintenance.

In this report, I will design a fairly simple system to provide a concrete example of finishing all the tasks above.

Contents

1	Desi	gn Problem	9
	1.1	Nomenclature	9
	1.2	Problem	9
	1.3	Mixing machine parameters	9
	1.4	Requirements	0
	1.5	Design problem	0
2	Cho	ose Motor 1	2
	2.1	Nomenclature	2
	2.2	Calculate η_{sys}	3
	2.3	Calculate <i>P</i>	3
	2.4	Calculate n_{mo}	3
	2.5	Choose motor	3
	2.6	Calculate power, rotational speed and torque	4
		2.6.1 Power	4
		2.6.2 Rotational speed	4
		2.6.3 Torque	5
3	Cha	in Drive Design 1	6
	3.1	Nomenclature	6
	3.2	Find <i>p</i>	7
		3.2.1 Calculate <i>z</i>	7
		3.2.2 Calculate [<i>P</i>]	7
		3.2.3 Determine p	8
	3.3	Find a, x_c , and $i \dots 1$	8

6 CONTENTS

		3.3.1	Find x_c	18
		3.3.2	Find a	18
		3.3.3	Find <i>i</i>	18
	3.4	Streng	th of chain drive	19
	3.5	Detern	nine sprocket specifications and output force on the shaft .	19
	3.6	Force	on shaft	20
	3.7	Other	parameters	20
4	Gea	rbox De	esign (Helix gears)	22
	4.1	Nome	nclature	22
	4.2	Choos	e material	24
	4.3	Calcul	ate $[\sigma_H]$ and $[\sigma_F]$	24
	4.4	Detern	nine basic specifications of the Transmission system	26
		4.4.1	Determine basic parameters	26
		4.4.2	Determine gear meshing parameters	27
		4.4.3	Basic parameters	28
		4.4.4	Find $[\sigma_{Hw}]$, $[\sigma_{Fw1}]$ and $[\sigma_{Fw2}]$	28
		4.4.5	Contact stress analysis	29
		4.4.6	Bending stress analysis	30
		4.4.7	Force on shafts	30
Re	eferen	ces		35

List of Figures

1.1	Working principle diagram and workload of the mixing ma-	
	chine: 1) electric motor, 2) coupling, 3) two-stage coaxial he-	
	lical speed reducer, 4) roller chain drive, 5) mixing tank (one-	
	directional, light duty, operate 1 shift, 8 hours each)	10

List of Tables

2.1	Output specifications	15
3.1	Chain drive specifications	21
4.1	Gearbox specifications	31

Chapter 1

Design Problem

1.1 Nomenclature

C_a	number of shift daily, shifts	\boldsymbol{P}	design power of the mixing
K_{ng}	working days/year, days		tank, kW
L	service life, years	T_1	working torque 1, $N \cdot m$
n	rotational velocity of the mixing	T_2	working torque 2, $N \cdot m$
	tank, rpm	t_1	working time 1, s
		t_2	working time 2, s

1.2 Problem

The problem is downloaded from E-learning website, designated number 8, see Figure 1.1.

1.3 Mixing machine parameters

From the parameters given in the document, we have:

```
P = 7 \text{ (kW)} t_1 = 15 \text{ (s)}

n = 65 \text{ (rpm)} t_2 = 11 \text{ (s)}

L = 8 \text{ (years)} T_1 = T \text{ (N} \cdot \text{m)}

K_{ng} = 260 \text{ (days)} T_2 = 0.7T \text{ (N} \cdot \text{m)}

Ca = 1 \text{ (shifts)}
```




Figure 1.1: Working principle diagram and workload of the mixing machine: 1) electric motor, 2) coupling, 3) two-stage coaxial helical speed reducer, 4) roller chain drive, 5) mixing tank (one-directional, light duty, operate 1 shift, 8 hours each)

1.4 Requirements

- 01 report.
- 01 assembly drawing.
- 01 detailed drawing.

1.5 Design problem

- 1. Decide the working power of the electric motor and transmission ratio of the system.
- 2. Calculate and design machine elements:
 - (a) Calculate system drives (belt, chain or gear).
 - (b) Calculate the elements in speed reducers (gears, lead screws).
 - (c) Draw and calculate force diagram exerting on the transmission elements.
 - (d) Calculate, design shafts and keys.
 - (e) Choose bearings and couplings.
 - (f) Choose machine bodies, fasteners and other elements.

- 3. Choose assembly tolerance.
- 4. Bibliography

Chapter 2

Choose Motor

2.1 Nomenclature

rotational speed of shaft, rpm	u_{sys}	transmission ratio of the system
calculated motor power to drive	T_{mo}	motor torque, $N \cdot mm$
the system, kW	T_{sh}	shaft torque, $N \cdot mm$
operating power of shaft, kW	η_b	bearing efficiency
operating power of the belt con-	η_c	coupling efficiency
veyor given a workload, kW	η_{ch}	chain drive efficiency
transmission ratio of quick stage	η_{hg}	helical gear efficiency
transmission ratio of slow stage	η_{sys}	efficiency of the system
transmission ratio of chain drive	1	shaft 1
transmission ratio of speed re-	2	shaft 2
ducer	3	shaft 3
	calculated motor power to drive the system, kW operating power of shaft, kW operating power of the belt con- veyor given a workload, kW transmission ratio of quick stage transmission ratio of slow stage transmission ratio of chain drive transmission ratio of speed re-	calculated motor power to drive T_{mo} the system, kW T_{sh} operating power of shaft, kW η_b operating power of the belt conveyor given a workload, kW η_{ch} transmission ratio of quick stage η_{hg} transmission ratio of slow stage η_{sys} transmission ratio of chain drive η_{ch} transmission ratio of speed re-

Known parameters From Chapter 1, we know that:

$$P = 7 \text{ kW}, n = 65 \text{ rpm}$$

 $T_1 = T, T_2 = 0.7T$

$$t_1 = 15 \text{ s}, t_2 = 11 \text{ s}$$

2.2 Calculate η_{sys}

From Table 2.3:

$$\eta_c = 1$$

$$\eta_b = 0.99$$

$$\eta_{hg} = 0.97$$

$$\eta_{ch} = 0.96$$

$$\eta_{sys} = \eta_c \eta_b^4 \eta_{hg}^2 \eta_{ch} = 0.87$$

2.3 Calculate *P*

From Equation 2.13 [1]:

$$P_{w} = P \sqrt{\frac{\left(\frac{T_{1}}{T}\right)^{2} t_{1} + \left(\frac{T_{2}}{T}\right)^{2} t_{2}}{t_{1} + t_{2}}} = 6.2 \text{ (kW)}$$

$$P_{mo} = \frac{P_{w}}{\eta_{sys}} = 7.14 \text{ (kW)} > P$$

2.4 Calculate n_{mo}

Using Table 2.4 [1]:

$$u_{ch} = 4$$
, $u_h = 10$

$$u_{sys} = u_{ch}u_h = 40$$

$$n_{mo} = u_{sys}n = 2600 \text{ (rpm)}$$

2.5 Choose motor

To work normally, the maximum operating power of the chosen motor must be no smaller than both estimated P_{mo} and P. Since $P_{mo} > P$ for our case, the minimum operating power of choice is $P_{mo} = 7.14$ (kW). In similar fashion, its rotational speed must also be no smaller than estimated n_{mo} .

Thus, from Table P1.3 [1], we choose motor 4A112M2Y3 which operates at 7.5 kW and 2922 rpm.

$$\Rightarrow P_{mo} = 7.5 \text{ (kW)}, n_{mo} = 2922 \text{ (rpm)}$$

14 2 Choose Motor

Recalculating u_{sys} with the new P_{mo} and n_{mo} , we obtain:

$$u_{sys} = \frac{n_{mo}}{n} = 44.95$$
Assuming $u_h = const$:
$$u_{ch} = \frac{u_{sys}}{u_h} = 4.5$$

2.6 Calculate power, rotational speed and torque

Let us denote P_{sh1} , n_{sh1} and T_{sh1} be the transmitted power, rotational speed and torque onto shaft 1, respectively. Similarly, P_{sh2} , n_{sh2} and T_{sh2} will be the transmitted parameters onto shaft 2 and P_{sh3} , n_{sh3} and T_{sh3} will be the transmitted parameters onto shaft 3. These notations will be used throughout the next chapters.

2.6.1 Power

$$P_{ch} = \frac{P_w}{\eta_b} = 6.3 \text{ (kW)}$$

$$P_{sh3} = \frac{P_{ch}}{\eta_{ch}} = 6.52 \text{ (kW)}$$

$$P_{sh2} = \frac{P_{sh3}}{\eta_b \eta_{hg}} = 6.79 \text{ (kW)}$$

$$P_{sh1} = \frac{P_{sh2}}{\eta_b \eta_{hg}} = 7.07 \text{ (kW)}$$

2.6.2 Rotational speed

To minimize the speed reducer weight, we can use the following formula, see Equation 3.12 [1]:

$$u_1 = 0.7332u_h^{0.6438}$$

Then,

$$u_1 = 3.23$$
 and $u_2 = u_h/u_1 = 3.1$
 $n_{sh1} = n_{mo} = 2922$ (rpm)
 $n_{sh2} = n_{sh1}/u_1 = 905.02$ (rpm)
 $n_{sh3} = n_{sh2}/u_2 = 292.20$ (rpm)

2.6.3 Torque

$$T_{mo} = 9.55 \times 10^6 \times P_{mo}/n_{mo} = 24512.32 \,(\text{N} \cdot \text{mm})$$

 $T_{sh1} = 9.55 \times 10^6 \times P_{sh1}/n_{sh1} = 23106.95 \,(\text{N} \cdot \text{mm})$
 $T_{sh2} = 9.55 \times 10^6 \times P_{sh2}/n_{sh2} = 71672.45 \,(\text{N} \cdot \text{mm})$
 $T_{sh3} = 9.55 \times 10^6 \times P_{sh3}/n_{sh3} = 213175.22 \,(\text{N} \cdot \text{mm})$

In summary, we obtain the following table:

	Motor	Shaft 1	Shaft 2	Shaft 3
P(kW)	7.5	7.07	6.79	6.52
и	-	1	3.23	3.1
n (rpm)	2922	2922	905.02	292.20
$T(\mathbf{N} \cdot \mathbf{mm})$	24512.32	23116.54	71672.45	213175.22

Table 2.1: Output specifications

Chapter 3

Chain Drive Design

3.1 Nomenclature

[i]	permissible impact times per	F_1	tight side tension force, N
	second	F_2	slack side tension force, N
[s]	permissible safety factor	F_r	force on the shaft, N
[P]	permissible power, kW	F_t	effective peripheral force, N
$[\sigma_H]$	permissible contact stress, MPa	F_{v}	centrifugal force, N
\boldsymbol{A}	cross sectional area of chain	F_{vd}	contact force, N
	hinge, mm ²	i	impact times per second
a	real center distance, mm	K_d	weight distribution factor
a_i	estimated center distance, mm	k	overall factor
a_{max}	maximum center distance, mm	k_a	center distance and chain's
a_{min}	minimum center distance, mm		length factor
В	width between inner link	k_{bt}	lubrication factor
	plate, mm	k_c	rating factor
d	chordal diameter, mm	k_d	dynamic load factor
d_a	addendum diameter, mm	k_{dc}	chain tension factor
d_f	dedendum diameter, mm	k_f	loosing factor
d_l	roller diameter, mm	k_n	coefficient of rotational speed
d_O	pin diameter, mm	k_r	number of tooth factor
E	modulus of elasticity, MPa	k_{x}	chain weight factor
F_0	sagging force, N	k_z	coefficient of number of teeth

3.2 Find *p* 17

k_0	arrangement of drive factor	v	instantaneous velocity along the
n	angular rotational speed, rpm		chain, m/s
n_{01}	experimental angular rotational	X	chain length in pitches, the num-
	speed, rpm		ber of links
P_t	calculated power, kW	x_c	an even number of links
p	pitch, mm	z	number of teeth of a sprocket
p_{max}	permissible sprocket pitch, mm	z_{max}	maximum number of teeth of
Q	permissible load, N		the driven sprocket
q	mass per unit length, kg/m	σ_H	contact stress, MPa
\boldsymbol{S}	safety factor	1	subscript for driving sprocket
		2	subscript for driven sprocket

Known parameters From Chapter 1, we know that:

The chain type is roller.

 $n_{sh3} = 292.2 \text{ rpm}.$

 $P_{ch} = 6.3 \text{ kW}, u_{ch} = 4.5.$

3.2 Find p

The driving sprocket is connected to shaft 3, $n_1 = n_{sh3} = 292.2$ (rpm).

3.2.1 Calculate *z*

Since z_1 and z_2 is preferably an odd number, Equation 5.1 [1]:

$$z_1 = 29 - 2u_{ch} = 21$$

$$z_2 = u_{ch} z_1 = 95 \le 120$$

3.2.2 Calculate [*P*]

Since 200 is the nearest to $n_{ch} = 292.2 \,\text{rpm}$, we choose $n_{01} = 200 \,\text{rpm}$, which is one of the experimental angular rotational speed values. Then, we can obtain the value [P], Equation 5.3 [1]:

$$P_t = P_{ch}k_0k_ak_{dc}k_{bt}k_dk_ck_zk_n \le [P]$$

where $k_z = 25/z_1 = 1.32$ and $k_n = n_{01}/n_1 = 1.02$.

Assuming good operational condition, $k_0 = k_a = k_{dc} = k_{bt} = 1$, $k_d = 1.25$, $k_c = 1$, see Table 5.6 [1]. Calculation yields $P_t = 6.38$ (kW) \leq [P]. Inspecting Table 5.5 [1] at column $n_{01} = 200$ rpm, choose the closet value [P] = 11 kW.

3.2.3 Determine p

Knowing [P], we have p = 25.4 mm, Table 5.5. Consequently, $d_c = 7.95$ mm, B = 22.61 mm. Consulting Table 5.8, the pitch is indeed suitable.

3.3 Find a, x_c , and i

3.3.1 Find x_c

 $a_{min} = 30p = 762 \text{ (mm)}, \ a_{max} = 50p = 1270 \text{ (mm)}.$ Limiting the range of choice for a in $[a_{min}, a_{max}]$, we can approximate $a_i = 1000 \text{ mm}$ and find x_c :

$$x = \frac{2a_i}{p} + \frac{z_1 + z_2}{2} + \frac{(z_2 - z_1)^2 p}{4\pi^2 a_i} = 140.26$$

Then, round x up to the nearest even number gives $x_c = 142$.

3.3.2 Find *a*

Using x_c to find the correct center distance, see Equation 5.13 [1]. In addition, it is recommended to loosing the chain an amount of $0.002 \div 0.004a$, which explains the coefficient 0.097 in the formula below:

$$a = \frac{0.097p}{4} \left[x_c - \frac{z_2 + z_1}{2} + \sqrt{\left(x_c - \frac{z_2 + z_1}{2}\right)^2 - 2\left(\frac{z_2 - z_1}{\pi}\right)^2} \right] = 1019.99 \text{ (mm)}$$

3.3.3 Find i

The permissible impact frequency is [i] = 30, Table 5.9 [1]. Calculating i gives:

$$i = \frac{z_1 n_1}{15x} = 2.92 < [i]$$

3.4 Strength of chain drive

In order to operate safely, the chain drive's safety factor must satisfy the following condition:

$$s = \frac{Q}{k_d F_t + F_0 + F_v} \ge [s]$$

Rotational speed of the smaller sprocket is determined using the formula below:

$$v_1 = \frac{n_1 p z_1}{60000} = 2.6 \,(\text{m/s})$$

Find k_d : Assuming moderate workload, choose $k_d = 1.2$.

Find F_t , F_v and F_0 : Knowing p, it is easy to look up the values Q = 56700 N and q = 2.6 kg/m from Table 5.2 [1]:

$$F_t = 10^3 P_{ch} / v_1 = 2410.48 \text{ (N)}$$

$$F_v = qv_1^2 = 17.54 \,(\text{N})$$

$$F_0 = 9.81 \times 10^{-3} k_f qa = 156.11 \text{ (N)}$$

Find k_f : Let the chain drive be parallel to the ground, we get $k_f = 6$.

Find [s]: The limit [s] = 8.71 is found using interpolation, Table 5.10 [1].

Replacing all the variables gives:

$$s = 18.49 \ge 8.71$$

which satisfies the condition.

3.5 Determine sprocket specifications and output force on the shaft

The following condition must be met, Equation 5.18 [1]:

$$\sigma_H = 0.47 \sqrt{\frac{k_r (F_t k_d + F_{vd}) E}{A K_d}} \le [\sigma_H]$$

Since the chain drive only has one strand, $K_d = 1$.

Find $[\sigma_H]$ Quenched 45 steel is the material of use for the chain drive, which

has HB210, $[\sigma_H] = 600$ (MPa) and $E = 2.1 \times 10^5$ (MPa), see Table 5.11 [1].

Find F_{vd} For 1-strand chain, $F_{vd} = 13 \times 10^{-7} n_1 p^3 = 6.22$ (N)

Find k_r Since z_1 is used to estimate k_r , $k_r = 0.47$.

Find E Assuming the sprockets and chain are made up from the same material (steel), $E = 2.1 \times 10^5 \text{ MPa}$

Find A From the given parameters and value p, the area $A = 180 \,\mathrm{mm}^2$, Table 5.12 [1].

Knowing k_d and F_t , we get the result:

$$\sigma = 591.29 \, (\text{MPa}) \le [\sigma_H]$$

which is satisfactory.

3.6 Force on shaft

Applying the following equations, see p.87 [1]:

$$F_2 = F_0 + F_v = 173.65 (N)$$

$$F_1 = F_t + F_2 = 2584.13$$
 (N)

Choose $k_x = 1.15$ to obtain F_r , Equation 5.20 [1]:

$$F_r = k_x F_t = 2772.05 (N)$$

3.7 Other parameters

$$d_1 = p/\sin\left(\frac{\pi}{z_1}\right) = 170.42 \text{ (mm)}$$

$$d_2 = p/\sin\left(\frac{\pi}{z_2}\right) = 768.22 \text{ (mm)}$$

$$d_{a1} = p\left(0.5 + \cot\frac{180}{z_1}\right) \approx 181.22 \text{ (mm)}$$

$$d_{a2} = p\left(0.5 + \cot\frac{180}{z_2}\right) \approx 780.50 \text{ (mm)}$$
Look up to find $d_l = 15.88 \text{ (mm)}$, see Table 5.2 [1]:
$$d_{f1} = d_1 - 2(0.502d_l + 0.05) \approx 154.36 \text{ (mm)}$$

$$d_{f2} = d_2 - 2(0.502d_l + 0.05) \approx 752.16 \text{ (mm)}$$

In summary, we have the following table:

	driving	driven	
[P] (kW)	11		
a (mm)	101	9.99	
B (mm)	22.0	61	
d (mm)	170.92	768.22	
d_a (mm)	181.22	780.50	
d_f (mm)	154.36	752.16	
d_l (mm)	15.8	88	
d_O (mm)	7.95		
i	2.92		
p (mm)	25.4		
Q(N)	56700		
u_{ch}	4.5		
v (m/s)	2.6		
Z	21	95	

Table 3.1: Chain drive specifications

Chapter 4

Gearbox Design (Helix gears)

4.1 Nomenclature

$[\sigma_H]$	permissible contact stress,	K_d	coefficient of gear material
	MPa	K_F	load factor from bending stress
$[\sigma_H]_{max}$	permissible contact stress	K_{FC}	load placement factor
	due to overload, MPa	K_{FL}	aging factor due to bending
$[\sigma_F]$	permissible bending stress,		stress
	MPa	K_{Fv}	factor of dynamic load from
$[\sigma_F]_{max}$	permissible bending stress		bending stress at meshing area
	due to overload, MPa	$K_{F\alpha}$	factor of load distribution from
AG	accuracy grade of gear		bending stress on gear teeth
a	center distance, mm	$K_{F\beta}$	factor of load distribution from
b	face width, mm		bending stress on top land
c	gear meshing rate	K_H	load factor of contact stress
d	pitch circle, mm	K_{HL}	aging factor due to contact stress
d_a	addendum diameter, mm	K_{Hv}	factor of dynamic load from
d_b	base diameter, mm		contact stress at meshing area
d_f	deddendum diameter, mm	$K_{H\alpha}$	factor of load distribution from
F_a	axial force, N		contact stress on gear teeth
F_r	radial force, N	$K_{H\beta}$	factor of load distribution from
F_t	tangential force, N		contact stress on top land
H	surface roughness, HB	k_x	a coefficient

4.1 Nomenclature 23

k_y	a coefficient	Z_{v}	speed factor
m	traverse module, mm	z_H	contact surface's shape factor
m_F	root of fatigue curve in bending	Z_M	material's mechanical proper-
	stress test		ties factor
m_H	root of fatigue curve in contact	z_{min}	minimum number of teeth cor-
	stress test		responding to β
m_n	normal module, mm	z_v	virtual number of teeth
N_{FE}	working cycle of equivalent	$z_{oldsymbol{arepsilon}}$	meshing condition factor
	tensile stress corresponding to	α	normal pressure angle, follow-
	$[\sigma_F]$		ing Vietnam standard (TCVN
N_{FO}	working cycle of bearing stress		1065-71), i.e. $\alpha = 20^{\circ}$
	corresponding to $[\sigma_F]$	α_t	traverse pressure angle, °
N_{HE}	working cycle of equivalent	$oldsymbol{arepsilon}_{lpha}$	traverse contact ratio
	tensile stress corresponding to	$arepsilon_eta$	face contact ratio
	$[\sigma_H]$	β	helix angle, °
N_{HO}	working cycle of bearing stress	eta_b	base circle helix angle, °
	corresponding to $[\sigma_H]$	ψ_{ba}	width to shaft distance ratio
S	specific length, mm	ψ_{bd}	face width factor
S_F	safety factor of bending stress	σ_b	ultimate strength, MPa
S_H	safety factor of contact stress	σ_{ch}	yield limit, MPa
T	input torque, $N \cdot mm$	σ^o_{Flin}	permissible bending stress cor-
ν	rotational velocity, m/s		responding to working cycle,
X	gear correction factor		MPa
Y_F	tooth shape factor	σ^o_{Hlin}	n permissible contact stress cor-
Y_R	surface roughness factor of the		responding to working cycle,
	gear's face		MPa
Y_s	sensitivity to stress concentra-	1	subscript for the pinion
	tion factor	2	subscript for the driven gear
Y_{β}	helix angle factor	q	subscript for the quick transmis-
Y_{ε}	contact ratio factor		sion stage
у	center displacement factor	S	subscript for the slow transmis-
Z_R	surface roughness factor of the		sion stage
	working's area	w	subscript for the value after cor-
			rection

Known parameters From Chapter 1 and 2, we know that:

$$L = 8$$
 years, $K_{ng} = 260$ days, $Ca = 1$ shift
 $T_1 = T$, $T_2 = 0.7T$, $t_1 = 15$ s, $t_2 = 11$ s
 $n_{sh1} = 2922$ rpm, $n_{sh2} = 905.02$ rpm, $n_{sh3} = 292.20$ rpm
 $u_h = 10$, $u_1 = u_q = 3.23$, $u_2 = u_s = 3.1$

This chapter will increase readability by calculating both stages at the same time with the first one being quick stage and the latter is slow stage.

4.2 Choose material

Because all gears are the same in material and working hours except for their angular rotational speed, this section applies for both pairs.

The material of choice for the 2 pair of gears is steel 40X. The specifications are $S \le 100$ mm, HB250, $\sigma_b = 850$ MPa, $\sigma_{ch} = 550$ MPa, see Table 6.1 [1].

From Table 6.2 [1],
$$\sigma_{Hlim}^o = 2\text{HB} + 70$$
, $S_H = 1.1$, $\sigma_{Flim}^o = 1.8\text{HB}$, $S_F = 1.75$.

Therefore, they have the same properties except for their surface roughness H, since $H_2 = H_1 - 10 \div 15$.

For the pinion,
$$H_1 = \text{HB250} \Rightarrow \sigma^o_{Hlim1} = 570 \,\text{MPa}$$
, $\sigma^o_{Flim1} = 450 \,\text{MPa}$.

For the driven gear,
$$H_2 = \text{HB}240 \Rightarrow \sigma^o_{Hlim2} = 550 \,\text{MPa}$$
, $\sigma^o_{Flim2} = 432 \,\text{MPa}$.

In this part, distinguishing between 2 stages is unnecessary since the variables are material-dependent, which in this case all the gears have identical choice of material. Therefore, unless otherwise specified, a single subscript 1 or 2 indicates the variable applies for both stages

4.3 Calculate $[\sigma_H]$ and $[\sigma_F]$

The permissible stresses are calculated as follows, see Equation 6.1 and 6.2 [1]:

$$[\sigma_H] = \frac{\sigma_{Hlim}^o}{S_H} Z_R Z_v K_{xH} K_{HL}$$

$$[\sigma_F] = \frac{\sigma_{Flim}^o}{S_F} Y_R Y_s K_{xF} K_{FL}$$

25

Calculate working cycle of bearing stress The stress is found using the formula below, see Equation 6.5 [1]:

$$N_{HO1} = 30H_1^{2.4} = 17067789.40$$
 (cycles).
 $N_{HO2} = 30H_2^{2.4} = 15474913.67$ (cycles).

Calculate working cycle of equivalent tensile stress Since $H_1, H_2 \leq$ HB350, $m_H = 6$, $m_F = 6$. Also, both pairs of gears are meshed indefinitely, which makes c = 1. From working condition, we calculate:

$$L_h = 8 \left(\frac{\text{hours}}{\text{shift}} \right) \times CaK_{ng}L = 16640 \text{ (hours)}$$

Find N_{HE} and N_{FE} using equation 6.7 and 6.8 [1]:

$$N_{HE1q} = 60n_{sh1}cL_h \left[\left(\frac{T_1}{T} \right)^3 \frac{t_1}{t_1 + t_2} + \left(\frac{T_2}{T} \right)^3 \frac{t_2}{t_1 + t_2} \right] = 2.11 \times 10^9 \text{ (cycles)}$$

$$N_{HE2q} = 60n_{sh2}cL_h \left[\left(\frac{T_1}{T} \right)^3 \frac{t_1}{t_1 + t_2} + \left(\frac{T_2}{T} \right)^3 \frac{t_2}{t_1 + t_2} \right] = 0.65 \times 10^9 \text{ (cycles)}$$

$$N_{FE1q} = 60n_{sh1}cL_h \left[\left(\frac{T_1}{T} \right)^{m_F} \frac{t_1}{t_1 + t_2} + \left(\frac{T_2}{T} \right)^{m_F} \frac{t_2}{t_1 + t_2} \right] = 1.83 \times 10^9 \text{ (cycles)}$$

$$N_{FE2q} = 60n_{sh2}cL_h \left[\left(\frac{T_1}{T} \right)^{m_F} \frac{t_1}{t_1 + t_2} + \left(\frac{T_2}{T} \right)^{m_F} \frac{t_2}{t_1 + t_2} \right] = 0.57 \times 10^9 \text{ (cycles)}$$

$$N_{HE1s} = 60n_{sh2}cL_h \left[\left(\frac{T_1}{T} \right)^3 \frac{t_1}{t_1 + t_2} + \left(\frac{T_2}{T} \right)^3 \frac{t_2}{t_1 + t_2} \right] = 0.65 \times 10^9 \text{ (cycles)}$$

$$N_{HE2s} = 60n_{sh3}cL_h \left[\left(\frac{T_1}{T} \right)^3 \frac{t_1}{t_1 + t_2} + \left(\frac{T_2}{T} \right)^3 \frac{t_2}{t_1 + t_2} \right] = 0.21 \times 10^9 \text{ (cycles)}$$

$$N_{FE1s} = 60n_{sh2}cL_h \left[\left(\frac{T_1}{T} \right)^{m_F} \frac{t_1}{t_1 + t_2} + \left(\frac{T_2}{T} \right)^{m_F} \frac{t_2}{t_1 + t_2} \right] = 0.57 \times 10^9 \text{ (cycles)}$$

$$N_{FE2s} = 60n_{sh3}cL_h \left[\left(\frac{T_1}{T} \right)^{m_F} \frac{t_1}{t_1 + t_2} + \left(\frac{T_2}{T} \right)^{m_F} \frac{t_2}{t_1 + t_2} \right] = 0.57 \times 10^9 \text{ (cycles)}$$

$$N_{FE2s} = 60n_{sh3}cL_h \left[\left(\frac{T_1}{T} \right)^{m_F} \frac{t_1}{t_1 + t_2} + \left(\frac{T_2}{T} \right)^{m_F} \frac{t_2}{t_1 + t_2} \right] = 0.18 \times 10^9 \text{ (cycles)}$$

Calculate aging factor For steel, $N_{FO1} = N_{FO2} = 4 \times 10^6$ (MPa). Equation 6.3 and 6.4 [1] gives (if the factors are smaller than 1, round them up to 1, see p.94 [1]):

$$K_{HL1q} = {}^{m} E \sqrt{N_{HO1}/N_{HE1q}} = 0.45 < 1 \Rightarrow K_{HL1q} = 1$$
 $K_{HL2q} = {}^{m} E \sqrt{N_{HO2}/N_{HE2q}} = 0.54 < 1 \Rightarrow K_{HL2q} = 1$
 $K_{FL1q} = {}^{m} E \sqrt{N_{FO1}/N_{FE1q}} = 0.36 < 1 \Rightarrow K_{FL1q} = 1$
 $K_{FL2q} = {}^{m} E \sqrt{N_{FO2}/N_{FE2q}} = 0.44 < 1 \Rightarrow K_{FL2q} = 1$

$$K_{HL1s} = {}^{m} \sqrt{N_{HO1}/N_{HE1s}} = 0.54 < 1 \Rightarrow K_{HL1s} = 1$$

 $K_{HL2s} = {}^{m} \sqrt{N_{HO2}/N_{HE2s}} = 0.65 < 1 \Rightarrow K_{HL2s} = 1$
 $K_{FL1s} = {}^{m} \sqrt{N_{FO1}/N_{FE1s}} = 0.44 < 1 \Rightarrow K_{FL1s} = 1$
 $K_{FL2s} = {}^{m} \sqrt{N_{FO2}/N_{FE2s}} = 0.53 < 1 \Rightarrow K_{FL2s} = 1$

Calculate $[\sigma_H]$, $[\sigma_{F1}]$, $[\sigma_{F2}]$ Since the motor works in one direction, $K_{FC} = 1$, which means all K factors are equal to 1 and we can safely skip them.

For initial estimation, assume $Z_R Z_v K_{xH} = 1$ and $Y_R Y_s K_{xF} = 1$, we obtain the permissible stresses (notice they are equal in both quick and slow transmission stages):

$$[\sigma_{H1}] = \sigma_{Hlim1}^o/S_H = 518.18 \text{ (MPa)}$$

 $[\sigma_{H2}] = \sigma_{Hlim2}^o/S_H = 500 \text{ (MPa)}$
 $[\sigma_{F1}] = \sigma_{Flim1}^o/S_F = 257.14 \text{ (MPa)}$
 $[\sigma_{F2}] = \sigma_{Flim2}^o/S_F = 246.86 \text{ (MPa)}$

The mean permissible contact stress must be lower than 1.25 times of either $[\sigma_{H1}]$ or $[\sigma_{H2}]$, whichever is smaller. In this case, it is 1.25 $[\sigma_{H2}]$ or 625 MPa:

$$[\sigma_H] = \frac{1}{2} ([\sigma_{H1}] + [\sigma_{H2}]) = 509.09 \text{ (MPa)} \le 625$$

which satisfy the condition.

In case of overloading, the permissible contact and bending stresses are calculated as follows:

$$[\sigma_H]_{max} = 2.8\sigma_{ch} = 1540 \text{ (MPa)}$$

 $[\sigma_F]_{max} = 0.8\sigma_{ch} = 440 \text{ (MPa)}$

4.4 Determine basic specifications of the Transmission system

4.4.1 Determine basic parameters

Figure 1.1 shows both pairs are helical, which gives $K_a = 43$, Table 6.5 [1]. Also, the entire speed reducer has asymmetrical design, resulting in $\psi_{ba} = 0.3$, Table 6.6 [1]. This value is then used in Equation 6.16 [1] to find ψ_{bd} :

$$\psi_{bdq} = 0.53\psi_{ba}(u_q + 1) = 0.67$$

$$\psi_{bds} = 0.53\psi_{ba}(u_s + 1) = 0.65$$

Using interpolation, we approximate the factors, Table 6.7 [1]:

$$K_{H\beta q} = 1.04, K_{F\beta q} = 1.09$$

$$K_{H\beta s} = 1.06, K_{F\beta s} = 1.13$$

Since the gear system only consists of involute gears and it is also a speed reducer gearbox, we estimate a, Equation 6.15a [1]:

$$a_{q} = K_{a}(u_{q} + 1)\sqrt[3]{\frac{T_{sh1}K_{H\beta q}}{[\sigma_{H}]^{2}u_{q}\psi_{ba}}} = 83.12 \text{ (mm)}$$

$$a_{s} = K_{a}(u_{s} + 1)\sqrt[3]{\frac{T_{sh2}K_{H\beta s}}{[\sigma_{H}]^{2}u_{s}\psi_{ba}}} = 119.85 \text{ (mm)}$$

It is recommended to round up the center distances to the nearest multiple of 5 for small production, p.99 [1]. Thus, $a_{wq} = 85 \text{ mm}$ and $a_{ws} = 120 \text{ mm}$.

4.4.2 Determine gear meshing parameters

Find *m* Using Equation 6.17 [1] and Table 6.8 [1], we determine *m* for each pair of gears:

$$m_q = (0.01 \div 0.02) a_{wq} = 0.85 \div 1.7 \text{ (mm)} \Rightarrow m_q = 1.5 \text{ (mm)}$$

 $m_s = (0.01 \div 0.02) a_{ws} = 1.2 \div 2.4 \text{ (mm)} \Rightarrow m_s = 2 \text{ (mm)}$

Find z_1 , z_2 , b_w Let $\beta = 14^\circ$. Combining equation (6.18) and (6.20), we come up with the formula to calculate z_1 . Then, find z_2 and b.

$$z_{1q} = \frac{2a_{wq}\cos\beta}{m_q(u_q+1)} = 26.01 \Rightarrow z_{1q} = 27$$

$$z_{2q} = u_q z_{1q} = 87.17 \Rightarrow z_{2q} = 88$$

$$b_q = \psi_{ba} a_{wq} = 25.50 \text{ (mm)}$$

$$z_{1s} = \frac{2a_{ws}\cos\beta}{m_s(u_s+1)} = 28.42 \Rightarrow z_{1s} = 29$$

$$z_{2s} = u_s z_{1s} = 89.82 \Rightarrow z_{2s} = 90$$

$$b_s = \psi_{ba} a_{ws} = 36.00 \text{ (mm)}$$

Correct β There are 2 approaches for correction involving the change of either α or β . Because altering α leads to many other corrections $(d_1, d_2 \text{ and } a_w)$, β

will be used instead.

Since z_1 is rounded, we must find β to obtain the correct angle, ensuring that $\beta \in (8^{\circ}, 20^{\circ})$. Using equation (6.32):

$$\beta_w = \arccos \frac{m(z_1 + z_2)}{2a_w} \approx 13.59^\circ$$

Find x_1, x_2 To find x_1 and x_2 , we will follow the calculation scheme provided in p.103. Since $\beta_w \approx 13.59^\circ \in (10, 15]$, $z_{min} = 11$, which leads to z_1 satisfying condition $z_1 \ge z_{min} + 2 > 10$, according to table (6.9). Combined with $u_{hg} = 5 \ge 3.5$, we obtain $x_1 = 0.3$, $x_2 = -0.3$, disregarding the calculation of y.

4.4.3 Basic parameters

$$d_{1} = d_{w1} = \frac{mz_{1}}{\cos \beta} \approx 41.67 \text{ (mm)}$$

$$d_{2} = d_{w2} = \frac{mz_{2}}{\cos \beta} \approx 208.33 \text{ (mm)}$$

$$d_{a1} = d_{1} + 2(1 + x_{1})m \approx 45.57 \text{ (mm)}$$

$$d_{a2} = d_{2} + 2(1 + x_{2})m \approx 210.43 \text{ (mm)}$$

$$d_{f1} = d_{1} - (2.5 - 2x_{1})m \approx 38.82 \text{ (mm)}$$

$$d_{f2} = d_{2} - (2.5 - 2x_{2})m \approx 203.68 \text{ (mm)}$$

$$d_{b1} = d_{1} \cos \alpha \approx 39.15 \text{ (mm)}$$

$$d_{b2} = d_{2} \cos \alpha \approx 195.77 \text{ (mm)}$$

$$\alpha_{t} = \alpha_{tw} = \arctan \frac{\tan \alpha}{\cos \beta_{w}} \approx 20.53^{\circ}$$

$$v = \frac{\pi d_{1} n_{sh1}}{6 \times 10^{4}} \approx 6.39 \text{ (m/s)}$$

4.4.4 Find $[\sigma_{Hw}]$, $[\sigma_{Fw1}]$ and $[\sigma_{Fw2}]$

In this section, we will try to approximate these parameters based on the factors Z_R , Z_V , K_{xH} and Y_R , Y_s , K_{xF} to substitute to equation (6.1) and (6.2):

$$[\sigma_{Hw}] = [\sigma_H] Z_R Z_V K_{xH}$$
$$[\sigma_{Fw}] = [\sigma_F] Y_R Y_S K_{xF}$$

Assuming smooth surface condition, $Z_R = 1$.

$$Z_V = 0.85v^{0.1} \approx 1.02$$
 with $H \le 350$.

In case of
$$v > 5$$
 (m/s), $K_{xH} = 1$.

The pair of gears are properly polished, which makes $Y_R = 1.1$

$$Y_s = 1.08 - 0.0695 \ln(m) \approx 1.05$$

Since $d_{a1}, d_{a2} \le 400 \text{ (mm)}, K_{xF} = 1$, which leads to:

$$[\sigma_{Hw}] = 520.93 \, (\text{MPa})$$

$$[\sigma_{Fw1}] = 297.51 \text{ (MPa)}$$

$$[\sigma_{Fw2}] = 285.61 \text{ (MPa)}$$

Contact stress analysis 4.4.5

From section 6.3.3. in the text, contact stress applied on a gear surface must satisfy the condition below:

$$\sigma_{H} = z_{M} z_{H} z_{\varepsilon} \sqrt{2T_{sh1} K_{H} \frac{u_{hg} + 1}{b u_{hg} d_{w1}^{2}}} \leq [\sigma_{Hw}]$$

Find $z_M = 274$, according to table (6.5)

Find
$$z_H$$
 $\beta_b = \arctan(\cos \alpha_t \tan \beta_w) \approx 12.76^\circ \Rightarrow z_H = \sqrt{2 \frac{\cos \beta_b}{\sin(2\alpha_{tw})}} \approx 1.72$

$$\varepsilon_{\alpha} = \frac{\sqrt{d_{a1}^2 - d_{b1}^2} + \sqrt{d_{a2}^2 - d_{b2}^2} - 2a_w \sin \alpha_{tw}}{2\pi m \frac{\cos \alpha_t}{\cos \beta_w}} \approx 1.41$$

$$\varepsilon_{\beta} = b \frac{\sin \beta_w}{m\pi} \approx 3.12 > 1 \Rightarrow z_{\varepsilon} = \varepsilon_{\alpha}^{-0.5} \approx 0.86$$

$$\varepsilon_{\beta} = b \frac{\sin \beta_{w}}{m\pi} \approx 3.12 > 1 \Rightarrow z_{\varepsilon} = \varepsilon_{\alpha}^{-0.5} \approx 0.86$$

Find K_H We find K_H using equation $K_H = K_{H\beta}K_{H\alpha}K_{H\nu}$

From table (6.13),
$$v \le 10 \text{ (m/s)} \Rightarrow AG = 8$$

From table (P2.3), using interpolation, we approximate:

$$K_{Hv} \approx 1.07, K_{Fv} \approx 1.18$$

From table (6.14), using interpolation, we approximate:

$$K_{H\alpha} \approx 1.1, K_{F\alpha} \approx 1.29$$

$$\Rightarrow K_H \approx 1.3$$

Find σ_H After calculating z_M , z_H , z_{ε} , K_H , we get the following result:

$$\sigma_H \approx 477.51 \, (\text{MPa}) \le [\sigma_{Hw}] \approx 509.09 \, (\text{MPa})$$

4.4.6 Bending stress analysis

For safety reasons, the following conditions must be met:

$$\sigma_{F1} = 2 \frac{T_{sh1} K_F Y_{\varepsilon} Y_{\beta} Y_{F1}}{b d_{w1} m_n} \le [\sigma_{Fw1}]$$

$$\sigma_{F2} = \frac{\sigma_{F1} Y_{F2}}{Y_{F1}} \le [\sigma_{Fw2}]$$

Find Y_{ε} Knowing that $\varepsilon_{\alpha} \approx 1.41$, we can calculate $Y_{\varepsilon} = \varepsilon_{\alpha}^{-1} \approx 0.71$

Find
$$Y_{\beta}$$
 $Y_{\beta} = 1 - \frac{\beta_w}{140} \approx 0.9$

Find Y_F Using formula $z_v = z \cos^{-3}(\beta_w)$ and table (6.18): $z_{v1} = z_1 \cos^{-3}(\beta_w) \approx 29.4 \Rightarrow Y_{F1} \approx 3.54$ $z_{v2} = z_2 \cos^{-3}(\beta_w) \approx 147.01 \Rightarrow Y_{F2} \approx 3.63$

Find K_F Using $K_{F\beta}$, $K_{F\alpha}$, $K_{F\nu}$ calculated from the sections above, we derive: $K_F = K_{F\beta}K_{F\alpha}K_{F\nu} \approx 1.91$

Find σ_F Since $m_n = m \cos \beta_w \approx 1.46$, substituting all the values, we find out that:

$$\sigma_{F1} \approx 114.11 \text{ (MPa)} \leq [\sigma_{Fw1}] \approx 297.51 \text{ (MPa)}$$

 $\sigma_{F2} \approx 117.01 \text{ (MPa)} \leq [\sigma_{Fw2}] \approx 285.61 \text{ (MPa)}$

4.4.7 Force on shafts

$$F_t = \frac{2T_{sh1}}{d_{w1}} \approx 2402.28 \text{ (N)}$$

 $F_r = F_t \tan \alpha_{tw} \approx 899.55 \text{ (N)}$
 $F_a = F_t \tan \beta_w \approx 580.75 \text{ (N)}$

In summary, we have the following table:

	pinion	driving gear
H (HB)	250	240
$[\sigma_F]$ (MPa)	257.14	246.86
$[\sigma_H]$ (MPa)	509.09	
$[\sigma_H]_{max}$ (MPa)	1540	
$[\sigma_F]_{max}$ (MPa)	440	
a_w (mm)	100	
b (mm)	50	
m (mm)	1.5	
d_{w} (mm)	33.33	166.67
d_a (mm)	37.23	168.77
d_f (mm)	30.48	162.02
$d_b (\mathrm{mm})$	31.32	156.62
u_{hg}	5	
v (m/s)	5	
x (mm)	0.3	-0.3
Z	21	105
α_{tw} (°)	20.65	
$\beta_{\scriptscriptstyle W}$ (°)	19.09	

Table 4.1: Gearbox specifications

Lorem ipsum dolor sit amet, consectetuer adipiscing elit. Ut purus elit, vestibulum ut, placerat ac, adipiscing vitae, felis. Curabitur dictum gravida mauris. Nam arcu libero, nonummy eget, consectetuer id, vulputate a, magna. Donec vehicula augue eu neque. Pellentesque habitant morbi tristique senectus et netus et malesuada fames ac turpis egestas. Mauris ut leo. Cras viverra metus rhoncus sem. Nulla et lectus vestibulum urna fringilla ultrices. Phasellus eu tellus sit amet tortor gravida placerat. Integer sapien est, iaculis in, pretium quis, viverra ac, nunc. Praesent eget sem vel leo ultrices bibendum. Aenean faucibus. Morbi dolor nulla, malesuada eu, pulvinar at, mollis ac, nulla. Curabitur auctor semper nulla. Donec varius orci eget risus. Duis nibh mi, congue eu, accumsan eleifend, sagittis quis, diam. Duis eget orci sit amet orci dignissim rutrum.

Nam dui ligula, fringilla a, euismod sodales, sollicitudin vel, wisi. Morbi auctor lorem non justo. Nam lacus libero, pretium at, lobortis vitae, ultricies et, tellus. Donec aliquet, tortor sed accumsan bibendum, erat ligula aliquet magna, vitae ornare odio metus a mi. Morbi ac orci et nisl hendrerit mollis. Suspendisse

ut massa. Cras nec ante. Pellentesque a nulla. Cum sociis natoque penatibus et magnis dis parturient montes, nascetur ridiculus mus. Aliquam tincidunt urna. Nulla ullamcorper vestibulum turpis. Pellentesque cursus luctus mauris.

Nulla malesuada porttitor diam. Donec felis erat, congue non, volutpat at, tincidunt tristique, libero. Vivamus viverra fermentum felis. Donec nonummy pellentesque ante. Phasellus adipiscing semper elit. Proin fermentum massa ac quam. Sed diam turpis, molestie vitae, placerat a, molestie nec, leo. Maecenas lacinia. Nam ipsum ligula, eleifend at, accumsan nec, suscipit a, ipsum. Morbi blandit ligula feugiat magna. Nunc eleifend consequat lorem. Sed lacinia nulla vitae enim. Pellentesque tincidunt purus vel magna. Integer non enim. Praesent euismod nunc eu purus. Donec bibendum quam in tellus. Nullam cursus pulvinar lectus. Donec et mi. Nam vulputate metus eu enim. Vestibulum pellentesque felis eu massa.

Quisque ullamcorper placerat ipsum. Cras nibh. Morbi vel justo vitae lacus tincidunt ultrices. Lorem ipsum dolor sit amet, consectetuer adipiscing elit. In hac habitasse platea dictumst. Integer tempus convallis augue. Etiam facilisis. Nunc elementum fermentum wisi. Aenean placerat. Ut imperdiet, enim sed gravida sollicitudin, felis odio placerat quam, ac pulvinar elit purus eget enim. Nunc vitae tortor. Proin tempus nibh sit amet nisl. Vivamus quis tortor vitae risus porta vehicula.

Fusce mauris. Vestibulum luctus nibh at lectus. Sed bibendum, nulla a faucibus semper, leo velit ultricies tellus, ac venenatis arcu wisi vel nisl. Vestibulum diam. Aliquam pellentesque, augue quis sagittis posuere, turpis lacus congue quam, in hendrerit risus eros eget felis. Maecenas eget erat in sapien mattis porttitor. Vestibulum porttitor. Nulla facilisi. Sed a turpis eu lacus commodo facilisis. Morbi fringilla, wisi in dignissim interdum, justo lectus sagittis dui, et vehicula libero dui cursus dui. Mauris tempor ligula sed lacus. Duis cursus enim ut augue. Cras ac magna. Cras nulla. Nulla egestas. Curabitur a leo. Quisque egestas wisi eget nunc. Nam feugiat lacus vel est. Curabitur consectetuer.

Suspendisse vel felis. Ut lorem lorem, interdum eu, tincidunt sit amet, laoreet vitae, arcu. Aenean faucibus pede eu ante. Praesent enim elit, rutrum at, molestie non, nonummy vel, nisl. Ut lectus eros, malesuada sit amet, fermentum

eu, sodales cursus, magna. Donec eu purus. Quisque vehicula, urna sed ultricies auctor, pede lorem egestas dui, et convallis elit erat sed nulla. Donec luctus. Curabitur et nunc. Aliquam dolor odio, commodo pretium, ultricies non, pharetra in, velit. Integer arcu est, nonummy in, fermentum faucibus, egestas vel, odio.

Sed commodo posuere pede. Mauris ut est. Ut quis purus. Sed ac odio. Sed vehicula hendrerit sem. Duis non odio. Morbi ut dui. Sed accumsan risus eget odio. In hac habitasse platea dictumst. Pellentesque non elit. Fusce sed justo eu urna porta tincidunt. Mauris felis odio, sollicitudin sed, volutpat a, ornare ac, erat. Morbi quis dolor. Donec pellentesque, erat ac sagittis semper, nunc dui lobortis purus, quis congue purus metus ultricies tellus. Proin et quam. Class aptent taciti sociosqu ad litora torquent per conubia nostra, per inceptos hymenaeos. Praesent sapien turpis, fermentum vel, eleifend faucibus, vehicula eu, lacus.

Pellentesque habitant morbi tristique senectus et netus et malesuada fames ac turpis egestas. Donec odio elit, dictum in, hendrerit sit amet, egestas sed, leo. Praesent feugiat sapien aliquet odio. Integer vitae justo. Aliquam vestibulum fringilla lorem. Sed neque lectus, consectetuer at, consectetuer sed, eleifend ac, lectus. Nulla facilisi. Pellentesque eget lectus. Proin eu metus. Sed porttitor. In hac habitasse platea dictumst. Suspendisse eu lectus. Ut mi mi, lacinia sit amet, placerat et, mollis vitae, dui. Sed ante tellus, tristique ut, iaculis eu, malesuada ac, dui. Mauris nibh leo, facilisis non, adipiscing quis, ultrices a, dui.

Morbi luctus, wisi viverra faucibus pretium, nibh est placerat odio, nec commodo wisi enim eget quam. Quisque libero justo, consectetuer a, feugiat vitae, porttitor eu, libero. Suspendisse sed mauris vitae elit sollicitudin malesuada. Maecenas ultricies eros sit amet ante. Ut venenatis velit. Maecenas sed mi eget dui varius euismod. Phasellus aliquet volutpat odio. Vestibulum ante ipsum primis in faucibus orci luctus et ultrices posuere cubilia Curae; Pellentesque sit amet pede ac sem eleifend consectetuer. Nullam elementum, urna vel imperdiet sodales, elit ipsum pharetra ligula, ac pretium ante justo a nulla. Curabitur tristique arcu eu metus. Vestibulum lectus. Proin mauris. Proin eu nunc eu urna hendrerit faucibus. Aliquam auctor, pede consequat laoreet varius, eros tellus scelerisque quam, pellentesque hendrerit ipsum dolor sed augue. Nulla

nec lacus.

Suspendisse vitae elit. Aliquam arcu neque, ornare in, ullamcorper quis, commodo eu, libero. Fusce sagittis erat at erat tristique mollis. Maecenas sapien libero, molestie et, lobortis in, sodales eget, dui. Morbi ultrices rutrum lorem. Nam elementum ullamcorper leo. Morbi dui. Aliquam sagittis. Nunc placerat. Pellentesque tristique sodales est. Maecenas imperdiet lacinia velit. Cras non urna. Morbi eros pede, suscipit ac, varius vel, egestas non, eros. Praesent malesuada, diam id pretium elementum, eros sem dictum tortor, vel consectetuer odio sem sed wisi.

References

[1] Chat Trinh and Uyen Van Le. *Thiet Ke He Dan Dong Co Khi*. 6th ed. Vol. 1. Vietnam Education Publishing House Limited, 2006.