VIETNAM NATIONAL UNIVERSITY HO CHI MINH CITY HCM UNIVERSITY OF TECHNOLOGY FACULTY OF MECHANICAL ENGINEERING - MECHATRONICS DEPARTMENT



ENGINEERING INTERNSHIP REPORT

Air Compressor Modeling using MATLAB

Submitted By: Nguyen Quy Khoi

Student ID: 1852158

Submitted To: Nguyen Tan Tien

Internship Office: DCSELab

Acknowledgements

Acknowledgements should be expressed as a special thanks to staff members of industrial companies, your supervisors, your collaborator/teammates. This chapter should not be longer than 1 page.

Lorem ipsum dolor sit amet, consectetuer adipiscing elit. Ut purus elit, vestibulum ut, placerat ac, adipiscing vitae, felis. Curabitur dictum gravida mauris. Nam arcu libero, nonummy eget, consectetuer id, vulputate a, magna. Donec vehicula augue eu neque. Pellentesque habitant morbi tristique senectus et netus et malesuada fames ac turpis egestas. Mauris ut leo. Cras viverra metus rhoncus sem. Nulla et lectus vestibulum urna fringilla ultrices. Phasellus eu tellus sit amet tortor gravida placerat. Integer sapien est, iaculis in, pretium quis, viverra ac, nunc. Praesent eget sem vel leo ultrices bibendum. Aenean faucibus. Morbi dolor nulla, malesuada eu, pulvinar at, mollis ac, nulla. Curabitur auctor semper nulla. Donec varius orci eget risus. Duis nibh mi, congue eu, accumsan eleifend, sagittis quis, diam. Duis eget orci sit amet orci dignissim rutrum.

Nam dui ligula, fringilla a, euismod sodales, sollicitudin vel, wisi. Morbi auctor lorem non justo. Nam lacus libero, pretium at, lobortis vitae, ultricies et, tellus. Donec aliquet, tortor sed accumsan bibendum, erat ligula aliquet magna, vitae ornare odio metus a mi. Morbi ac orci et nisl hendrerit mollis. Suspendisse ut massa. Cras nec ante. Pellentesque a nulla. Cum sociis natoque penatibus et magnis dis parturient montes, nascetur ridiculus mus. Aliquam tincidunt urna. Nulla ullamcorper vestibulum turpis. Pellentesque cursus luctus mauris.

Abstract

Data acquisition is one of the crucial steps of designing a mechatronic system. Changes in the environment must be observed for decision making purposes.

Sensors can be seen anywhere such as natural or man-made objects. The natural sensors, like those found in living organisms, usually respond with signals having electrochemical character. In man-made devices, information is also transmitted and process in electrical form. Application for sensors is almost limitless, from simple system such as car door monitoring arrangement to extremely complex one like Mars Exploration Rover – B.

Since the topic about sensors is so vast and technical, designing a complex sensor is beyond the scope of this report. Therefore, in our project, we only focus on flow sensor, and specifically how to make the best of the sensor catalog. This goal includes what parameters are important in choosing the right flow sensor for one's project, expected failure modes during operation and maintenance of the sensor, which makes the report somewhat practical in designing the system as a whole.

Contents

1	Chai	racteristics of a sensor	7
	1.1	Mobile Communication Devices	7
	1.2	Full-Scale Input/Output	
	1.3	Accuracy	8
	1.4	Possible types of error	9
	1.5	Resolution	10
	1.6	Special output characteristics	10
	1.7	Environmental factors	11
	1.8	Reliability	12
	1.9	Application characteristics	12
	1.10	Uncertainty	12
2	Intro	oduction	13
	2.1	Characteristics of a flow sensor	13
	2.2	Several examples of flow sensors	13
		2.2.1 Pressure gradient technique	13
		2.2.2 Thermal transport sensors	14
3	Sum	mary and Conclusions	15
Gl	ossary	y	16
References			
Index			

List of Figures

1.1	Built-in sensors in a typical present-day smartphone	7
1.2	Non-linearity error using (from left to right): end-range values;	
	best straight line for all values; best straight line through the zero point	10
2.1	Pressure gradient technique example using narrow channel flow. Small cross section causes	14

List of Tables

Chapter 1

Characteristics of a sensor

When designing a mechatronic system, sensor is crucial for data acquisition and generating an adequate response. However, if a engineer only relies on the best available sensor, the product price will be higher than necessary, resulting in customers lost to competitive manufacturers. Therefore, this chapter is dedicated to accommodate selecting the right sensor for one's application with common characteristics available on datasheets.

1.1 Mobile Communication Devices



Figure 1.1: Built-in sensors in a typical present-day smartphone

Mobile Communication Devices (MCD) sensors are designed for portability and full integration with other components inside a hand-held device. It is a self-containing sensing module that detects, conditions, digitizes, processes, outputs and communicates information while being small, light, accurate, stable, fast-response, etc. A generic purpose device (e.g. smartphones, tablets, smartwatches) contains dozens of them for different applications and is categorized in 4 areas:

1. **Industrial** for detecting noncontact tempertaure, thermal imaging, humidity, air flow ionizing radiation, smell, diaelectric constant of objects,

maerial composition, range (distance), air pressure, produce freshness, etc.

- 2. **Medical** for the inner (core) and skin body temperatures, thermal imaging, arterial blood pressure, EKG, blood factors (glucose, cholesterol, hemoglobin oxygen saturation), deep body imaging, smell (e-nose), behavior modification, etc.
- 3. **Military** for night vision, detecting poisonous gases, proximity, ionizing radiation, explosives, chemical and biological agents, etc.
- 4. **Consumer** for the body core temperature, heart rate, radon gas, pregnancy detection, breathalizer for alcohol and hydrogen sulfide, food composition, behavior modification, proximity, V level, electromagnetic pollution, surface temperature, etc.

1.2 Full-Scale Input/Output

A *span* or an *input full scale* (FS) is a dynamic range of stimuli convertible by a sensor. In a datasheet, it is regarded as the highest possible input value without causing unacceptably large error. For sensors with broad response characteristics, the span is often expressed in decibels, which is a logarithmic measure of ratios of either power or force (voltage).

A *full-scale output* (FSO) for an analog output is the difference between electrical output signals at 2 ends of the input signals. For digital output, it is the maximum digital count the A/D converter can resolve for maximum FS.

1.3 Accuracy

It is defined as *maximum*, or *typical*, or *average* error of the sensor alone. The rating of accuracy is represented in 4 common forms, depending on the application:

- 1. *Directly in terms of measured value of a stimulus*, which is used when error is independent on the input signal magnitude.
- 2. *In percentage of FS*, which is useful for a sensor with a linear transfer function and can be thought as an alternative of the approach above. For nonlinear transfer function, the representation may be misleading.
- 3. *In percentage of the measured signal*, which is useful for a nonlinear transfer function, even with very dynamic inputs. However, the error typically does not proportionally scale with the input magnitude.

4. *In terms of the output signal*, which is useful for sensors with a digital output format.

In reality, a datasheet mixes 2 or more forms and take whichever value is the largest. In this way, the error can be evaluated more accurately.

1.4 Possible types of error

In a datasheet, tolerance and error limit are paramount for any measuring equipment, which the manufacture always dedicates a section for. Distinguishing the types of error is helpful to determine the suitable sensor for designing a mechatronic system. Generally, there are 6 types of error:

Calibration error Calibration error occurs while adjusting a sensor. In dynamic system and control, it is categorized as *disturbance*, which is quantitative data and contributes the systematic error. Another source of errors regarding calibration is a reference sensor. This type of sensor is considered as national standard, which all manufactured sensors rely on. Therefore, for absolute accuracy, the error from "standardized sensors" is considered.

Hysteresis error Hysteresis error is the maximum deviation between output values given the same input signal. For example, if the sensitivity of the sensor is $10 \,\mathrm{mV/mm}$, the hysteresis error in terms of displacement units is $2 \,\mathrm{mm}$. Possible causes of this faulty result are geometry of design, friction or deformation of material.

Nonlinearity error If the error is assumed to , nonlinearity error will be specified to compensate for any faulty assumptions. It is the maximum deviation of a real transfer function from the approximation straight line. After several calibration runs, the worst linearity result is stated. This type of error is crucial if the output signal requires best accuracy in a small range (e.g. medical thermometer measures body temperature between $36-38^{\circ}$ C). Oftentimes, manufacturers are inclined to publish the smallest possible nonlinearity error without specifying what approximation method is used.

Saturation error Saturation error occurs when the input signal exceeds the operating limit of a sensor.




Figure 1.2: Non-linearity error using (from left to right): end-range values; best straight line for all values; best straight line through the zero point.

Repeatability error Repeatability error causes a sensor to output different values under identical conditions. Possible noises for the error are thermal conductivity, charge, deformation, etc.

Dead band error Dead band error is the insensitivity of a sensor in a specific range of the input signals, which generates output signals between a certain value (often zero).

1.5 Resolution

Digital input-output signals are not continuous as shown in the figures in a datasheet but rather distinguish data points. The distance between 2 consecutive data points is defined as resolution. Depending on manufacturers, the step size may be specified as typical, average, or worst.

1.6 Special output characteristics

Depending on sensor types, specifying input properties might be necessary. For instance, in case of flow sensors, thermal transport sensors require identifying temperature bandwidth to give the accurate response.

Impedance When working with an electronic sensor, the output impedance of the sensor Z_{out} and the input impedance of the connecting system Z_{in} should be acknowledge. A current generating sensor should have high Z_{out} and low Z_{in} . This is the opposite for voltage generating sensor.

Format For mechatronic systems, programming a microcontroller or microprocessor needs the output format of the sensor. The output electrical characteristics may include voltage, current, charge, frequency, amplitude, phase, polarity, shape of a signal, time delay and digital code. These responses can be displayed in formats such as binary, text (ASCII), or digital output, etc. with various forms of communication (e.g. serial link, PWM, I^2C).

Excitation Analogues to a match catching fire with a spark, excitation signal could be included in a datasheet. An exapmle of an excitation signal is electric current passing through a thermistor to measure its temperature-dependent resistance.

Dynamic characteristics Besides from steady input signals, dynamic and time-varying stimuli are also considered. The sensor responses slowly to this input type, which generates dynamic error. At best, the error is a delay. At worst, it causes undesirable oscillations. In such cases, Dynamic Systems and Control course is provided to discuss extensively about this topic.

1.7 Environmental factors

Generally, all possible environmental factors that may affect the sensor performance are specified by manufacturers. In a datasheet, it is typical to include information about the following factors:

- 1. *Storage condition*, which specifies the highest and lowest storage temperature. It also has maximum relative humidities at these temperatures and may be mentioned as "noncondensing". Along with operating temperature range, this information is *one of the most common environmental factors* available in any datasheet.
- 2. *Short-term stability* is manifested as changes in the sensor's performance within minutes, hours, or days, which essentially is another way to express bidirectional repeatability.
- 3. *Long-term stability* is the irreversible change in the material's electrical, mechanical, chemical or thermal properties. Similar to heat treated materials, a sensor can improve its stability by *pre-aging*. For instance, a sensor may be periodically swung from freezing to hot temperatures before being calibrated and installed into a product.
- 4. Environmental conditions during normal operation affects the transfer function of a sensor. An example is a strain gauge whose sensitivity

increases with temperature. Even if the manufacture does not specify these conditions in the datasheet, it is the responsibility of an engineer to simulate and prototype the end-product corresponding to the environment.

1.8 Reliability

In statistical terms, reliability is the probability that the device will function without failure over a specified time or a number of uses. Reliability specifies a failure is a temporary or permanent malfunction of a device. Although this is an important property of a sensor, the information is not readily available in most datasheet due to the absence of measuring standards of reliability. Therefore, an engineer should be ready to do the test by any means. Some example testing procedures are MTBF, extreme testing, accelerated life testing, HALT testing, FOAT testing, etc.

1.9 Application characteristics

This information includes geometry and other simple physical specifications such as design, weight, power consumption and overall dimensions. Although price heavily influences a sensor's performance, any amount of cost is justified if reliability and accuracy are of a paramount importance.

1.10 Uncertainty

While error is what we unknowably get when we measure, uncertainty is what we think how large that error might be. No matter how well a sensor is made, there always exists obscure factors. Even if they are recognized, it is impossible to measure exactly (e.g. human factor). Attempts have been made to quantitatively identify them: evaluation through statistical methods, preceding measurement data, personal experience, manufacturer's specifications, uncertainty data referenced from handbooks and manuals, etc.

Chapter 2

Introduction

2.1 Characteristics of a flow sensor

There are 2 types of moving media [1]:

- liquids. Ex: water, oil, gasoline.
- air and gas. *Ex*: O₂, N₂, CO₂, CH₄.

Although flow sensors may be simple as detecting velocity of the fluid or air/gas,

2.2 Several examples of flow sensors

2.2.1 Pressure gradient technique

This technique is applicable only for measuring **steady flow of nonviscous**, **incompressible medium** using Bernoulli equation, which relates to *flow resistance*. The working principle of this technique is as follows:

- 1. Create a medium impeding the flow motion in a section of the pipe, such as orifices, porous plugs, and Venturi tubes.
- 2. Place 1 differential pressure sensor between the normal sections or 2 absolute pressure sensors in each normal section of the pipe.
- 3. Because the high resistance area creates a slight pressure difference in the flow, the mass transferred through the pipe can be estimated.

The equation for finding mass flow is:

$$q = \epsilon A_2 \sqrt{\Delta p} \tag{2.1}$$

where

14 2 Introduction




Figure 2.1: Pressure gradient technique example using narrow channel flow. Small cross section causes

- q is the mass flow per unit time, kg/s.
- ϵ is the calibration coefficient.
- A_2 is the cross section of the high resistance area, m^2 .
- Δp is the pressure difference, Pa.

Derivation of the equation is provided in chapter 12 [1].

Advantage of the pressure gradient method is in the absence of moving components and use of standard pressure sensors that are readily available. A disadvantage is in the restriction of flow by a resistive device.

2.2.2 Thermal transport sensors

Chapter 3

Summary and Conclusions

Last chapter. Provide discussions: what should be done/ has been reached; difficulties in the making of this project. Describe logical relation of the previous chapters. (optional) give advice for a reasonable continuation of the project.

During the internship, I had a chance to get acquainted with a new working environment. I have accumulated experience in industry knowledge as well as experience skills above [2].

I was trained in problem solving skills in many stages, trying to complete the job in the shortest time, boldly exchanging and sharing knowledge. At the same time, it also fosters a lot of knowledge about graphic software as well as programming skills to solve the problems learned in school but professionally and saves more time [li_1984_hng].

Shortcomings: the skill is not mature which still takes a long time to execute; the ability to think and propose design plans is limited due to the lack of practical experience and in-depth knowledge [li_1984_hng].

Solution: practice more software skills, add additional specialized knowledge that is lacking.

latex

mathematics

Chezy equation

Glossary name Complicated name (thuật ngữ tiếng Việt)

Glossary

Chezy equation Chezy equation,

$$a = b + c$$

which is commonly used. 15

complicated name (thuật ngữ tiếng Việt) glossary description. 15

glossary name glossary description. 15

latex Is a mark up language specially suited for scientific documents. 15mathematics Mathematics is what mathematicians do. 15

References

- [1] Jacob Fraden. *Handbook of modern sensors: physics, designs, and applications*. 5th ed. Vol. 1. Springer International Publishing Switzerland, 2016, pp. 453–484.
- [2] Dan B Marghitu. *Mechanisms and Robots Analysis with MATLAB*. Dordrecht Springer, 2009.

Index

index 1, 15

index 2, 15