# Machine Elements Report

June 25, 2020

# **Contents**

1	Mot	tor Design	4
	1.1	Nomenclature	4
	1.2	Calculate $\eta_{sys}$	4
	1.3	Calculate $P_{motor}$	5
	1.4	Calculate $n_{motor}$	5
	1.5	Choose motor	5
	1.6	Calculate power, rotational speed and torque of the motor and 2 shafts	6
		1.6.1 Power	6
		1.6.2 Rotational speed	6
		1.6.3 Torque	6
2	Cha	in Drive Design	7
	2.1	Nomenclature	7
	2.2	Find $p$	8
	2.3	Find $a$ , $x_c$ and $i$	9
	2.4	Strength of chain drive	9
	2.5	Force on shaft	10
3	Gea	rbox Design (Helix gears)	11
	3.1	Nomenclature	11
	3.2	Choose material	13
	3.3	Calculate $[\sigma_H]$ and $[\sigma_F]$	13

		3.3.1	Working cycle of bearing stress	13
		3.3.2	Working cycle of equivalent tensile stress	13
		3.3.3	Aging factor	14
		3.3.4	Calculate $[\sigma_H]$ and $[\sigma_F]$	14
	3.4	Transn	nission Design	14
		3.4.1	Determine basic parameters	14
		3.4.2	Determine gear meshing parameters	15
		3.4.3	Other parameters	15
		3.4.4	Contact stress analysis	16
		3.4.5	Bending stress analysis	17
4	Shaf	ft Desig	n	19
	4.1	Nomer	nclature	20
	4.2	Choose	e material	21
	4.3	Tranm	ission Design	21
		4.3.1	Load on shafts	21
		4.3.2	Preliminary calculations	22
		4.3.3	Identify the distance between bearings and applied forces	22
		4.3.4	Determine shaft diameters and lengths	23

## **List of Tables**

1.1	System properties	6
2.1	Table of chain drive specifications	10
3.1	Gearbox specifications	18

- $F_t$  tangential force, N
- v conveyor belt speed, m/s
- D pulley diameter, mm
- L service life, year
- T working torque,  $N \cdot mm$
- t working time, s
- $\delta_u$  error of speed ratio, %

### **Chapter 1**

# **Motor Design**

#### 1.1 Nomenclature

$\eta_c$	coupling efficiency	$n_{bc}$	rotational speed of belt conveyor,
$\eta_b$	bearing efficiency		rpm
$\eta_{hg}$	helical gear efficiency	$n_{sh}$	rotational speed of shaft, rpm
$\eta_{ch}$	chain drive efficiency	$u_{hg}$	transmission ratio of helical gear
$\eta_{sys}$	efficiency of the system	$u_{ch}$	transmission ratio of chain drive
$P_m$	maximum operating power of belt	$u_{sys}$	transmission ratio of the system
	conveyor, kW	$T_{motor}$	motor torque, $N \cdot mm$
$P_{w}$	opearting power of belt conveyor	$T_{sh}$	shaft torque, $N \cdot mm$
	given a workload, kW		
$P_{motor}$	calculated motor power to drive the		
	system, kW		
$P_{sh}$	operating power of shaft, kW		

### **1.2** Calculate $\eta_{sys}$

From table 2.3:

$$\eta_c = 1, \eta_b = 0.99, \eta_{hg} = 0.96, \eta_{ch} = 0.95$$

$$\eta_{sys} = \eta_c \eta_b^3 \eta_{hg} \eta_{ch} \approx 0.88$$

#### **1.3** Calculate $P_{motor}$

$$P_m = \frac{F_t v}{1000} \approx 13.73 \text{ (kW)}$$

From equation (2.13):

$$P_{w} = P_{m} \sqrt{\frac{\left(\frac{T_{1}}{T}\right)^{2} t_{1} + \left(\frac{T_{2}}{T}\right)^{2} t_{2}}{t_{1} + t_{2}}} \approx 10.41 \text{ (kW)}$$

$$P_{motor} = \frac{P_{w}}{\eta_{sys}} \approx 11.76 \text{ (kW)}$$

#### **1.4** Calculate $n_{motor}$

$$n_{bc} = \frac{6 \times 10^4 v}{\pi D} \approx 116.5 \text{ (rpm)}$$

$$u_{ch} = 5, u_{hg} = 5 \text{ (table 2.4)}$$

$$u_{sys} = u_{ch} u_{hg} = 25$$

$$n_{motor} = u_{sys} n_{bc} \approx 2912.54 \text{ (rpm)}$$

#### 1.5 Choose motor

The operating power and rotational speed of the chosen motor must be larger than estimated  $P_{motor}$  and  $n_{motor}$ , respectively. Thus, from table P1.3, we choose motor 4A160S2Y3 operating at 15 kW and 2930 rpm

$$\Rightarrow P_{motor} = 15 \text{ kW}, n_{motor} = 2930 \text{ (rpm)}$$

Recalculating  $u_{sys}$  with the new  $P_{motor}$  and  $n_{motor}$ , we obtain:

$$u_{sys} = \frac{n_{motor}}{n_{bc}} \approx 25.15$$

Assuming  $u_{hg} = const$ :

$$u_{ch} = \frac{u_{sys}}{u_{hg}} \approx 5.03$$

# 1.6 Calculate power, rotational speed and torque of the motor and 2 shafts

#### **1.6.1** Power

$$P_{ch} = P_w \approx 10.41 \text{ (kW)}$$

$$P_{sh2} = \frac{P_{ch}}{\eta_{ch}} \approx 10.96 \text{ (kW)}$$

$$P_{sh1} = \frac{P_{sh2}}{\eta_b \eta_{hg}} \approx 11.53 \text{ (kW)}$$

$$P_{motor} = \frac{P_{sh1}}{\eta_b \eta_c} \approx 11.64 \text{ (kW)}$$

#### 1.6.2 Rotational speed

$$n_{sh1} = n_{motor} = 2930 \text{ (rpm)}$$
  
 $n_{sh2} = \frac{n_{sh1}}{u_{hg}} = 586 \text{ (rpm)}$ 

#### **1.6.3** Torque

$$T_{motor} = 9.55 \times 10^{6} \frac{P_{motor}}{n_{motor}} \approx 37950.46 \,(\text{N} \cdot \text{mm})$$

$$T_{sh1} = 9.55 \times 10^{6} \frac{P_{sh1}}{n_{sh1}} \approx 37570.93 \,(\text{N} \cdot \text{mm})$$

$$T_{sh2} = 9.55 \times 10^{6} \frac{P_{sh2}}{n_{sh2}} \approx 178537.08 \,(\text{N} \cdot \text{mm})$$

In summary, we obtain the following table:

	Motor	Shaft 1	Shaft 2
P(kW)	11.64	11.527	10.96
и	5	5.03	
n (rpm)	2930	2930	586
$T(N \cdot mm)$	37950.44	37570.93	178537.08

Table 1.1: System properties

### Chapter 2

# **Chain Drive Design**

#### 2.1 Nomenclature

$z_1$	number of teeth on the driving	q	mass per meter of chain, kg/m
	sprocket	$v_1$	driving sprocket speed, m/s
$z_2$	number of teeth on the driven	$F_t$	tangential force on shaft, N
	sprocket	$F_{v}$	centrifugal force, N
$z_{max}$	maximum number of teeth on the	$F_0$	tension from passive chain part, N
	driven sprocket	$F_r$	force on shaft, N
[P]	permissible power, kW	$n_{ch}$	rotational speed of chain drive,
p	sprocket pitch, mm		rpm
$d_1$	driving sprocket diameter, mm	$n_{01}$	experimental rotational speed,
$d_2$	driven sprocket diameter, mm		rpm
$d_c$	pin diameter, mm	$k_z$	coefficient of number of teeth
$\boldsymbol{B}$	bush length, mm	$k_n$	coefficient of rotational speed
Q	permissible load, N	k	overall factor
a	center distance, mm	$k_0$	arrangement of drive factor
$a_{min}$	minimum center distance, mm	$k_a$	center distance and chain's length
$a_{max}$	maximum center distance, mm		factor

x number of links  $k_{dc}$  chain tension factor

 $x_c$  an even number of links  $k_{bt}$  lubrication factor

i impact times per second  $k_d$  dynamic loads factor

[i] permissible impact times per  $k_c$  rating factor

second  $k_f$  loosing factor

s safety factor  $k_x$  chain weight factor

[s] permissible safety factor

#### **2.2** Find p

$$n_{ch} = n_{sh2} = 586 \, (\text{rpm})$$

**Find** z Since  $z_1$  and  $z_2$  is preferably an odd number (p.80):

$$z_1 = 29 - 2u_{ch} = 18.94 \approx 19$$

$$z_2 = u_{ch} z_1 = 95.57 \approx 97 \le z_{max} = 120$$

**Find** k Since  $n_{ch} = 586 \approx 600$  (rpm), choose  $n_{01} = 600$  (rpm), which is obtained from table 5.5. Then, we calculate  $k_z$  and  $k_n$ 

$$k_z = \frac{25}{z_1} \approx 1.32, k_n = \frac{n_{01}}{n_{ch}} \approx 1.02$$

Specifying the chain drive's working condition and ultizing table 5.6 , we find out

that 
$$k_0 = k_a = k_{dc} = k_{bt} = 1$$
,  $k_d = 1.25$ ,  $k_c = 1.3$ 

$$\Rightarrow k = k_0 k_a k_{dc} k_{bt} k_d k_c = 1.625$$

**Find** p From table 5.5:

$$[P] = P_{ch}kk_zk_n \approx 22.78 \text{ (kW)} \le 25.7 \text{ (kW)} \Rightarrow [P] = 25.7 \text{ (kW)}$$

Using the table, we also get the other parameters:

$$p = 25.4 \text{ (mm)}, d_c = 7.95 \text{ (mm)}, B = 22.61 \text{ (mm)},$$

$$d_1 = \frac{p}{\sin\frac{\pi}{z_1}} \approx 154.32 \text{ (mm)}, d_2 = \frac{p}{\sin\frac{\pi}{z_2}} \approx 784.39 \text{ (mm)}$$

#### 2.3 Find a, $x_c$ and i

Find  $x_c$   $a_{min} = 30p = 762 \text{ (mm)}$ ,  $a_{max} = 50p = 1270 \text{ (mm)}$ . Therefore, we can approximate a = 800 (mm)

$$x = \frac{2a}{p} + \frac{z_1 + z_2}{2} + \frac{(z_2 - z_1)^2 p}{4\pi^2 a} \approx 123.71 \Rightarrow x_c = 124$$

**Find** a From equation (5.13), recalculating a with  $x_c$ :

$$a = \frac{p}{4} \left( x_c - \frac{z_2 + z_1}{2} + \sqrt{\left( x_c - \frac{z_2 + z_1}{2} \right)^2 - 2 \frac{(z_2 - z_1)^2}{\pi^2}} \right) - 0.003 \cdot 800 \approx 771.66 \text{ (mm)}$$

**Find** i From table 5.9:

$$i = \frac{z_1 n_{sh2}}{15x} \approx 6 < [i] = 30$$

#### 2.4 Strength of chain drive

Choose  $k_d = 1.2, k_f = 6$ 

Given p from previous calculations, Q and q are obtained from table 5.2:

$$Q = 56.7 \times 10^3 \text{ (N)}, q = 2.6 \text{ (kg/m)}$$
  
 $v_1 = \frac{n_{ch}pz_1}{6 \times 10^4} \approx 4.71 \text{ (m/s)}$ 

**Find**  $F_t$ ,  $F_v$ ,  $F_0$  We also need to calculate  $F_t$ ,  $F_v$  and  $F_0$ 

$$F_t = \frac{10^3 P_{ch}}{v_1} \approx 2208.07 \text{ (N)}$$
$$F_v = q v_1^2 \approx 57.76 \text{ (N)}$$

$$F_0 = 9.81 \times 10^{-3} k_f qa \approx 118.09 \text{ (N)}$$

**Validate** s From equation (5.15):

$$s = \frac{Q}{k_d F_t + F_0 + F_v} \approx 20.07 \ge [s] = 10.3$$
, where [s] is chosen from table 5.10

#### 2.5 Force on shaft

Choose  $k_x = 1.15$  and follow equation (5.20):

 $F_r = k_x F_t \approx 2539.28 \, (\text{N})$ 

In su(mm)ary, we have the following table:

[P] (kW)	25.7
n (rpm)	586
$u_{ch}$	5.03
<i>z</i> <sub>1</sub>	19
$z_2$	97
p (mm)	25.4
$d_1$ (mm)	154.32
$d_2  (\mathrm{mm})$	784.39
$d_c$ (mm)	7.95
B (mm)	22.61
$x_c$	124
a (mm)	771.66
i	6

Table 2.1: Table of chain drive specifications

### **Chapter 3**

# Gearbox Design (Helix gears)

#### 3.1 Nomenclature

$[\sigma_H]$	permissible contact stress, MPa		aging factor due to contact stress
$[\sigma_F]$	permissible bending stress, MPa	$K_{FL}$	aging factor due to bending stress
$\sigma^o_{Hlim}$	permissible contact stress	$K_{FC}$	load placement factor
	corresponding to working cycle,	$K_{H\alpha}$	factor of load distribution from
	MPa		contact stress on gear teeth
$\sigma^o_{Flim}$	permissible bending stress	$K_{H\beta}$	factor of load distribution from
	corresponding to working cycle,		contact stress on top land
	MPa	$K_{Hv}$	factor of dynamic load from
$\sigma_b$	ultimate strength, MPa		contact stress at meshing area
$\sigma_{ch}$	yield limit, MPa	$K_H$	load factor from contact stress
H	surface roughness, HB	$K_{F\alpha}$	factor of load distribution from
S	length, mm		bending stress on gear teeth
$S_H$	safety factor of contact stress	$K_{F\beta}$	factor of load distribution from
$S_F$	safety factor of bending stress		bending stress on top land
$N_{HO}$	working cycle of bearing stress	$K_{Fv}$	factor of dynamic load from
	corresponding to $[\sigma_H]$		bending stress at meshing area
		$K_F$	load factor from bending stress

$N_{HE}$	working cycle of equivalent tensile	$K_d$	coefficient of gear material
	stress corresponding to $[\sigma_H]$	$Y_{\epsilon}$	meshing factor
$N_{FO}$	working cycle of bearing stress	$Y_{\beta}$	helix angle factor
	corresponding to $[\sigma_F]$	$Y_F$	tooth shape factor
$N_{FE}$	working cycle of equivalent tensile	C	gear meshing rate
	stress corresponding to $[\sigma_F]$	$a_w$	center distance, mm
AG	accuracy grade of gear	$b_w$	face width, mm
$z_M$	material's mechanical properties	d	pitch circle diameter, mm
	factor	$d_w$	rolling circle diameter, mm
$z_H$	contact surface's shape factor	$d_a$	addendum diameter, mm
$z_{\epsilon}$	meshing condition factor	$d_f$	deddendum diameter, mm
$z_{min}$	minimum number of teeth	$d_b$	base diameter, mm
	corresponding to $\beta$	$m_H$	root of fatigue curve in contact
$z_v$	equivalent number of teeth		stress test
$\epsilon_{lpha}$	horizontal meshing condition	$m_F$	root of fatigue curve in bending
	factor		stress test
$\epsilon_{eta}$	vertical meshing condition factor	m	traverse module, mm
$\alpha$	base profile angle, following	$m_n$	normal module, mm
	Vietnam standard (TCVN	v	rotational velocity, $m/s$
	1065-71), i.e. $\alpha = 20^{\circ}$	X	gear correction factor
$\alpha_t$	profile angle of a gear tooth, $^{\circ}$	y	center displacement factor
$\alpha_{tw}$	meshing profile angle, °	1	subscript for driving gear
β	helix angle, °	2	subscript for driven gear
$eta_b$	helix angle at base circle, °		
$\psi_{ba}$	width to shaft distance ratio		
$\psi_{bd}$	width to pinion diameter ratio		

#### 3.2 Choose material

From table 6.1, the material of choice for both gears is steel 40X with  $S \le 100$  mm, HB250,  $\sigma_b = 850$  MPa,  $\sigma_{ch} = 550$  MPa.

Table 6.2 also gives 
$$\sigma_{Hlim}^{o} = 2\text{HB} + 70$$
,  $S_{H} = 1.1$ ,  $\sigma_{Flim}^{o} = 1.8\text{HB}$ ,  $S_{F} = 1.75$ 

Therefore, they have the same properties except for their surface roughness H.

For the driving gear, 
$$H_1 = \text{HB250} \Rightarrow \sigma^o_{Hlim1} = 570 \,\text{MPa}, \, \sigma^o_{Flim1} = 450 \,\text{MPa}$$

For the driven gear, 
$$H_2 = \text{HB}240 \Rightarrow \sigma^o_{Hlim2} = 550 \,\text{MPa}$$
,  $\sigma^o_{Flim2} = 432 \,\text{MPa}$ 

#### **3.3** Calculate $[\sigma_H]$ and $[\sigma_F]$

#### 3.3.1 Working cycle of bearing stress

Using equation (6.5):

$$N_{HO1} = 30H_1^{2.4} = 17.07 \times 10^6$$
 cycles

$$N_{HO2} = 30H_2^{2.4} = 15.4749 \times 10^6 \text{ cycles}$$

#### 3.3.2 Working cycle of equivalent tensile stress

Since  $H_1, H_2 \le \text{HB350}, m_H = 6, m_F = 6.$ 

Both gears meshed indefinitely, thus c = 1.

Applying equation (6.7) and  $T_1$ ,  $T_2$ ,  $t_1$ ,  $t_2$  from the initial parameters:

$$N_{HE1} = 60c \left[ \left( \frac{T_1}{T} \right)^3 n_1 t_1 + \left( \frac{T_2}{T} \right)^3 n_2 t_2 \right] \approx 5.73 \times 10^6 \text{ cycles } (n_1 = n_2 = n_{sh1})$$

$$N_{HE2} = 60c \left[ \left( \frac{T_1}{T} \right)^3 n_1 t_1 + \left( \frac{T_2}{T} \right)^3 n_2 t_2 \right] \approx 1.15 \times 10^6 \text{ cycles } (n_1 = n_2 = n_{sh2})$$

$$N_{FE1} = 60c \left[ \left( \frac{T_1}{T} \right)^{m_F} n_1 t_1 + \left( \frac{T_2}{T} \right)^{m_F} n_2 t_2 \right] \approx 3.35 \times 10^6 \text{ cycles } (n_1 = n_2 = n_{sh1})$$

$$N_{FE2} = 60c \left[ \left( \frac{T_1}{T} \right)^{m_F} n_1 t_1 + \left( \frac{T_2}{T} \right)^{m_F} n_2 t_2 \right] \approx 0.67 \times 10^6 \text{ cycles } (n_1 = n_2 = n_{sh2})$$

#### **Aging factor** 3.3.3

For steel,  $N_FO = 4 \times 10^6$  MPa. Applying equation (6.3) and (6.4) yield:

$$K_{HL1} = {}^{m} \sqrt[H]{N_{HO1}/N_{HE1}} \approx 1.2$$
  
 $K_{HL2} = {}^{m} \sqrt[H]{N_{HO2}/N_{HE2}} \approx 1.54$   
 $K_{FL1} = {}^{m} \sqrt[L]{N_{FO1}/N_{FE1}} \approx 1.03$ 

$$K_{FL1} = {}^{m_{F}} \! \! / N_{FO1} / N_{FE1} \approx 1.03$$

$$K_{FL2} = \sqrt[m_F]{N_{FO2}/N_{FE2}} \approx 1.35$$

#### Calculate $[\sigma_H]$ and $[\sigma_F]$ 3.3.4

Since the motor works in one direction,  $K_{FC} = 1$ 

$$[\sigma_{H1}] = \sigma^o_{Hlim1} K_{HL1} / S_{H1} \approx 621.61 \text{ MPa}$$

$$[\sigma_{H2}] = \sigma^o_{Hlim2} K_{HL2} / S_{H2} \approx 771.63 \text{ MPa}$$

$$[\sigma_{F1}] = \sigma^o_{Flim1} K_{FC1} K_{FL1} / S_{F1} \approx 264.85 \text{ MPa}$$

$$[\sigma_{F2}] = \sigma^o_{Flim2} K_{FC2} K_{FL2} / S_{F2} \approx 332.48 \,\text{MPa}$$

$$[\sigma_{F2}] = \sigma^o_{Flim2} K_{FC2} K_{FL2} / S_{F2} \approx 332.48 \text{ MPa}$$
  
 $[\sigma_H]_{max} = \frac{1}{2} ([\sigma_{H1}] + [\sigma_{H2}]) \approx 696.62 \text{ MPa} \leq 1.25 [\sigma_H]_{min} = 1.25 [\sigma_{H1}]$ 

Permissible bending stress during overload:

$$[\sigma_F]_{max} = [\sigma_{F2}] = 0.8\sigma_{ch} \approx 440 \,\mathrm{MPa}$$

#### **Transmission Design** 3.4

#### 3.4.1 **Determine basic parameters**

Examine table 6.5 gives  $K_a = 43$ 

Assuming symmetrical design, table 6.6 also gives  $\psi_{ba} = 0.5$ 

$$\Rightarrow \psi_{bd} = 0.53 \psi_{ba} (u_{hg} + 1) = 1.59$$

From table 6.7 , using interpolation we approximate  $K_{H\beta} \approx 1.108, K_{F\beta} \approx 1.2558$ 

Since the gear system only consists of involute gears and it is also a speed reducer gearbox, we estimate  $a_w$  using equation (6.15a) before following SEV229-75 standard:

$$a_w = K_a (u_{hg} + 1) \sqrt[3]{\frac{T_{sh1} K_{H\beta}}{[\sigma_H]^2 u_{hg} \psi_{ba}}} = 83.84 \text{ mm}$$

#### 3.4.2 Determine gear meshing parameters

**Find** m Applying equation (6.17) and choose m from table (6.8):

$$m = (0.01 \div 0.02)a_w = (0.84 \div 1.68) \,\mathrm{mm} \Rightarrow m = 1.5 \,\mathrm{mm}$$

**Find**  $z_1$ ,  $z_2$ ,  $a_w$  We have  $\beta = \alpha = 20^\circ$ . Combining equation (6.18) and (6.20), we come up with the formula to calculate  $z_1$ . From the result,  $z_1$  is rounded to the nearest odd number (preferably a prime number).

$$z_1 = \frac{2a_w \cos \beta}{m(u+1)} \approx 17.51 \approx 17$$
$$z_2 = u_{hg} z_1 = 85$$

According to SEV229-75 standard, we choose  $a_w = 80 \text{ mm}$ 

$$\Rightarrow b_w = \psi_{ba} a_w = 40 \,\mathrm{mm}$$

**Find**  $x_1$ ,  $x_2$  Let  $\beta = 20^\circ$ ,  $z_{min} = 15$ . Knowing that  $y = \frac{a_w}{m} - \frac{z_1 + z_2}{2} = 0$ , we conclude  $z_1$  must not be smaller than 17 as mentioned by table 6.9. Hence, there is no need for correction ( $x_1 = x_2 = 0$ ) and  $z_1 = 17$  satisfy the condition.

Find 
$$\alpha_{tw}$$
 Since  $y = 0 \Rightarrow \alpha_{tw} = \alpha_t = \tan^{-1} \frac{\tan \alpha}{\cos \beta} \approx 21.17^{\circ} \text{ (p.105)}$ 

#### 3.4.3 Other parameters

$$\alpha_t = \tan^{-1} \frac{\tan \alpha}{\cos \beta} \approx 21.17^{\circ}$$
  $d_{f2} = d_2 - 2.5m \approx 131.93 \text{ mm}$   $d_1 = \frac{mz_1}{\cos \beta} \approx 27.14 \text{ mm}$   $d_{b1} = d_1 \cos \alpha \approx 25.3 \text{ mm}$   $d_{b2} = \frac{d_2 \cos \alpha}{\cos \beta} \approx 135.68 \text{ mm}$   $d_{a1} = d_1 + 2m \approx 30.14 \text{ mm}$   $d_{a2} = d_2 + 2m \approx 138.68 \text{ mm}$   $d_{d1} = d_1 - 2.5m \approx 23.39 \text{ mm}$   $d_{d2} = \frac{d_2 - 2.5m}{\cos \alpha} \approx 126.52 \text{ mm}$   $d_{d3} = d_2 + 2m \approx 138.68 \text{ mm}$   $d_{d3} = d_3 + 2m \approx 138.68 \text{ mm}$   $d_{d4} = d_4 - 2.5m \approx 23.39 \text{ mm}$ 

#### 3.4.4 Contact stress analysis

From section 6.3.3. in the text, contact stress applied on a gear surface must satisfy the condition below:

$$\sigma_H = z_M z_H z_\epsilon \sqrt{2T_{sh1} K_H \frac{u_{hg} + 1}{b_w u_{hg} d_{w1}^2}} \le [\sigma_H]$$
 (3.1)

**Find**  $z_M = 274$ , according to table 6.5

**Find**  $z_H$  Since correction is unused in our calculation:

$$\beta_b = \arctan(\cos \alpha_t \tan \beta) \approx 18.75^\circ \Rightarrow z_H = \sqrt{2 \frac{\cos \beta_b}{\sin(2\alpha_t)}} \approx 1.68$$

**Find**  $z_{\epsilon}$  Obtaining  $z_{\epsilon}$  through calculations:

$$\epsilon_{\alpha} = \frac{\sqrt{d_{a1}^2 - d_{b1}^2 + \sqrt{d_{a2}^2 - d_{b2}^2} - 2a_w \sin \alpha_t}}{2\pi m \frac{\cos \alpha_t}{\cos \beta}} \approx 1.64$$

$$\epsilon_{\beta} = b_w \frac{\sin \beta}{m\pi} \approx 2.9 > 1 \Rightarrow z_{\epsilon} = \epsilon_{\alpha}^{-0.5} \approx 0.78$$

**Find**  $K_H$  We find  $K_H$  using equation  $K_H = K_{H\beta}K_{H\alpha}K_{H\nu}$ 

From table 6.13,  $v \le 10 \text{ m/s} \Rightarrow AG = 8$ 

From table P2.3, using interpolation, we approximate:

$$K_{Hv} \approx 1.0417, K_{Fv} \approx 1.1145$$

From table 6.14, using interpolation, we approximate:

$$K_{H\alpha} \approx 1.0766, K_{F\alpha} \approx 1.253$$

$$\Rightarrow K_H \approx 1.24$$

**Find**  $\sigma_H$  After calculating  $z_M$ ,  $z_H$ ,  $z_\epsilon$ ,  $K_H$ , we get the following result:

$$\sigma_H \approx 699.12 \,\mathrm{MPa} \leq [\sigma_H] \approx 696.62 \,\mathrm{MPa}$$

Since  $\sigma_H$  and  $[\sigma_H]$  are almost equal to each other, i.e  $||\sigma_H - [\sigma_H]|| < 4\%$ , the assumed parameters are appropriate.

#### 3.4.5 Bending stress analysis

For safety reasons, the following conditions must be met:

$$\sigma_{F1} = 2 \frac{T_{sh1} K_F Y_{\epsilon} Y_{\beta} Y_{F1}}{b_w d_{w1} m_n} \le [\sigma_{F1}]$$

$$(3.2)$$

$$\sigma_{F2} = \frac{\sigma_{F1} Y_{F2}}{Y_{F1}} \le [\sigma_{F2}]$$
 (3.3)

**Find**  $Y_{\epsilon}$  Knowing that  $\epsilon_{\alpha} \approx 1.64$ , we can calculate  $Y_{\epsilon} = \epsilon_{\alpha}^{-1} \approx 0.61$ 

Find 
$$Y_{\beta}$$
 Since  $\beta = 20^{\circ} \Rightarrow Y_{\beta} = 1 - \frac{\beta}{140} \approx 0.86$ 

**Find**  $Y_F$  Using formula  $z_v = z \cos^{-3}(\beta)$  and table 6.18:

$$z_{v1} = z_1 \cos^{-3}(\beta) \approx 20.49 \Rightarrow Y_{F1} \approx 4.06$$

$$z_{v2} = z_2 \cos^{-3}(\beta) \approx 102.44 \Rightarrow Y_{F2} \approx 3.6$$

**Find**  $K_F$  Using  $K_{F\beta}$ ,  $K_{F\alpha}$ ,  $K_{F\nu}$  calculated from the sections above, we derive:

$$K_F = K_{F\beta}K_{F\alpha}K_{F\nu} \approx 1.75$$

**Find**  $\sigma_F$  Substituting all the values, we find out that:

$$\sigma_{F1} \approx 182.39 \, \text{MPa} \leq [\sigma_{F1}] \approx 264.85 \, \text{MPa}$$

$$\sigma_{F2} \approx 161.69 \, \text{MPa} \leq [\sigma_{F2}] \approx 332.48 \, \text{MPa}$$

The calculated results are appropriate.

Through calculations, there is no correction needed, i.e. y = 0. Thus, the specifications will not include corrections.

In summary, we have the following table:

	pinion	driving gear	
H HB	250	240	
$[\sigma_H]$ MPa	621.61	771.63	
$[\sigma_F]$ MPa	264.85	332.48	
$[\sigma_H]$ MPa	696	.62	
$\sigma_F$ MPa	182.39	161.69	
$\sigma_H$ MPa	699.12		
$\alpha_{tw}$ $^{\circ}$	21.17		
β°	20		
$a_w$ mm	80		
$b_w$ mm	40		
m mm	1.5		
Z	17	85	
d mm	27.14	135.68	
$d_a$ mm	30.14	138.68	
$d_f$ mm	23.39	131.93	
$d_b$ mm	25.3	126.52	

Table 3.1: Gearbox specifications

### **Chapter 4**

# **Shaft Design**

#### 4.1 Nomenclature

F 3			
$[\tau]$	permissible torsion, MPa	q	standardized coefficient of shaft
r	position of applied force on the		diameter
	shaft, mm	$b_O$	rolling bearing width, mm
hr	tooth direction	$l_m$	hub diameter, mm
cb	role of gear on the shaft (active or	$k_1$	distance between elements, mm
	passive)	$k_2$	distance between bearing surface
cq	rotational direction of the shaft		and inner walls of the gearbox, mm
$\sigma_b$	ultimate strength, MPa	$k_3$	distance between element surface
$\sigma_{ch}$	yield limit, MPa		and bearing lid, mm
S	safety factor	$h_n$	distance between bearing lid and
$F_{x}$	applied force, N		bolt, mm
$F_t$	tangential force, N	T	torque on shaft
$F_r$	radial force, N	$\alpha_{tw}$	meshing profile angle, °
$F_a$	axial force, N	β	helix angle, °
$a_w$	shaft distance, mm	1	subscript for shaft 1
d	shaft diameter, mm	2	subscript for shaft 2
$d_w$	gear diameter, mm	x	subscript for x-axis
	20	y	subscript for y-axis
	20	z	subscript for z-axis

#### 4.2 Choose material

For moderate load, we will use quenched steel 40X to design the shafts. From table 6.1, the specifications are as follows:  $S \le 100 \, (\text{mm})$ , HB260,  $\sigma_b = 850 \, (\text{MPa})$ ,  $\sigma_{ch} = 550 \, (\text{MPa})$ .

#### 4.3 Tranmission Design

#### 4.3.1 Load on shafts

#### **Applied forces from Gears**

Following p.186, the subscript convention of the book will be used in this chapter. If a symbol has 2 numeric subscripts, the first one is the ordinal number of shafts while the second one is used for machine elements. On shaft 1, the motor is labeled 1 and the pinion is labeled 2. On shaft 2, the driven gear is labeled 1 and the driving sprocket is labeled 2. Therefore, we obtain:

$$r_{12} = -d_{w12}/2 \approx -13.57 \text{ (mm)}, hr_{12} = +1, cb_{12} = +1, cq_1 = +1$$
  
 $r_{21} = +d_{w21}/2 \approx +67.84 \text{ (mm)}, hr_{21} = -1, cb_{21} = -1, cq_2 = -1$ 

Find magnitude of  $F_t$ ,  $F_r$ ,  $F_a$  Using the results from the previous chapter:  $\alpha_{tw} \approx 21.17^\circ$ ,  $\beta = 20^\circ$ ,  $d_{w12} \approx 27.14$  (mm)

$$\begin{cases} F_{t12} = F_{t21} = \frac{2T_{sh1}}{d_{w12}} \approx 2769.03 \text{ (N)} \\ F_{r12} = F_{r21} = \frac{F_{t12} \tan \alpha_{tw}}{\cos \beta} \approx 1141.36 \text{ (N)} \\ F_{a12} = F_{a21} = F_{t12} \tan \beta \approx 1007.84 \text{ (N)} \end{cases}$$

**Find direction of**  $F_t$ ,  $F_r$ ,  $F_a$  Following the sign convention, we obtain the forces:

$$\begin{cases} F_{x12} = \frac{r_{12}}{|r_{12}|} cq_1 cb_{12} F_{t12} \approx -2769.03 \text{ (N)} \\ F_{y12} = -\frac{r_{12}}{|r_{12}|} \frac{\tan \alpha_{tw}}{\cos \beta} F_{t12} \approx 1141.36 \text{ (N)} \\ F_{z12} = cq_1 cb_{12} hr_{12} F_{t12} \tan \beta \approx 1007.84 \text{ (N)} \end{cases}$$

$$\begin{cases} F_{x21} = \frac{r_{21}}{|r_{21}|} cq_2 cb_{21} F_{t21} \approx 2769.03 \text{ (N)} \\ F_{y21} = -\frac{r_{21}}{|r_{21}|} \frac{\tan \alpha_{tw}}{\cos \beta} F_{t21} \approx -1141.36 \text{ (N)} \\ F_{z21} = cq_2 cb_{21} hr_{21} F_{t21} \tan \beta \approx -1007.84 \text{ (N)} \end{cases}$$

#### **Applied forces from Chain drives**

Assuming the angle between x-axis and  $F_r$  is 150° and  $F_r \approx 2539.28$  (N) (chapter 2), we get the direction of  $F_r$  on shaft 2:

$$\begin{cases} F_{x22} = F_{r22} \cos 150^{\circ} \approx -2199.08 \text{ (N)} \\ F_{y22} = F_{r22} \sin 150^{\circ} \approx 1269.64 \text{ (N)} \end{cases}$$

#### 4.3.2 Preliminary calculations

Since shaft 1 receives input torque  $T_{sh1}$  and shaft 2 is produces output torque  $T_{sh2}$ ,  $[\tau_1] = 15$  (MPa) and  $[\tau_2] = 30$  (MPa). Using equation (10.9), we can approximate  $d_1$  and  $d_2$ :

$$d_1 \ge \sqrt[3]{\frac{T_{sh1}}{0.2[\tau_1]}} \approx 23.22 \text{ (mm)} \Rightarrow d_1 = 25 \text{ (mm)}$$

$$d_2 \ge \sqrt[3]{\frac{T_{sh2}}{0.2[\tau_2]}} \approx 30.99 \text{ (mm)} \Rightarrow d_2 = 35 \text{ (mm)}$$

#### 4.3.3 Identify the distance between bearings and applied forces

In this section, we will find all the parameters in Figure 4.1. However, if a parameter has 2 numeric subscripts, the first one will denote the ordinal number of shafts.

From table (10.2), we can estimate  $b_O$ . On shaft 1,  $b_{O1} = 15$  (mm). On shaft 2,

 $b_{O2}=21$  (mm). Using equation (10.10), the gear hubs are  $l_{m13}=l_{m12}=1.5d_1\approx 34.83$  (mm),  $l_{m23}=l_{m22}=1.5d_2\approx 46.48$  (mm) ( $l_{m22}$  is the chain hub)

From table (10.3), we choose  $k_1 = 10 \text{ (mm)}$ ,  $k_2 = 8 \text{ (mm)}$ ,  $k_3 = 15 \text{ (mm)}$ ,  $h_n = 18 \text{ (mm)}$ . This parameters apply for both shafts in the system.

Table (10.4) introduce the formulas for several types of gearbox. Since our system only concerns about 1-level gear reducer, the formulas below are used:

#### On shaft 2:

$$l_{22} = -l_{c22} = -[0.5(l_{m22} + b_{O2}) + k_3 + h_n] \approx -66.74 \text{ (mm)}$$
  
 $l_{23} = 0.5(l_{m23} + b_{O2}) + k_1 + k_2 \approx 55.74 \text{ (mm)}$   
 $l_{21} = 2l_{23} \approx 103.48 \text{ (mm)}$ 

#### On shaft 1:

$$l_{12} = -l_{c12} = -[0.5(l_{m12} + b_{O1}) + k_3 + h_n] \approx -57.92 \text{ (mm)}$$
  
 $l_{13} = 0.5(l_{m13} + b_{O1}) + k_1 + k_2 \approx 42.92 \text{ (mm)}$   
 $l_{11} = 2l_{13} \approx 85.83 \text{ (mm)}$ 




Figure 4.1: Shaft design and its dimensions

#### 4.3.4 Determine shaft diameters and lengths