


Issues with Housing

V0.3 - Prototype

Controller board









Controller boar doesn't fit. Ethernet port not at edge of housing

Relay Board





Board is longer than housing Mounting screws have no support in housing


Transformer board



Holes do not align with transformers

Also board doesn't fit into guide (board too thick, plus consider solder on underside)

Battery & Zigbee



This doesn't fit