
P1
Arduino
Motors
last command at t0
no valid command for 2000 ms
PWM 0, drivers disabled
PANIC (dead-man)
H (heartbeat)
timer re-armed
drivers enabled, mode READY
event: dead-man cleared
P1
Arduino
Motors