

1959 Skyliner Melissa

| | | |
|--|--|----------------------------|
| Motor and Drivetrain | Description: | |
| | Change engine oil | 50.00 |
| | Change transmission oil | 140.00 |
| | Change rear end gear oil | 200.00 |
| | Change radiator fluid and replace thermostat | 140.00 |
| | Replaced suspension springs and bushings | 650.00 |
| | Research and purchase transmission flywheel cover | 225.00 |
| | | <hr/> |
| | Total: | 1405.00 |
| | Credit: | 2000.00 |
| | Credit balance: | 595.00 |
| | | ↓ |
| Skyliner Top | Description: | |
| | Troubleshoot problem with trunk not opening | 250.00 |
| | Repair and adjust hard top mechanism | |
| | Check existing condition of retractable top motors and bushings | |
| | Check existing condition of retractable top wiring | |
| | Align and adjust rear trunk lid | |
| | | Credit balance: 345.00 |
| | | ↓ |
| Paint and Bodywork | Description: | Estimate: 15,000.00 |
| Note: all described has been completed | Redo bodywork and hand block entire car leave ready for paint | |
| | align doors, fenders and hood | Sent Check 7,500 |
| | Paint exterior of car 2 tone, door jams, inside of trunk | Sent Check 10,000.00 |
| | dash and all mouldings that require paint | Total : -15,000.00 paid |
| | Stripped and Painted metal storage unit for trunk | 2,500.00 |
| | Stripped and Painted steel wheels | 345.00 |
| | | Credit balance: 2,845.00 |
| | | ↓ |
| Stainless Exterior Mouldings and trim | Description: | |
| | Repair and Polish all damaged stainless steel mouldings and trim | |
| | Install all mouldings and trim | |
| Chrome trim and Bumpers | Description: | 2,845.00 |
| | Re-Chrome Bumpers and Straighten front and rear Bumpers | 980.00 x 2 = 1,960.00 |
| | | Credit balance: 885.00 |
| | | ↓ |
| Purchased Instrument Cluster | | 885.00 |
| | | 300.00 |
| | | Credit balance: 585.00 |
| | | ↓ |
| Electrical | Description: | |
| | Re-Wire entire electrical system | |
| | | |
| | | Credit balance: 585.00 |