

DEPARTMENT OF ELECTRICAL ENGINEERING

1. Lab Safety Requirements: All students attending High Voltage Lab and Power Electronics Lab must wear insulated non-conductive shoes and safety goggles.
2. Lab Equipment Usage: Oscilloscopes, function generators, and power analyzers must be inspected before and after experiment sessions. Any equipment damage must be reported to the lab technician immediately.