

26.04.13.세미나

최성우

Hankuk University of Foreign Studies

The Division of Computer Engineering



1. RA 알고리즘 도식화

If you check the next highest bit after the highest bit and overlap with the highest bit, the operation can be omitted, so it is omitted

13	0	0	0	0	1	1	0	1
-57	1	1	0	0	0	1	1	1
20	0	0	0	1	0	1	0	0
-11	1	1	1	1	0	1	0	1

Bit 7	Bit 6	Bit 5	Bit 4	Bit 3	Bit 2	Bit 1	Bit 0
-------	-------	-------	-------	-------	-------	-------	-------

13	0	0	0	0	1	1	0	1
-57	1	1	0	0	0	1	1	1
20	0	0	0	1	0	1	0	0
-11	1	1	1	1	0	1	0	1

Bit 7	Bit 6	Bit 5	Bit 4	Bit 3	Bit 2	Bit 1	Bit 0
-------	-------	-------	-------	-------	-------	-------	-------

13
6
4
5

average

→7

Remove Redundant column

7	0	0	0	0	1	1	1
-57	1	0	0	0	1	1	1
23	0	0	1	0	1	1	1
-9	1	1	1	0	1	1	1

Bit 6	Bit 5	Bit 4	Bit 3	Bit 2	Bit 1	Bit 0
-------	-------	-------	-------	-------	-------	-------

Column average

7	0	0	0
-57	1	0	0
23	0	0	1
-9	1	1	1

+

MetaData

6bits

0	0	0	1	1	1
---	---	---	---	---	---

→ BBS Constant

0	1
---	---

2bits

→ Number of
Redundant
columns

Bit 7	Bit 6	Bit 5	Bit 4
-------	-------	-------	-------

→ Preserve

Bit 3	Bit 2	Bit 1	Bit 0
-------	-------	-------	-------

→ Replace to
average

Bit 6	Bit 5	Bit 4
-------	-------	-------

2. ZS 알고리즘 도식화

Add optimal constant

If you check the next highest bit after the highest bit and overlap with the highest bit, the operation can be omitted, so it is omitted

Zero Skipping

81	0	1	0	1	0	0	0	1	-14 =	67
-20	1	1	1	0	1	1	0	0	-14 =	-34
1	0	0	0	0	0	0	0	1	-14 =	-13
-7	1	1	1	1	1	0	0	1	-14 =	-21

Bit	Bit	Bit	Bit	Bit	Bit	Bit	Bit
7	6	5	4	3	2	1	0

0	1	0	0	0	0	1	1
1	1	0	1	1	1	1	0
1	1	1	1	0	0	1	1
1	1	1	0	1	0	1	1

Bit	Bit	Bit	Bit	Bit	Bit	Bit	Bit
7	6	5	4	3	2	1	0

64	0	1	0	0	0	0	0	0
-32	1	1	1	0	0	0	0	0
-16	1	1	1	1	0	0	0	0
-16	1	1	1	1	0	0	0	0


Bit	Bit	Bit	Bit	Bit	Bit	Bit	Bit
7	6	5	4	3	2	1	0

78	0	1	0	0
-18	1	1	1	0
-2	1	1	1	1
-2	1	1	1	1

+

Bit	Bit	Bit	Bit
6	5	4	3

MetaData




Bit 7	Bit 6	Bit 5	Bit 4
-------	-------	-------	-------

→ Preserve

Bit 3	Bit 2	Bit 1	Bit 0
-------	-------	-------	-------

→ Replace to zero

3. SBR 도식화



4. BADA 비트 슬라이스 도식화

