







File Downloads

P1_VisualTools.pdf (4 MB)
[NOTE: When saving, if you see .tmp as the file ext, rename it to 'P1_VisualTools.pdf']

Step 2: Gather Your Materials

A visual bill of materials necessary to build the Foamcore CNC is attached to this step as a PDF. Also a sample McMaster-Carr order is attached to provide better details for the parts.



