

Main Menu

Home

USB 8 Relay BOX Drivers Instalation



KMtronic

Manuals

Software examples

Information

KMtronic projects

Other

Arduino DINo projects

Mach3 CNC software

Forum

Register

Discussion

Online Shop

USB 8 Relay BOX


Like 21




Download Drivers from:

http://sigma-shop.com/software/usb_relay/Driver_KMtronic_USB8relays_BOX_CDC.zip


UnZip in separate folder (in example D:\Driver_KMtronic_USB8relays_BOX_CDC)



Open Device Manager



Connect board to PC




You will see USB CDC COM junder "Other devices"


Click on USB CDC COM and next Update Driver...



Click on Browse my computer ...



Locate driver's holder and click Next




Click on Install this driver ...



Wait until Windows install driver

Windows will show confirmation message that drivers are installed $% \left(1\right) =\left(1\right) \left(1\right) \left$

Close and open again Device Manager to check that USB COM is now installed



Windows 8

http://dangerismymiddlename.com/archives/8913

http://www.technipages.com/windows-8-disable-driver-signing.html

