## **Testing Tasks**

## Program output for oht\_data.txt

Figure (1): Program output using oht data.txt file.

## Program output for oht short.txt

```
Please enter the file name you wish to retrieve the five variables required by the decision tree from: oht_short.txt  
Current Transfomer Explosion Count: 22
Tree Encroachment Count: 11
Crane Count: 10
Pollution Count: 20
Lightning Strike Count: 20
C:\USers\CHOO\Desktop\TSD\Assignment3\101212783_AldaltonChoo_TSD_Assignment3\Debug\101212783_AldaltonChoo_TSD_Assignment3
3.exe (process 19016) exited with code 0.
To automatically close the console when debugging stops, enable Tools->Options->Debugging->Automatically close the console when debugging stops.

Press any key to close this window . . .
```

Figure (2): Program output using oht short.txt file.

## Program output for oht long.txt




Figure (2): Program output using oht\_long.txt file.