salientPole

## «enumeration» Synchronous Machine Model Kind

subtransient subtransient Type Fsubtransient Type Jsubtransient Simplifiedsubtransient Simplified Direct Axis + rotorType: RotorKind [0..1]

+ tc: Seconds [0..1]

+ tpdo: Seconds [0..1]

+ tppdo: Seconds [0..1]

+ tppqo: Seconds [0..1]

tpqo: Seconds [0..1]

xDirectSubtrans: PU [0..1]

xDirectSync: PU [0..1]

xDirectTrans: PU [0..1]

+ xQuadSubtrans: PU [0..1]

+ xQuadSync: PU [0..1]

+ xQuadTrans: PU [0..1]

+ riq: P0 [0..1] + r2q: PU [0..1] + rfd: PU [0..1]

+ x1d: PU [0..1]

+ x1q: PU [0..1]

+ x2q: PU [0..1]

+ xad: PU [0..1]

+ xaq: PU [0..1] + xf1d: PU [0..1]

+ xfd: PU [0..1]