


Force sensor R1 with LED D1 (Component X), Switch S1 (Push Button), RPOT2 (Potentiometer)

## Schematic Diagram: (LCD, Arduino Uno, L293D Motor Driver U1)



Schematic Diagram: (Stepper Motor M1, 9V Battery (BAT1), Optical Sensor (LED D2 & Phototransistor Q1) M1 pin 1 is red, pin 2 is orange, 3 is yellow, 4 is pink, 5 is blue.

