1: ar0130 sensor 存在的光爆问题

echo 3 > /proc/isp328/ae/hi_light_supp // 压制光爆 等级 3~5 越高越黑cat /proc/isp328/ae/info

.

[Status]

frame number 31626

status AE_STS_CONVERGE

ev value 3423

1uminance current (82) pevious (82) target (100)

// 压制 之后 current (光照) 会变低

TargetY adjust -18 (max=-18)

current exposure 1/33 s

current gain 1.31 (sensor 1.31 X isp 1.00)