```
make menuconfig 选项添加

1: 在

Kconfig 里面加上
config I2C_MINING_GPIO_ENABLED

bool "enabled shenzhenmining.com hack I2C base GPIO bus"
default y
help
need i2c-mining-gpio adapter in I2C buses.
if enabled will ignore i2c-ftiic010
```

make menuconfig 就有这个选项了