

ERRI D 181/RP 6	VAMPIRE	Fig 2.2
The state of the s		115. 4.4
	HORIZONTAL TRACK IRREGULARITIES (PASSENGER)	





LATERAL IRREG. . (mm