

Release Notes: JN-AN-1243

DK006: JN5189/JN5188/K32W061/K32W041/K32W041A/K32W041AM

Zigbee 3.0 Base Device

These release notes provide information on the SDK compatibility, memory usage and change history for the JN-AN-1243 Zigbee 3.0 Base Device Application Note.

1 Public v2005 - 06-Sep-2021

Public release for DK006: JN5189 / JN5188 / K32W061 / K32W041/ K32W041A/ K32W041AM.

1.1 Public v2005: Compatibility

The software provided with this Application Note has been tested with the following evaluation kits and SDK versions. The supplied makefiles are configured to compile for K32W061 chips on the K32W061DK6 SDK which was also used to create the pre-built binaries, there is information on the main Application Note document on how to compile for different chips/SDKs.

| Product Type | Part Number | Version | Supported Chips |
|-------------------------|---|-----------------------|---|
| JN518x Development Kit | JN518x-DK006 | - | JN5189 / JN5188 |
| IoT_ZTB Development Kit | IoT_ZTB-DK006 | - | K32W061/K32W041/ K32W041A/K32W041AM |
| MPCXpresso –Toolchain | - | v11.3.0 build 5222 | JN5189 / JN5188 K32W061/K32W041/ K32W041A/K32W041AM |
| Development Kit – SDK | K32W061DK6 K32W041ADK6 K32W041AMDK6 | v2.6.4 MR3 QPATCH1 | JN5189 / JN5188 K32W061/K32W041/ K32W041A/K32W041AM |

1.2 Public v2005: Memory Usage

The applications of this Application Note have the following memory footprints:

```
text data bss dec filename
206992 3168 29960 240120 Coordinator_GpProxy_DONGLE
208088 3168 29968 241224 Coordinator_GpProxy_OM15082
222640 3184 30664 256488 Coordinator_NciIcode_NciOta_GpProxy_OM5578
208376 3168 29968 241512 Ssbl_Coordinator_GpProxy_OM15082
203200 1760 27752 232712 Router_GpProxy_OM15081
231484 2048 29940 263472 Router_NtagNwk_NtagOta_GpProxy_Ota_OM15081
213808 1864 28092 243764 Ssbl_Router_NtagNwk_GpProxy_OM15081
162796 1556 18080 182432 EndDevice_OM15082
196844 1828 20284 218956 EndDevice_NtagNwk_NtagOta_Ota_RamOpt_OM15082
173772 1652 18424 193848 Ssbl_EndDevice_NtagNwk_OM15082
```

1.3 Public v2005: End Device RAM Retention

The End Devices in this Application Note retain the following RAM during sleep:

```
retain spare kb banks filename

15416 968 16 ----567 EndDevice_OM15082

3400 696 4 -----7 EndDevice_NtagNwk_NtagOta_Ota_RamOpt_OM15082

15608 776 16 ----567 Ssbl EndDevice NtagNwk OM15082
```

1.4 Public v2005: New Features

None.

1.5 Public v2005: Bug Fixes

JIRA MCB 2674

RNG generates non-random outputs which could cause same network address allocated to different child device during commissioning.

JIRA MCZB 919

Accidental reset during device rejoin could lead to channel number change in NIB.

1.6 Public v2005: Known Issues

JIRA MCZB 710

framework flash driver limitation to K32W041AM variant.

JIRA MCZB 715

Deep Power-Down mode of the embedded MX25R8035F in K32W041AM couldn't be set correctly with framework API.

JIRA MCZB 939

New DIO wakeup mask doesn't take effect after sleep/wakeup cycle.

JIRA MCZB_919

End device channel number in NIB changes accidentally during rejoin.

JIRA MCZB 882

ZPS default confirmation is not implemented for fragmented transmission.

JIRA MCZB 996

sStackEvent.uEvent.sApsTcEvent.uTcData.pKeyDesc->au8LinkKey is not available to application.

2 Public v2004 - 20-Mar-2021

Public release for DK006: JN5189 / JN5188 / K32W061 / K32W041/ K32W041A/ K32W041AM.

2.1 Public v2004: Compatibility

The software provided with this Application Note has been tested with the following evaluation kits and SDK versions. The supplied makefiles are configured to compile for K32W061 chips on the K32W061DK6 SDK which was also used to create the pre-built binaries, there is information on the main Application Note document on how to compile for different chips/SDKs.

| Product Type | Part Number | Version | Supported Chips |
|-------------------------|---|--------------------|---|
| JN518x Development Kit | JN518x-DK006 | - | JN5189 / JN5188 |
| IoT_ZTB Development Kit | IoT_ZTB-DK006 | - | K32W061/K32W041/ K32W041A/K32W041AM |
| MPCXpresso –Toolchain | - | v11.3.0 build 5222 | JN5189 / JN5188 K32W061/K32W041/ K32W041A/K32W041AM |
| Development Kit – SDK | K32W061DK6 K32W041ADK6 K32W041AMDK6 | v2.6.3 MR3 | JN5189 / JN5188 K32W061/K32W041/ K32W041A/K32W041AM |

2.2 Public v2004: Memory Usage

The applications of this Application Note have the following memory footprints:

```
text data bss dec filename
206400 3160 29252 238812 Coordinator_GpProxy_DONGLE
207560 3160 29260 239980 Coordinator_GpProxy_OM15082
222048 3176 29956 255180 Coordinator_NciIcode_NciOta_GpProxy_OM5578
207848 3160 29260 240268 Ssbl_Coordinator_GpProxy_OM15082
202608 1756 27044 231408 Router_GpProxy_OM15081
230956 2044 29232 262232 Router_NtagNwk_NtagOta_GpProxy_Ota_OM15081
213280 1860 27384 242524 Ssbl_Router_NtagNwk_GpProxy_OM15081
161972 1564 17392 180928 EndDevice_OM15082
195956 1820 19596 217372 EndDevice_NtagNwk_NtagOta_Ota_RamOpt_OM15082
172948 1660 17736 192344 Ssbl_EndDevice_NtagNwk_OM15082
```

2.3 Public v2004: End Device RAM Retention

The End Devices in this Application Note retain the following RAM during sleep:

2.4 Public v2004: New Features

None.

2.5 Public v2004: Bug Fixes

None.

2.6 Public v2004: Known Issues

JIRA MCZB_710

framework flash driver limitation to K32W041AM variant.

JIRA MCZB 715

Deep Power-Down mode of the embedded MX25R8035F in K32W041AM couldn't be set correctly with framework API.

3 Public v2003 - 23-Dec-2020

Public release for DK006: JN5189 / JN5188 / K32W061 / K32W041.

3.1 Public v2003: Compatibility

The software provided with this Application Note has been tested with the following evaluation kits and SDK versions. The supplied makefiles are configured to compile for K32W061 chips on the K32W061DK6 SDK which was also used to create the pre-built binaries, there is information on the main Application Note document on how to compile for different chips/SDKs.

| Product Type | Part Number | Version | Supported Chips |
|-------------------------|---------------|--------------------|--------------------------------------|
| JN518x Development Kit | JN518x-DK006 | - | JN5189 / JN5188 |
| IoT_ZTB Development Kit | IoT_ZTB-DK006 | - | K32W061 / K32W041 |
| MPCXpresso –Toolchain | | v11.2.1 build 4149 | JN5189 / JN5188 K32W061 / K32W041 |
| Development Kit – SDK | K32W061DK6 | v2.6.2 MR2 | JN5189 / JN5188 K32W061 / K32W041 |

3.2 Public v2003: Memory Usage

The applications of this Application Note have the following memory footprints:

```
text data bss dec filename
205200 3160 29368 237728 Coordinator_GpProxy_DONGLE
206360 3160 29376 238896 Coordinator_GpProxy_OM15082
220848 3176 30072 254096 Coordinator_NciIcode_NciOta_GpProxy_OM5578
20648 3160 29376 239184 Ssbl_Coordinator_GpProxy_OM15082
201408 1756 27160 230324 Router_GpProxy_OM15081
229820 2044 29868 261732 Router_NtagNwk_NtagOta_GpProxy_Ota_OM15081
212080 1860 27500 241440 Ssbl_Router_NtagNwk_GpProxy_OM15081
160584 1544 17504 179632 EndDevice_OM15082
194696 1816 20244 216756 EndDevice_NtagNwk_NtagOta_Cta_RamOpt_OM15082
171560 1640 17848 191048 Ssbl_EndDevice_NtagNwk_OM15082
```

3.3 Public v2003: End Device RAM Retention

The End Devices in this Application Note retain the following RAM during sleep:

3.4 Public v2003: New Features

None.

3.5 Public v2003: Bug Fixes

None.

3.6 Public v2003: Known Issues

None.

4 Public v2002 – 21-Aug-2020

Public release for DK006: JN5189 / JN5188 / K32W061 / K32W041.

4.1 Public v2002: Compatibility

The software provided with this Application Note has been tested with the following evaluation kits and SDK versions. The supplied makefiles are configured to compile for K32W061 chips on the K32W061DK6 SDK which was also used to create the pre-built binaries, there is information on the main Application Note document on how to compile for different chips/SDKs.

| Product Type | Part Number | Version | Supported Chips |
|-------------------------|---------------|--------------------|--------------------------------------|
| JN518x Development Kit | JN518x-DK006 | - | JN5189 / JN5188 |
| IoT_ZTB Development Kit | IoT_ZTB-DK006 | - | K32W061 / K32W041 |
| MPCXpresso -Toolchain | | v11.2.0 build 4120 | JN5189 / JN5188 K32W061 / K32W041 |
| Development Kit – SDK | K32W061DK6 | v2.6.1 MR1 | JN5189 / JN5188 K32W061 / K32W041 |

4.2 Public v2002: Memory Usage

The applications of this Application Note have the following memory footprints:

```
text data bss dec filename

202368 3128 29284 234780 Coordinator_GpProxy_DONGLE

203528 3128 29292 235948 Coordinator_GpProxy_OM15082

218016 3144 29988 251148 Coordinator_NciIcode_NciOta_GpProxy_OM5578

203816 3128 29292 236236 Ssbl_Coordinator_GpProxy_OM15082

198640 1720 27076 227436 Router_GpProxy_OM15081

226988 2008 29784 258780 Router_NtagNwk_NtagOta_GpProxy_Ota_OM15081

209248 1824 27416 238488 Ssbl_Router_NtagNwk_GpProxy_OM15081

158184 1512 17424 177120 EndDevice_OM15082

192312 1800 20148 214260 EndDevice_NtagNwk_NtagOta_Cta_RamOpt_OM15082

169156 1628 17784 188568 Ssbl_EndDevice_NtagNwk_OM15082
```

4.3 Public v2002: End Device RAM Retention

The End Devices in this Application Note retain the following RAM during sleep:

4.4 Public v2002: New Features

None.

4.5 Public v2002: Bug Fixes

MCUZIGBEE-2592: EndDevice RamOpt OTA via Router : fail to rejoin and continue when Router powered off

Application now monitors ZPS_EVENT_NWK_POLL_CONFIRM message, accumulate the error and do rejoin once the errors is bigger than the threshold. Find below code in AN.

```
#ifdef SLEEP_MIN_RETENTION
```

MCB-1924: ZED sleep current is too high, should about 1.15uA for 4K RAM retention.

Update makefile to select correct mode for 32K clock. Find below code in makefile and AN.

```
CLK_32K = 1
ifeq ($(CLK_32K), 1)
CFLAGS += -DgClkUseFro32K=1
CFLAGS += -DgPWR_UseAlgoTimeBaseDriftCompensate=1
# 32k FRO automatic calibration (0 = disable, 1 = enable)
CFLAGS += -DgClkRecalFro32K=0
else
CFLAGS += -DgClkUseFro32K=0
Endif
#ifdef APP_LOW_POWER_API
static void PreSleep(void)
#else
PWRM_CALLBACK(PreSleep)
#endif
/* Minimize GPIO power consumption */
  BOARD_SetPinsForPowerMode();
}
```

4.6 Public v2002: Known Issues

None.

5 Public v2001 – 17-Apr-2020

Public release for DK006: JN5189 / JN5188 / K32W061 / K32W041.

5.1 Public v2001: Compatibility

The software provided with this Application Note has been tested with the following evaluation kits and SDK versions. The supplied makefiles are configured to compile for K32W061 chips on the K32W061DK6 SDK which was also used to create the pre-built binaries, there is information on the main Application Note document on how to compile for different chips/SDKs.

| Product Type | Part Number | Version | Supported Chips |
|-------------------------|---------------|--------------------|--------------------------------------|
| JN518x Development Kit | JN518x-DK006 | - | JN5189 / JN5188 |
| IoT_ZTB Development Kit | IoT_ZTB-DK006 | - | K32W061 / K32W041 |
| MPCXpresso -Toolchain | | v11.1.1 build 3241 | JN5189 / JN5188 K32W061 / K32W041 |
| Development Kit – SDK | K32W061DK6 | v2.6.0 RFP RC5 | JN5189 / JN5188 K32W061 / K32W041 |

5.2 Public v2001: Memory Usage

The applications of this Application Note have the following memory footprints:

```
text data bss dec filename
202912 3128 29272 235312 Coordinator_GpProxy_DONGLE
204072 3128 29280 236480 Coordinator_GpProxy_OM15082
218496 3144 29976 251616 Coordinator_NciIcode_NciOta_GpProxy_OM5578
204360 3128 29280 236768 Ssbl_Coordinator_GpProxy_OM15082
199332 1720 27064 228116 Router_GpProxy_OM15081
227700 2008 29772 259480 Router_NtagNwk_NtagOta_GpProxy_Ota_OM15081
209872 1824 27404 239100 Ssbl_Router_NtagNwk_GpProxy_OM15081
158864 1520 17424 177808 EndDevice_OM15082
192812 1796 20148 214756 EndDevice_NtagNwk_NtagOta_Cta_RamOpt_OM15082
169708 1620 17768 189096 Ssbl EndDevice NtagNwk_OM15082
```

5.3 Public v2001: End Device RAM Retention

The End Devices in this Application Note retain the following RAM during sleep:

```
retain spare kb banks filename
14712 1672 16 ----567 EndDevice_OM15082
3224 872 4 -----7 EndDevice_NtagNwk_NtagOta_Ota_RamOpt_OM15082
14920 1464 16 ----567 Ssbl EndDevice NtagNwk_OM15082
```

5.4 Public v2001: New Features

None.

5.5 Public v2001: Bug Fixes

artf734822: OTA end request error due to server power off during OTA process

When server power off then power on, device will restart the OTA, but the flash driver needs to reinit as well.

5.6 Public v2001: Known Issues

None.

6 Public v2000 - 9-Mar-2020

Public release for DK006: JN5189 / JN5188 / K32W061 / K32W041.

6.1 Public v2000: Compatibility

The software provided with this Application Note has been tested with the following evaluation kits and SDK versions. The supplied makefiles are configured to compile for JN5189 chips on the JN5189DK6 SDK which was also used to create the pre-built binaries,

there is information on the main Application Note document on how to compile for different chips/SDKs.

| Product Type | Part Number | Version | Supported Chips |
|-------------------------|---------------|--------------------|--------------------------------------|
| JN518x Development Kit | JN518x-DK006 | - | JN5189 / JN5188 |
| K32W061 Development Kit | K32W061-DK006 | - | K32W061 / K32W041 |
| MPCXpresso –Toolchain | | v11.1.0 build 3209 | JN5189 / JN5188 K32W061 / K32W041 |
| Development Kit – SDK | JN5189DK6 | v2.6.0 build 110 | JN5189 / JN5188 K32W061 / K32W041 |

6.2 Public v2000: Memory Usage

The applications of this Application Note have the following memory footprints:

```
text data bss dec filename
202760 3128 29084 234972 Coordinator_GpProxy_DONGLE
203916 3128 29092 236136 Coordinator_GpProxy_OM15082
218340 3144 29788 251272 Coordinator_NciIcode_NciOta_GpProxy_OM5578
204204 3128 29092 236424 Ssbl_Coordinator_GpProxy_OM15082
199104 1720 26876 227700 Router_GpProxy_OM15081
227408 2008 29584 259000 Router_NtagNwk_NtagOta_GpProxy_Ota_OM15081
209708 1824 27216 238748 Ssbl_Router_NtagNwk_GpProxy_OM15081
158768 1520 17248 177536 EndDevice_OM15082
192648 1800 19972 214420 EndDevice_NtagNwk_NtagOta_Cta_RamOpt_OM15082
169676 1620 17592 188888 Ssbl_EndDevice_NtagNwk_OM15082
```

6.3 Public v2000: End Device RAM Retention

The End Devices in this Application Note retain the following RAM during sleep:

```
retain spare kb banks filename
14536 1848 16 ----567 EndDevice_OM15082
3224 872 4 -----7 EndDevice_NtagNwk_NtagOta_Ota_RamOpt_OM15082
14744 1640 16 ----567 Ssbl EndDevice NtagNwk OM15082
```

6.4 Public v2000: New Features

None – first release.

6.5 Public v2000: Bug Fixes

None - first release.

6.6 Public v2000: Known Issues

None - first release.

Important Notice

How To Reach Us

Home Page:

nxp.com

Web Support:

nxp.com/support

Information in this document is provided solely to enable system and software implementers to use NXP products. There are no express or implied copyright licenses granted hereunder to design or fabricate any integrated circuits based on the information in this document. NXP reserves the right to make changes without further notice to any products herein.

NXP makes no warranty, representation, or guarantee regarding the suitability of its products for any particular purpose, nor does NXP assume any liability arising out of the application or use of any product or circuit, and specifically disclaims any and all liability, including without limitation consequential or incidental damages. "Typical" parameters that may be provided in NXP data sheets and/or specifications can and do vary in different applications, and actual performance may vary over time. All operating parameters, including "typicals," must be validated for each customer application by customer's technical experts. NXP does not convey any license under its patent rights nor the rights of others. NXP sells products pursuant to standard terms and conditions of sale, which can be found at the following address: nxp.com/SalesTermsandConditions.

While NXP has implemented advanced security features, all products may be subject to unidentified vulnerabilities. Customers are responsible for the design and operation of their applications and products to reduce the effect of these vulnerabilities on customer's applications and products, and NXP accepts no liability for any vulnerability that is discovered. Customers should implement appropriate design and operating safeguards to minimize the risks associated with their applications and products.

NXP, the NXP logo, NXP SECURE CONNECTIONS FOR A SMARTER WORLD, COOLFLUX, EMBRACE, GREENCHIP, HITAG, ICODE, JCOP, LIFE VIBES, MIFARE, MIFARE CLASSIC, MIFARE DESFire, MIFARE PLUS, MIFARE FLEX, MANTIS, MIFARE ULTRALIGHT, MIFARE4MOBILE, MIGLO, NTAG, ROADLINK, SMARTLX, SMARTMX, STARPLUG, TOPFET, TRENCHMOS, UCODE, Freescale, the Freescale logo, AltiVec, CodeWarrior, ColdFire+, the Energy Efficient Solutions logo, Kinetis, Layerscape, MagniV, mobileGT, PEG, PowerQUICC, Processor Expert, QorlQ, QorlQ Qonverge, SafeAssure, the SafeAssure logo, StarCore, Symphony, VortiQa, Vybrid, Airfast, BeeKit, BeeStack, CoreNet, Flexis, MXC, Platform in a Package, QUICC Engine, Tower, TurboLink, EdgeScale, EdgeLock, elQ, and Immersive3D are trademarks of NXP B.V.

All other product or service names are the property of their respective owners. AMBA, Arm, Arm7, Arm7TDMI, Arm9, Arm11, Artisan, big.LITTLE, Cordio, CoreLink, CoreSight, Cortex, DesignStart, DynamIQ, Jazelle, Keil, Mali, Mbed, Mbed Enabled, NEON, POP, RealView, SecurCore, Socrates, Thumb, TrustZone, ULINK, ULINK2, ULINK-ME, ULINK-PLUS, ULINKpro, µVision, Versatile are trademarks or registered trademarks of Arm Limited (or its subsidiaries) in the US and/or elsewhere. The related technology may be protected by any or all of patents, copyrights, designs and trade secrets. All rights reserved. Oracle and Java are registered trademarks of Oracle and/or its affiliates. The Power Architecture and Power.org word marks and the Power and Power.org logos and related marks are trademarks and service marks licensed by Power.org.

© NXP B.V. 2021. All rights reserved.

For more information, please visit: http://www.nxp.com

For sales office addresses, please send an email to: salesaddresses@nxp.com

Date of release: 06-Sep-2021 Document identifier: JN-AN-1243

