No ex All SendToPort Commands							
St Nc ex All SendToPort Commands							
St Nc ex All SendToPort Commands							
No ex All SendToPort Commands	tart DAO Timeout						
ex All SendToPort Commands	o retries						
	xecuteCommand()						
		Local			reset() has CommandMetac	data	
St	tart Retry loop						
		Start Rx Queue Timeout					
		executeCommand()					
			SendToPort		discoverSerial() has Comm	andMetadata 	
BlockedDataCommands							
getData()							
St	tart Retry loop	Restart Rx Queue Timeout					
		getDataBlockCount()					
			Start BlockRead loop				
				Start Retry loop	D		
					Restart DAO Timeout Restart Rx Queue Timeout		
					getDataBlock()		
					Jan and U	SendToPort	
Other ID-1-O							
SteppedDataCommands							
getConfiguration()							
	tart Module loop						
		Restart DAO Timeout					
		getModuleConfiguration()	Start Retry loop				
			Start Retry 100p	Restart DAO Timeout			
				Restart Rx Queue Timeout			
				Has CommandMetadata			
				getConfigurationBlockCount()	Start BlockRead loop		
					Start BlockRead loop	Start Retry loop	
						Ciait riony loop	Restart DAO Timeout
							Restart Rx Queue Timeou
							getConfigurationBlock()
captureSpectrum()							
St	tart Step loop						
		Start Commands loop	Otant Data da an				
			Start Retry loop	Restart DAO Timeout			
				Restart Rx Queue Timeout			
				do Step Command			
					Local OR SendToPort		
setModuleConfiguration()							
	tart BlockWrite loop						
		Start Retry loop	Destart DAO Till				
<u> </u>			Restart DAO Timeout Restart Rx Queue Timeout				
			setConfigurationBlock				
				SendToPort			
IteratedStaribusMultichannelData							
captureRealtime()							
	tart Capture loop						
		Start Retry loop					
			Restart DAO Timeout Restart Rx Queue Timeout				
 			getRealtimeData()			1	
			gotouitimoData()	SendToPort			
IteratedDataCommands							
captureContinuum()	tart Count loop	Ctart Date: las:					
captureContinuum()	tart Count loop	Start Retry loop					
	tart Count loop		Restart DAO Timeout				
captureContinuum()	tart Count loop		Restart Rx Queue Timeout				
captureContinuum()	tart Count loop		Restart Rx Queue Timeout do Iterated Command	SendToPort			
captureContinuum()	tart Count loop		Restart Rx Queue Timeout do Iterated Command	SendToPort			
captureContinuum()			Restart Rx Queue Timeout do Iterated Command				
captureContinuum()			Restart Rx Queue Timeout do Iterated Command				