


01

BEARHAWK COMPANION / WING005 · REVIEW REQUIRED

FIT TORQUE TUBE AND PAIRED ARMS



FWD




JIG POSITION MUST COME FROM FACTORY DATA

FASTENER AXES SHOWN · INVENTORY IS NOT STACK ORDER

HARDWARE

	4×	AN3-12A
	4×	AN960-10
	4×	AN365-1032A


CONNECTION DETAIL



ONE ARM EACH SIDE OF SUPPORT

? VERIFY POSITION BEFORE DRILLING

CONNECT FLAP PUSHRODS



FWD




JIG POSITION MUST COME FROM FACTORY DATA

FASTENER AXES SHOWN · INVENTORY IS NOT STACK ORDER

HARDWARE

	2×	AN3-26
	2×	AN960L-10
	2×	AN310-3
	2×	MS24665-132


CONNECTION DETAIL



INSERT PUSHROD BUSHING

SOURCE CONFLICT — VERIFY

FIT RETURN SPRINGS AND BUMPER




FWD




JIG POSITION MUST COME FROM FACTORY DATA

FASTENER AXES SHOWN · INVENTORY IS NOT STACK ORDER

HARDWARE

 **2×** W-FRS1 **2 cuts** 6000-12

CONNECTION DETAIL



SPRINGS BEFORE WING CLOSING

? VERIFY SPRING ATTACHMENTS