ESD MEASUREMENT SMT LINE

Periode : June 19th 2020

No	Station	Check Item	Standard	Result	Remark
		Resistivity			
		ESD MAT	Max - 10^8	10^5	ОК
1	PWB Destacker	Lantai ESD	Max - 10^8	10^6	OK
		Static Voltage			
		Conveyor belt	<150 volts	20 volts	ОК
_	PWB Cleaner	Static Voltage			
2		Conveyor belt	<150 volts	30 volts	ОК
		Static Voltage			
		Conveyor belt	<150 volts	25 volts	ОК
3	Conveyor after label	Conveyor belt	<150 volts	20 volts	OK
	labei	Cover Conveyor	<150 volts	25 volts	OK
		Secondary Grounding	Max - 10^8	10^6	OK
	Solder Paste	Resistivity			
	Printing	Lantai ESD	Max - 10^8	10^5	OK
		Static Voltage			
4		Conveyor belt	<150 volts	25 volts	ОК
	Conveyor	Cover conveyor	<150 volts	20 volts	ОК
		Scaner	<150 volts	30 volts	OK
		Secondary Grounding	Max - 10^8	10^5	OK
		Static Voltage			
_	Solder pasta	Conveyor belt	<150 volts	25 volts	OK
5	3D SPI	Cover Conveyor	<150 volts	30 volts	OK
		Secondary Grounding	Max - 10^8	10^5	OK
		Resistivity			
		Lantai ESD	Max - 10^8	10^5	OK
	Pick & Place	Bonding point earth	Max - 10^8	10^6	OK
6		Static Voltage			
		Conveyor belt	<150 volts	20 volts	OK
		Cover conveyor	<150 volts	30 volts	OK
		Secondary Grounding	Max - 10^8	10^6	OK
	Reflow	Static Voltage			
7		Conveyor belt	<150 volts	25 volts	OK
		Secondary Grounding	Max - 10^8	10^6	OK
	Loader AOI	Static Voltage			
		Conveyor belt	<150 volts	20 volts	OK
		Scaner	<150 volts	25 volts	OK
		Secondary Grounding	Max - 10^8	10^6	OK
		Static Voltage			
	401	Conveyor belt	<150 volts	25 volts	OK
	AOI	Cover conveyor	<150 volts	30 volts	OK
8		Secondary Grounding	Max - 10^8	10^5	OK
	AOI Loading	Static Voltage			
		Conveyor belt	<150 volts	30 volts	OK
		Magazine	<150 volts	35 volts	OK
		Lantai ESD	Max - 10^8	10^6	OK
		Secondary Grounding	Max - 10^8	10^5	OK
		Resistivity			
		ESD MAT	Max - 10^8	10^5	OK
	Meja AOI (RVS)	Static Voltage			
	' ' '	Scaner	<150 volts	25 volts	OK
		Scaner	<150 volts	25 volts	ОК

_				
	Secondary Grounding	Max - 10^8	10^6	OK

No	Station	Check Item	Standard	Result	Remark
		Static Voltage			
8	Convovor	Conveyor belt	<150 volts	25 volts	OK
	Conveyor	Cover conveyor	<150 volts	30 volts	OK
		Secondary Grounding	Max - 10^8	10^6	OK
		Static Voltage			
	Conveyor Open	Conveyor belt	<150 volts	35 volts	OK
	close	Cover conveyor	<150 volts	30 volts	OK
		Secondary Grounding	Max - 10^8	10^5	OK
		Static Voltage			
		Conveyor belt	<150 volts	20 volts	OK
9	Conveyor After Label	Conveyor belt	<150 volts	15 volts	OK
	Label	Cover conveyor	<150 volts	42 volts	OK
		Secondary Grounding	Max - 10^8	10^5	OK
	Solder Paste	Resistivity			
	Printing	Lantai ESD	Max - 10^8	10^5	OK
4.0		Conveyor belt	<150 volts	25 volts	ОК
10	Coveyor After	Cover Conveyor	<150 volts	30 volts	ОК
	Printing	Scaner	<150 volts	35 volts	ОК
		Secondary Grounding	Max - 10^8	10^5	OK
	Solder pasta	Static Voltage			
	3D SPI	Conveyor belt	<150 volts	25 volts	ОК
11		Cover conveyor	<150 volts	30 volts	OK
	Conveyor	Secondary Grounding	Max - 10^8	10^5	OK
		Resistivity			
	Pick & Place	Lantai ESD	Max - 10^8	10^5	OK
		4 bonding point earth	Max - 10^8	10^5	OK
12		Static Voltage			
		Conveyor Belt	<150 volts	25 volts	OK
	Conveyor	Cover Conveyor	<150 volts	27 volts	OK
		Secondary Grounding	Max - 10^8	10^5	ОК
	Reflow	Static Voltage			
13	Conveyor	Conveyor belt	<150 volts	25 volts	ОК
		Secondary Grounding	Max - 10^8	10^6	OK
		Static Voltage			
		Conveyor belt	<150 volts	20 volts	ОК
	Loader AOI	Scaner	<150 volts	25 volts	ОК
		Secondary Grounding	Max - 10^8	10^5	OK
		Static Voltage			
		Conveyor belt	<150 volts	25 volts	ОК
14	AOI	Cover conveyor	<150 volts	20 volts	OK
		Secondary Grounding	Max - 10^8	10^5	OK
		Static Voltage			
	AOI Loading	Conveyor belt	<150 volts	30 volts	ОК
		Cover conveyor	<150 volts	30 volts	ОК
		Magazine	<150 volts	25 volts	ОК
		Secondary Grounding	Max - 10^8	10^6	OK
		Resistivity			
		ESD MAT	Max - 10^8	10^5	ОК
, -		Static Voltage			
14	Meja AOI (RVS)	Scaner	<150 volts	30 volts	ОК
		Secondary Grounding	Max - 10^8	10^5	OK
		Lantai ESD	Max - 10^8	10^6	OK
					J.,

No	Station	Check Item	Standard	Result	Remark
	Drop In	Static Voltage			
	conveyor before seho	Belt conveyor	<150 volts	30 volts	OK
15		Jig drop in	<150 volts	25 volts	OK
		Belt conveyor	<150 volts	30 volts	OK
		Secondary Grounding	Max - 10^8	10^5	OK
	Colootius	Static Voltage			
16	Selective Solder 2	Belt conveyor	<150 volts	30 volts	OK
		Secondary Grounding	Max - 10^8	10^5	OK
		Static Voltage			
17	ICT	Belt conveyor	<150 volts	30 volts	OK
''		Jig ICT	<150 volts	25 volts	OK
		Secondary Grounding	Max - 10^8	10^5	OK
	Flashing	Static Voltage			
18		Belt conveyor	<150 volts	30 volts	OK
10		jig Flash	<150 volts	25 volts	OK
		Secondary Grounding	Max - 10^8	10^5	OK
19	Router	Jig	Max - 10^8	10^5	OK
19	Routei	Secondary Grounding	Max - 10^8	10^5	OK
	FCT	Lantai ESD	Max - 10^8	10^5	OK
20		Static Voltage			
		JIG FCT 1	<150 volts	30 volts	OK
			<150 volts	35 volts	OK
		Jig FCT 2	<150 volts	20 volts	OK
			<150 volts	20 volts	OK
		Secondary Grounding	Max - 10^8	10^6	OK

Checked	Prepared	
Ade Rukmi S.	Arif Setiawan	