


# Setup Sheet for Program 1001

## ▼ Summary

**Program comment:**  
Design document:  
nut v3  
**Product version:**  
Fusion CAM 2601.0.90  
**Created:**  
15/4/2025 11:36:07 am  
**Number of setups:** 1  
**Maximum feedrate:** 635 mm/min  
**Maximum spindle speed:** 0 rpm  
**Cutting distance:** 40.714 mm  
**Rapid distance:** 74.6 mm  
**Estimated cycle time:** 1s

**Number of operations:** 1  
**Number of tools:** 1  
**Tools:** T1  
**Maximum Z:** 5 mm  
**Minimum Z:** -12.9 mm



## ▼ Tools

**Number:** 1  
**Diameter offset:** 1  
**Tool type:** groove turning  
**Insert type:** Square  
**Width:** 3 mm  
**Nose radius:** 0.04 mm

**Relief:** N 0deg  
**Compensation:** Tip tangent  
**Tool product:**  
**Minimum Z:** -12.9 mm  
**Maximum feedrate:**  
635 mm/min  
**Maximum spindle speed:**  
0 rpm

**Cutting distance:** 40.714 mm  
**Rapid distance:** 74.6 mm  
**Estimated cycle time:** 1s  
**Holder type:** External Right  
**Holder product:**



## ▼ Setup

**Description:** Setup1  
**WCS:** 0

**Stock:**  
x: 5 mm  
y: 5 mm  
z: 14 mm  
**Part:**  
x: 5 mm  
y: 5 mm  
z: 14 mm

**Stock lower:**  
x: -2.5 mm  
y: -2.5 mm  
z: -14 mm  
**Stock upper:**  
x: 2.5 mm  
y: 2.5 mm  
z: 0 mm

## ▼ Operations

Operation 1/1

Description:

Groove Roughing1

Strategy:

turningGrooveRoughing

WCS: 0

Tolerance: 0.01 mm

Finish allowance: 0.1 mm

Maximum Z: 5 mm

Minimum Z: -12.9 mm

Maximum feedrate:

635 mm/min

Surface speed:

200000 mm/min

Feedrate per rev.: 0.127 mm

Cutting distance: 40.714 mm

Rapid distance: 74.6 mm

Estimated cycle time: 1s

Coolant: Flood

Number: 1

Diameter offset: 1

Insert type: Square

Width: 3 mm

Nose radius: 0.04 mm

Relief: N 0deg

Compensation: Tip tangent

Tool type: groove turning

Tool product:

Holder type: External Right

Holder product:

