#### Documentation



#### TABLE OF CONTENTS


► Home.md

## Home.md

## Installation

Install via Pressure Recorder Setup.exe Matlab 2024 or Matlab Runtime 2024 is needed. Run the Setup Arduino.bat script after.

## **Function**



- 1. Connect to Arduino from the menu bar: Arduino => Connect => select the folder where the Arduino CLI is installed. (e.g. C:\Arduino)
- 2. Once connected, the pressure should be permanently visible on the gauge and display.
- 3. To record the pressure over time, press Start.
- 4. Press Stop to stop recording.
- 5. Save the recorded data as a .csv file with Save.

## Circuit diagram

# Honeywell HSCDANT005PG2AS

0-5 psi (0-259 mmHg) gauge pressure (atmospheric pressure as zero point)

Protocol: I<sup>2</sup>C

