
A
Direction error $\theta$; sum of $S_1 = 0.40$
B
Direction-error vector; sum of $S_1 = 0.89$
Slow drift
Site-field curvature
Induced magnetization
Imaging pose
Loop centering
Buried extent
Sensor tilt
0.0
0.2
0.4
0.6
0.8
1.0
Sobol index (share of variance)
Total, $S_T$
First order, $S_1$