# 1. Description


### 1.1. Project

Project Name	P3-1
Board Name	P3-1
Generated with:	STM32CubeMX 4.22.0
Date	07/27/2017

### 1.2. MCU

MCU Series	STM32F1
MCU Line	STM32F103
MCU name	STM32F103RCTx
MCU Package	LQFP64
MCU Pin number	64


## 2. Pinout Configuration



# 3. Pins Configuration

Pin Number LQFP64	Pin Name (function after reset)	Pin Type	Alternate Function(s)	Label
1	VBAT	Power		
5	PD0-OSC_IN	I/O	RCC_OSC_IN	
6	PD1-OSC_OUT	I/O	RCC_OSC_OUT	
7	NRST	Reset		
12	VSSA	Power		
13	VDDA	Power		
15	PA1	I/O	TIM2_CH2	
18	VSS	Power		
19	VDD	Power		
22	PA6	I/O	TIM3_CH1	
31	VSS	Power		
32	VDD	Power		
42	PA9	I/O	USART1_TX	
43	PA10	I/O	USART1_RX	
46	PA13	I/O	SYS_JTMS-SWDIO	
47	VSS	Power		
48	VDD	Power		
49	PA14	I/O	SYS_JTCK-SWCLK	
50	PA15	I/O	SYS_JTDI	
55	PB3	I/O	SYS_JTDO-TRACESWO	
60	воото	Boot		
63	VSS	Power		
64	VDD	Power		

## 4. Clock Tree Configuration



## 5. IPs and Middleware Configuration

#### 5.1. RCC

High Speed Clock (HSE): Crystal/Ceramic Resonator

#### 5.1.1. Parameter Settings:

#### **System Parameters:**

VDD voltage (V) 3.3
Prefetch Buffer Enabled

Flash Latency(WS) 2 WS (3 CPU cycle)

**RCC Parameters:** 

HSI Calibration Value 16
HSE Startup Timout Value (ms) 100
LSE Startup Timout Value (ms) 5000

#### 5.2. SYS

Debug: JTAG (4 pins)

Timebase Source: SysTick

#### 5.3. TIM2

Clock Source: Internal Clock
Channel2: Output Compare CH2

#### 5.3.1. Parameter Settings:

#### **Counter Settings:**

Prescaler (PSC - 16 bits value) 0

Counter Mode Up

Counter Period (AutoReload Register - 16 bits value) 0

Internal Clock Division (CKD) No Division auto-reload preload Disable

#### **Trigger Output (TRGO) Parameters:**

Master/Slave Mode Disable (no sync between this TIM (Master) and its Slaves

Trigger Event Selection Reset (UG bit from TIMx\_EGR)

#### **Output Compare Channel 2:**

Mode Frozen (used for Timing base)

Pulse (16 bits value) 0
CH Polarity High

#### 5.4. TIM3

Clock Source: Internal Clock
Channel1: Output Compare CH1

#### 5.4.1. Parameter Settings:

#### **Counter Settings:**

Prescaler (PSC - 16 bits value) 0

Counter Mode Up

Counter Period (AutoReload Register - 16 bits value ) 0

Internal Clock Division (CKD)

No Division

auto-reload preload

Disable

#### **Trigger Output (TRGO) Parameters:**

Master/Slave Mode Disable (no sync between this TIM (Master) and its Slaves

Trigger Event Selection Reset (UG bit from TIMx\_EGR)

#### **Output Compare Channel 1:**

Mode Frozen (used for Timing base)

Pulse (16 bits value) 0
CH Polarity High

#### 5.5. USART1

**Mode: Asynchronous** 

#### 5.5.1. Parameter Settings:

#### **Basic Parameters:**

Baud Rate 115200

Word Length 8 Bits (including Parity)

Parity None Stop Bits 1

#### **Advanced Parameters:**

Data Direction Receive and Transmit

Over Sampling 16 Samples

#### 5.6. FREERTOS

mode: Enabled

#### 5.6.1. Config parameters:

#### **Versions:**

FreeRTOS version 9.0.0
CMSIS-RTOS version 1.02

#### Kernel settings:

USE\_PREEMPTION Enabled

CPU\_CLOCK\_HZ SystemCoreClock

 TICK\_RATE\_HZ
 1000

 MAX\_PRIORITIES
 7

 MINIMAL\_STACK\_SIZE
 128

 MAX\_TASK\_NAME\_LEN
 16

 USE\_16\_BIT\_TICKS
 Disabled

 IDLE\_SHOULD\_YIELD
 Enabled

 USE\_MUTEXES
 Enabled

USE\_MUTEXES Enabled
USE\_RECURSIVE\_MUTEXES Disabled
USE\_COUNTING\_SEMAPHORES Disabled

QUEUE\_REGISTRY\_SIZE 8

USE\_APPLICATION\_TASK\_TAG Disabled
ENABLE\_BACKWARD\_COMPATIBILITY Enabled
USE\_PORT\_OPTIMISED\_TASK\_SELECTION Enabled
USE\_TICKLESS\_IDLE Disabled
USE\_TASK\_NOTIFICATIONS Enabled

#### Memory management settings:

Memory AllocationDynamicTOTAL\_HEAP\_SIZE3072Memory Management schemeheap\_4

#### Hook function related definitions:

USE\_IDLE\_HOOK Disabled
USE\_TICK\_HOOK Disabled
USE\_MALLOC\_FAILED\_HOOK Disabled
USE\_DAEMON\_TASK\_STARTUP\_HOOK Disabled
CHECK\_FOR\_STACK\_OVERFLOW Disabled

#### Run time and task stats gathering related definitions:

GENERATE\_RUN\_TIME\_STATS Disabled
USE\_TRACE\_FACILITY Disabled
USE\_STATS\_FORMATTING\_FUNCTIONS Disabled

Co-routine related definitions:

USE\_CO\_ROUTINES Disabled MAX\_CO\_ROUTINE\_PRIORITIES 2

Software timer definitions:

USE\_TIMERS Disabled

#### Interrupt nesting behaviour configuration:

LIBRARY\_LOWEST\_INTERRUPT\_PRIORITY 15
LIBRARY\_MAX\_SYSCALL\_INTERRUPT\_PRIORITY 5

#### 5.6.2. Include parameters:

#### Include definitions:

vTaskPrioritySet Enabled uxTaskPriorityGet Enabled vTaskDelete Enabled vTaskCleanUpResources Disabled vTaskSuspend Enabled vTaskDelayUntil Disabled vTaskDelay Enabled Enabled xTaskGetSchedulerState xTaskResumeFromISR Enabled xQueueGetMutexHolder Disabled Disabled xSemaphoreGetMutexHolder pcTaskGetTaskName Disabled uxTaskGetStackHighWaterMark Disabled Disabled xTaskGetCurrentTaskHandle eTaskGetState Disabled xEventGroupSetBitFromISR Disabled xTimerPendFunctionCall Disabled xTaskAbortDelay Disabled xTaskGetHandle Disabled

#### \* User modified value

# 6. System Configuration

### 6.1. GPIO configuration

IP	Pin	Signal	GPIO mode	GPIO pull/up pull down	Max Speed	User Label
RCC	PD0- OSC_IN	RCC_OSC_IN	n/a	n/a	n/a	
	PD1- OSC_OUT	RCC_OSC_OUT	n/a	n/a	n/a	
SYS	PA13	SYS_JTMS- SWDIO	n/a	n/a	n/a	
	PA14	SYS_JTCK- SWCLK	n/a	n/a	n/a	
	PA15	SYS_JTDI	n/a	n/a	n/a	
	PB3	SYS_JTDO- TRACESWO	n/a	n/a	n/a	
TIM2	PA1	TIM2_CH2	Alternate Function Push Pull	n/a	Low	
TIM3	PA6	TIM3_CH1	Alternate Function Push Pull	n/a	Low	
USART1	PA9	USART1_TX	Alternate Function Push Pull	n/a	High *	
	PA10	USART1_RX	Input mode	No pull-up and no pull-down	n/a	

### 6.2. DMA configuration

nothing configured in DMA service

## 6.3. NVIC configuration

Interrupt Table	Enable	Preenmption Priority	SubPriority
Non maskable interrupt	true	0	0
Hard fault interrupt	true	0	0
Memory management fault	true	0	0
Prefetch fault, memory access fault	true	0	0
Undefined instruction or illegal state	true	0	0
System service call via SWI instruction	true	0	0
Debug monitor	true	0	0
Pendable request for system service	true	15	0
System tick timer	true	15	0
PVD interrupt through EXTI line 16	unused		
Flash global interrupt	unused		
RCC global interrupt	unused		
TIM2 global interrupt	unused		
TIM3 global interrupt	unused		
USART1 global interrupt	unused		

<sup>\*</sup> User modified value

# 7. Power Consumption Calculator report

#### 7.1. Microcontroller Selection

Series	STM32F1
Line	STM32F103
мси	STM32F103RCTx
Datasheet	14611_Rev12

#### 7.2. Parameter Selection

Temperature	25
Vdd	3.3

# 8. Software Project

### 8.1. Project Settings

Name	Value
Project Name	P3-1
Project Folder	C:\Users\leu19\Desktop\P3-1
Toolchain / IDE	MDK-ARM V5
Firmware Package Name and Version	STM32Cube FW_F1 V1.6.0

### 8.2. Code Generation Settings

Name	Value
STM32Cube Firmware Library Package	Copy all used libraries into the project folder
Generate peripheral initialization as a pair of '.c/.h' files	No
Backup previously generated files when re-generating	No
Delete previously generated files when not re-generated	Yes
Set all free pins as analog (to optimize the power	No
consumption)	