


## TP

## 手持式熱電偶 ( 彈簧式熱電偶 ) / ハンドヘルド熱電対 / Temperature Probe




#### 何謂熱電偶 / Thermocouple Explained

把兩種不同材質之金屬導體以電氣連接(焊接),使其產生一密閉回路,在焊接端(即溫接點)加熱產生溫差,則回路中就會有電流流動,此現象稱為席貝克效應。 如果將另一端(基準接點或稱冷接點)的溫度,保持於一定溫度(一般設定為  $0^{\circ}$ C)則可依熱電動勢值 (EMF) 之大小,而換算出溫接點這一端的溫度。此兩種成對的金屬導體,稱為"熱電偶"。 A thermocouple consists of two dissimilar conductors in contact, which produce a voltage when heated. The voltage produced is dependent on the difference of temperature of the junction to other parts of the circuit. Thermocouples are a widely used type of temperature sensor for measurement and control and can also be used to convert a temperature gradient into electricity. Thermocouples are self powered and require no external form of excitation. The main limitation with thermocouples is accuracy; system errors of less than one degree Celsius (°C) can be difficult to achieve.

### 適用領域 / Product Application

適合用於水、液體或油類品溫度量測量 Suitable for water, liquid or oil product temperature measurement.



500	C 15 100 3	Surface High temperature surface	<b>600</b> °C	155 156 156 156 156 156 156 156 156 156	Air Immerison
500	C L 6 6 L 6 17	Surface	<b>400</b> °C	130 30 + 30 + \$15 100	Flow Surface
500	20 200 130	Surface	900°C	∞ -32 - 156 -32 - 1 + 55 - 130 - 13	Air



# 補償導線的種類 / Compensation Wire Type

偶記號 Wire Type		熱電動勢 (mV)	測定溫度 範圍	優點	缺點	材料	
			Measured Temperature Range	Advantage	Shortcoming	+	-
高溫	K	-200~1200	-5.89/-200°C	1. 廣泛應用於工業 2. 抗酸性安定佳	1. 不適用 CO 及亞硫酸瓦斯中 2. 在高溫還原性空氣中會劣化	鉻	鋁、錳、
			48.8/1200°C	3. 具線性性質 4.1000℃ 以下耐氧化性良		鎳	矽等 鎳合金
	Е	-200~800	-8.82/-200°C	1. 具有最大之熱電動勢 2. 現有熱電偶中感度最佳者 3. 與 J 熱電偶相比耐熱性良好	1. 不可耐於還原性空氣中使用 2. 電氣電阻大	鉻	鎳
			61.02/800°C	4. 兩腳不具磁性 5. 適於氧化性氣體環境		鎳	銅
中溫	J	-200~350	-7.89/-200°C	1. 可耐於還原性空氣中使用 2. 熱電動勢較 K 熱電偶大 20%	1. 容易生鏽 2. 再現性不佳	鐵	鎳
			72.28/750°C	3. 價格較便宜, 適用於中溫區域			銅
	Т	-200~350	-5.6/-200°C	1. 在弱酸性、還原性空氣中很 安定 2. 熱電動勢之直線性良好	1.300°C 以上銅會氧化 2. 極限使用溫域低 3.(+) 腳之銅易氧化 4. 熱傳導誤差大	銅	鎳
低溫			17.82/350°C	3. 低溫之特性良好 4. 再現性良好高、高密度 5. 可使用於還原性氣體環境			銅
	В	500~1700	1.24/500°C	1. 能耐於酸性空氣中 2. 適用於 1000°C 至 1800°C 之 高溫測定 3. 於常溫環境下熱電動勢非常	1. 不可耐於還原性空氣中使用 2. 於中低溫域之熱電動勢極 小,600℃以下測定溫度不準 確 3. 感度不佳(熱電動勢值小) 3. 熱電動勢之直線性不佳 4. 價格高昂	銠	銠
耐高溫			12.4/1700°C	5. 於帝區壞境下熱電勤勞非常小,不需補償導線 4. 耐氧化、耐藥品性良好 5. 耐熱性與機械強度較 R 型優良		白金	白金
	R	0~1600	0/0°C		1. 感度不佳(熱電動勢值小) 2. 再還原性氣體環境較脆弱 (特別是氫、金屬蒸氣) 3. 補償導線誤差大 4. 價格高昂	銠	白金
			18.84/1600°C	1. 耐熱性、安定性、再現性良好及優越的精準度		白金	
	S		-7.89/-200°C	2. 耐氧化、耐藥品性良好 3. 可以做為標準使用		銠	白金
			72.28/750°C			白金	