27641 QA

7Ch BI Breast head Inv Coil Check 2020-04-29 14:38:58

```
Detected return code: 121
Start Coil Check
Performing Coil Check
Measure Protocol: 005 7Ch BI Breast LBR H Cor Inv sn.edb.
Measured Series Loid #1:
Local 2.0.145253817
Measured Series Loid #2:
Local 2.0.145250596
Ordered Series Loid #1:
Local 2.0.145253817
Series Loid for Evaluation 1:
Local 2.0.145253817
Number of images in series: 2
Evaluate image #1
Protocol 005_7Ch_BI_Breast_LBR_H_Cor_Inv_sn
Slice shift: 10.000000 (specified), 10.000000 (image)
Evaluation for LB1_LB2_LB3 MBR specified in ServiceCoilData.ini.
Evaluation for coil element: LB1 LB2 LB3 MBR.
SN evaluation
New Evaluation mode: 0x310 specified
S/N Results
                          = 850.0 [Specification from 400.0 to 1800.0]
- Brightness
- S/N Ratio
                            62.8 [Specification >
                                                     40.01
Applet Info:
Title: Series: 1, Image 1/2 of protocol 005 7Ch BI Breast LBR H Cor Inv sn.edb
Data type: short
Width: 256
Height: 256
Results of coil-element LB1 LB2 LB3 MBR are in Specification!
Slice shift: 10.000000 (specified), 10.000000 (image)
No Evaluation for LB1 LB2 LB3 MBR@1 specified in ServiceCoilData.ini.
Evaluate image #2
Protocol 005 7Ch BI Breast LBR H Cor Inv sn
Slice shift: 10.000000 (specified), 75.000000 (image)
No Evaluation for LB1 LB2 LB3 MBR specified in ServiceCoilData.ini.
Slice shift: 10.000000 (specified), 75.000000 (image)
No Evaluation for LB1 LB2 LB3 MBR@1 specified in ServiceCoilData.ini.
Ordered Series Loid #2:
Local 2.0.145250596
Series Loid for Evaluation 2:
Local 2.0.145250596
Number of images in series: 8
Evaluate image #1
Protocol 005_7Ch_BI_Breast_LBR_H_Cor_Inv_sn
Slice shift: 10.000000 (specified), 10.000000 (image)
Evaluation for LB1 specified in ServiceCoilData.ini.
```

```
Evaluation for coil element: LB1.
SN evaluation
New Evaluation mode: 0x1634 specified
S/N Results
                         = 551.2 [Specification from 0.0 to 0.0]
- Brightness
- S/N Ratio
                         = 37.2 [Specification >
Applet Info:
Title: Series: 2, Image 1/8 of protocol 005 7Ch BI_Breast_LBR_H_Cor_Inv_sn.edb
Data type: short
Width: 256
Height: 256
Results of coil-element LB1 are in Specification!
Slice shift: 10.000000 (specified), 10.000000 (image)
No Evaluation for LB1@1 specified in ServiceCoilData.ini.
Evaluate image #2
Protocol 005 7Ch BI Breast LBR H Cor Inv sn
Slice shift: 75.000000 (specified), 10.000000 (image)
No Evaluation for LB2 specified in ServiceCoilData.ini.
Slice shift: 75.000000 (specified), 10.000000 (image)
No Evaluation for LB2@1 specified in ServiceCoilData.ini.
Evaluate image #3
Protocol 005 7Ch BI Breast LBR H Cor Inv sn
Slice shift: 10.000000 (specified), 10.000000 (image)
Evaluation for LB3 specified in ServiceCoilData.ini.
Evaluation for coil element: LB3.
SN evaluation
New Evaluation mode: 0x1634 specified
S/N Results
- Brightness
                        = 731.4 [Specification from 0.0 to 0.0]
- S/N Ratio
                        = 61.8 [Specification > 42.0]
Applet Info:
Title: Series: 2, Image 3/8 of protocol 005 7Ch BI Breast LBR H Cor Inv sn.edb
Data type: short
Width: 256
Height: 256
Results of coil-element LB3 are in Specification!
Slice shift: 10.000000 (specified), 10.000000 (image)
No Evaluation for LB3@1 specified in ServiceCoilData.ini.
Evaluate image #4
Protocol 005 7Ch BI Breast LBR H Cor Inv sn
Slice shift: 10.000000 (specified), 10.000000 (image)
Evaluation for MBR specified in ServiceCoilData.ini.
Evaluation for coil element: MBR.
SN evaluation
New Evaluation mode: 0x310 specified
S/N Results
- Brightness
                        = 213.0 [Specification from 0.0 to 0.0]
- S/N Ratio
                        = 20.2 [Specification > 13.0]
Applet Info:
Title: Series: 2, Image 4/8 of protocol 005 7Ch BI Breast LBR H Cor Inv sn.edb
Data type:
            short
Width: 256
Height: 256
Results of coil-element MBR are in Specification!
Slice shift: 10.000000 (specified), 10.000000 (image)
No Evaluation for MBR@1 specified in ServiceCoilData.ini.
Evaluate image #5
```

```
Protocol 005 7Ch BI Breast LBR H Cor Inv sn
Slice shift: 10.000000 (specified), 75.000000 (image)
No Evaluation for LB1 specified in ServiceCoilData.ini.
Slice shift: 10.000000 (specified), 75.000000 (image)
No Evaluation for LB1@1 specified in ServiceCoilData.ini.
Evaluate image #6
Protocol 005_7Ch_BI_Breast_LBR_H_Cor_Inv_sn
Slice shift: 75.000000 (specified), 75.000000 (image)
Evaluation for LB2 specified in ServiceCoilData.ini.
Evaluation for coil element: LB2.
SN evaluation
New Evaluation mode: 0x310 specified
S/N Results
                         = 652.6 [Specification from 0.0 to 0.0]
- Brightness
- S/N Ratio
                         = 67.1 [Specification > 42.0]
Applet Info:
Title: Series: 2, Image 6/8 of protocol 005_7Ch_BI_Breast_LBR_H_Cor_Inv_sn.edb
Data type: short
Width: 256
Height: 256
Results of coil-element LB2 are in Specification!
Slice shift: 75.000000 (specified), 75.000000 (image)
No Evaluation for LB2@1 specified in ServiceCoilData.ini.
Evaluate image #7
Protocol 005_7Ch_BI_Breast_LBR_H_Cor_Inv_sn
Slice shift: 10.000000 (specified), 75.000000 (image)
No Evaluation for LB3 specified in ServiceCoilData.ini.
Slice shift: 10.000000 (specified), 75.000000 (image)
No Evaluation for LB3@1 specified in ServiceCoilData.ini.
Evaluate image #8
Protocol 005 7Ch BI Breast LBR H Cor Inv sn
Slice shift: 10.000000 (specified), 75.000000 (image)
No Evaluation for MBR specified in ServiceCoilData.ini.
Slice shift: 10.000000 (specified), 75.000000 (image)
No Evaluation for MBR@1 specified in ServiceCoilData.ini.
_____
Performing Coil Check
_____
Measure Protocol: 005 7Ch BI Breast RBR H Cor Inv sn.edb.
Measured Series Loid #1:
Local 2.0.145255867
Measured Series Loid #2:
Local 2.0.145252652
Ordered Series Loid #1:
Local 2.0.145255867
Series Loid for Evaluation 1:
Local 2.0.145255867
Number of images in series: 2
Evaluate image #1
Protocol 005 7Ch BI Breast RBR H Cor Inv sn
Slice shift: 10.000000 (specified), 10.000000 (image)
Evaluation for RB1 RB2 RB3 MBR specified in ServiceCoilData.ini.
Evaluation for coil element: RB1 RB2 RB3 MBR.
SN evaluation
New Evaluation mode: 0x310 specified
S/N Results
                       = 823.9 [Specification from 400.0 to 1800.0]
- Brightness
- S/N Ratio
                        = 61.1 [Specification > 40.0]
Applet Info:
```

```
Title: Series: 1, Image 1/2 of protocol 005 7Ch BI Breast RBR H Cor Inv sn.edb
Data type:
               short
Width: 256
Height: 256
Results of coil-element RB1_RB2_RB3_MBR are in Specification!
Slice shift: 10.000000 (specified), 10.000000 (image)
No Evaluation for RB1 RB2 RB3 MBR@1 specified in ServiceCoilData.ini.
Evaluate image #2
Protocol 005 7Ch BI Breast RBR H Cor Inv sn
Slice shift: 10.000000 (specified), 75.000000 (image)
No Evaluation for RB1 RB2 RB3 MBR specified in ServiceCoilData.ini.
Slice shift: 10.000000 (specified), 75.000000 (image)
No Evaluation for RB1 RB2 RB3 MBR@1 specified in ServiceCoilData.ini.
Ordered Series Loid #2:
Local 2.0.145252652
Series Loid for Evaluation 2:
Local 2.0.145252652
Number of images in series: 8
Evaluate image #1
Protocol 005 7Ch BI Breast RBR H Cor Inv sn
Slice shift: 75.000000 (specified), 10.000000 (image)
No Evaluation for RB1 specified in ServiceCoilData.ini.
Slice shift: 75.000000 (specified), 10.000000 (image)
No Evaluation for RB1@1 specified in ServiceCoilData.ini.
Evaluate image #2
Protocol 005_7Ch_BI_Breast_RBR_H_Cor_Inv_sn
Slice shift: 10.000000 (specified), 10.000000 (image)
Evaluation for RB2 specified in ServiceCoilData.ini.
Evaluation for coil element: RB2.
SN evaluation
New Evaluation mode: 0x1634 specified
S/N Results
- Brightness
                         = 750.0 [Specification from 0.0 to 0.0]
- S/N Ratio
                         = 57.9 [Specification > 42.0]
Applet Info:
Title: Series: 2, Image 2/8 of protocol 005 7Ch BI Breast RBR H Cor Inv sn.edb
              short
Data type:
Width: 256
Height: 256
Results of coil-element RB2 are in Specification!
Slice shift: 10.000000 (specified), 10.000000 (image)
No Evaluation for RB2@1 specified in ServiceCoilData.ini.
Evaluate image #3
Protocol 005 7Ch BI Breast RBR H Cor Inv sn
Slice shift: 10.000000 (specified), 10.000000 (image)
Evaluation for RB3 specified in ServiceCoilData.ini.
Evaluation for coil element: RB3.
SN evaluation
New Evaluation mode: 0x1634 specified
S/N Results
- Brightness
                         = 440.8 [Specification from 0.0 to 0.0]
- S/N Ratio
                            31.0 [Specification > 18.0]
Applet Info:
Title: Series: 2, Image 3/8 of protocol 005 7Ch BI_Breast_RBR_H_Cor_Inv_sn.edb
Data type:
             short
Width: 256
Height: 256
```

```
Results of coil-element RB3 are in Specification!
Slice shift: 10.000000 (specified), 10.000000 (image)
No Evaluation for RB3@1 specified in ServiceCoilData.ini.
Evaluate image #4
Protocol 005 7Ch BI Breast RBR H Cor Inv sn
Slice shift: 10.000000 (specified), 10.000000 (image)
Evaluation for MBR specified in ServiceCoilData.ini.
Evaluation for coil element: MBR.
SN evaluation
New Evaluation mode: 0x310 specified
S/N Results
- Brightness
                         = 226.0 [Specification from 0.0 to 0.0]
- S/N Ratio
                            21.0 [Specification > 13.0]
Applet Info:
Title: Series: 2, Image 4/8 of protocol 005 7Ch BI Breast RBR H Cor Inv sn.edb
Data type: short
Width: 256
Height: 256
Results of coil-element MBR are in Specification!
Slice shift: 10.000000 (specified), 10.000000 (image)
No Evaluation for MBR@1 specified in ServiceCoilData.ini.
Evaluate image #5
Protocol 005 7Ch BI Breast RBR H Cor Inv sn
Slice shift: 75.000000 (specified), 75.000000 (image)
Evaluation for RB1 specified in ServiceCoilData.ini.
Evaluation for coil element: RB1.
SN evaluation
New Evaluation mode: 0x310 specified
S/N Results
- Brightness
                         = 640.2 [Specification from
                                                        0.0 to 0.01
- S/N Ratio
                         = 63.1 [Specification >
Applet Info:
Title: Series: 2, Image 5/8 of protocol 005_7Ch_BI_Breast_RBR_H_Cor_Inv_sn.edb
Data type: short
Width: 256
Height: 256
Results of coil-element RB1 are in Specification!
Slice shift: 75.000000 (specified), 75.000000 (image)
No Evaluation for RB1@1 specified in ServiceCoilData.ini.
Evaluate image #6
Protocol 005 7Ch BI Breast RBR H Cor Inv sn
Slice shift: 10.000000 (specified), 75.000000 (image)
No Evaluation for RB2 specified in ServiceCoilData.ini.
Slice shift: 10.000000 (specified), 75.000000 (image)
No Evaluation for RB2@1 specified in ServiceCoilData.ini.
Evaluate image #7
Protocol 005 7Ch BI Breast RBR H Cor Inv sn
Slice shift: 10.000000 (specified), 75.000000 (image)
No Evaluation for RB3 specified in ServiceCoilData.ini.
Slice shift: 10.000000 (specified), 75.000000 (image)
No Evaluation for RB3@1 specified in ServiceCoilData.ini.
Evaluate image #8
Protocol 005_7Ch_BI_Breast_RBR_H_Cor_Inv_sn
Slice shift: 10.000000 (specified), 75.000000 (image)
No Evaluation for MBR specified in ServiceCoilData.ini.
Slice shift: 10.000000 (specified), 75.000000 (image)
No Evaluation for MBR@1 specified in ServiceCoilData.ini.
Results are in specification
```

Program finished successfully