## 27641 QA

## 4Ch Flex Large Coil Check 2020-04-29 14:49:31

```
Detected return code: 121
Start Coil Check
Performing Coil Check
_____
Measure Protocol: 005 4Ch FlexLarge Tra sn.edb.
Measured Series Loid #1:
Local 2.0.145256837
Measured Series Loid #2:
Local 2.0.145253678
Ordered Series Loid #1:
Local 2.0.145256837
Series Loid for Evaluation 1:
Local 2.0.145256837
Number of images in series: 1
Evaluate image #1
Protocol 005_4Ch_FlexLarge_Tra
No Evaluation for FL1 FL2 FL3 FL4 specified in ServiceCoilData.ini.
No Evaluation for FL1 FL2 FL3 FL4@1 specified in ServiceCoilData.ini.
Ordered Series Loid #2:
Local 2.0.145253678
Series Loid for Evaluation 2:
Local 2.0.145253678
Number of images in series: 4
Evaluate image #1
Protocol 005 4Ch FlexLarge Tra
Evaluation for FL1 specified in ServiceCoilData.ini.
Evaluation for coil element: FL1.
SN evaluation
New Evaluation mode: 0x310 specified
S/N Results
- Brightness
                         = 219.2 [Specification from 100.0 to 500.0]
- S/N Ratio
                            27.3 [Specification >
Applet Info:
Title: Series: 2, Image 1/4 of protocol 005 4Ch FlexLarge Tra sn.edb
Data type:
            short
Width: 256
Height: 256
Results of coil-element FL1 are in Specification!
No Evaluation for FL1@1 specified in ServiceCoilData.ini.
Evaluate image #2
Protocol 005 4Ch FlexLarge Tra
Evaluation for FL2 specified in ServiceCoilData.ini.
Evaluation for coil element: FL2.
SN evaluation
New Evaluation mode: 0x310 specified
S/N Results
- Brightness
                         = 268.2 [Specification from 0.0 to 0.0]
```

```
- S/N Ratio
                        = 31.8 [Specification > 26.0]
Applet Info:
Title: Series: 2, Image 2/4 of protocol 005 4Ch FlexLarge Tra sn.edb
Data type: short
Width: 256
Height: 256
Results of coil-element FL2 are in Specification!
No Evaluation for FL2@1 specified in ServiceCoilData.ini.
Evaluate image #3
Protocol 005 4Ch FlexLarge Tra
Evaluation for FL3 specified in ServiceCoilData.ini.
Evaluation for coil element: FL3.
SN evaluation
New Evaluation mode: 0x310 specified
S/N Results
- Brightness
                        = 282.5 [Specification from 0.0 to 0.0]
- S/N Ratio
                        = 31.0 [Specification > 26.0]
Applet Info:
Title: Series: 2, Image 3/4 of protocol 005 4Ch FlexLarge Tra sn.edb
Data type: short
Width: 256
Height: 256
Results of coil-element FL3 are in Specification!
No Evaluation for FL3@1 specified in ServiceCoilData.ini.
Evaluate image #4
Protocol 005 4Ch FlexLarge Tra
Evaluation for FL4 specified in ServiceCoilData.ini.
Evaluation for coil element: FL4.
SN evaluation
New Evaluation mode: 0x310 specified
S/N Results
- Brightness
                         = 262.6 [Specification from 0.0 to 0.0]
- S/N Ratio
                         = 30.6 [Specification > 24.0]
Applet Info:
Title: Series: 2, Image 4/4 of protocol 005 4Ch FlexLarge Tra sn.edb
Data type:
              short
Width: 256
Height: 256
Results of coil-element FL4 are in Specification!
No Evaluation for FL4@1 specified in ServiceCoilData.ini.
Results are in specification
Program finished successfully
```