Detected return code: 121

## 27641 QA

## PAMatrix feet Coil Check 2020-04-29 13:11:23

```
Start Coil Check
Performing Coil Check
Measure Protocol: 005 PAMatrix PL1 PR1 F Tra sn.edb.
Measured Series Loid #1:
Local 2.0.145223975
Measured Series Loid #2:
Local 2.0.145219792
Ordered Series Loid #1:
Local 2.0.145223975
Series Loid for Evaluation 1:
Local 2.0.145223975
Number of images in series: 2
Evaluate image #1
Protocol 005 PAMatrix PL1 PR1 F Tra sn
No Evaluation for PL1 PR1 specified in ServiceCoilData.ini.
No Evaluation for PL1 PR1@1 specified in ServiceCoilData.ini.
Evaluate image #2
Protocol 005 PAMatrix PL1 PR1 F Tra sn
No Evaluation for PL1 PR1 specified in ServiceCoilData.ini.
No Evaluation for PL1 PR1@1 specified in ServiceCoilData.ini.
Ordered Series Loid #2:
Local 2.0.145219792
Series Loid for Evaluation 2:
Local 2.0.145219792
Number of images in series: 4
Evaluate image #1
Protocol 005 PAMatrix PL1 PR1 F Tra sn
Slice shift: 10.000000 (specified), -10.000000 (image)
No Evaluation for PL1 specified in ServiceCoilData.ini.
Slice shift: 10.000000 (specified), -10.000000 (image)
No Evaluation for PL1@1 specified in ServiceCoilData.ini.
Evaluate image #2
Protocol 005 PAMatrix PL1 PR1 F Tra sn
Slice shift: -10.000000 (specified), -10.000000 (image)
Evaluation for PR1 specified in ServiceCoilData.ini.
Evaluation for coil element: PR1.
SN evaluation
New Evaluation mode: 0x310 specified
S/N Results
- Brightness
                          = 1474.4 [Specification from 750.0 to 3000.0]
- S/N Ratio
                          = 80.1 [Specification > 52.0]
Applet Info:
Title: Series: 2, Image 2/4 of protocol 005 PAMatrix PL1 PR1 F Tra sn.edb
Data type:
                short
Width: 256
Height: 256
```

```
Results of coil-element PR1 are in Specification!
Slice shift: -10.000000 (specified), -10.000000 (image)
No Evaluation for PR1@1 specified in ServiceCoilData.ini.
Evaluate image #3
Protocol 005 PAMatrix PL1 PR1 F Tra sn
Slice shift: 10.000000 (specified), 10.000000 (image)
Evaluation for PL1 specified in ServiceCoilData.ini.
Evaluation for coil element: PL1.
SN evaluation
New Evaluation mode: 0x310 specified
S/N Results
- Brightness
                         = 1312.3 [Specification from 500.0 to 3000.0]
- S/N Ratio
                         = 72.9 [Specification > 52.0]
Applet Info:
Title: Series: 2, Image 3/4 of protocol 005 PAMatrix PL1 PR1 F Tra sn.edb
Data type: short
Width: 256
Height: 256
Results of coil-element PL1 are in Specification!
Slice shift: 10.000000 (specified), 10.000000 (image)
No Evaluation for PL1@1 specified in ServiceCoilData.ini.
Evaluate image #4
Protocol 005 PAMatrix_PL1_PR1_F_Tra_sn
Slice shift: -10.000000 (specified), 10.000000 (image)
No Evaluation for PR1 specified in ServiceCoilData.ini.
Slice shift: -10.000000 (specified), 10.000000 (image)
No Evaluation for PR1@1 specified in ServiceCoilData.ini.
Detected return code: 122
Start Coil Check
_____
Performing Coil Check
_____
Measure Protocol: 005 PAMatrix PL2 PR2 F Tra sn.edb.
Measured Series Loid #1:
Local 2.0.145226027
Measured Series Loid #2:
Local 2.0.145221844
Ordered Series Loid #1:
Local 2.0.145226027
Series Loid for Evaluation 1:
Local 2.0.145226027
Number of images in series: 2
Evaluate image #1
Protocol 005 PAMatrix PL2 PR2 F Tra sn
No Evaluation for PL2 PR2 specified in ServiceCoilData.ini.
No Evaluation for PL2 PR2@1 specified in ServiceCoilData.ini.
Evaluate image #2
Protocol 005 PAMatrix PL2 PR2 F Tra sn
No Evaluation for PL2 PR2 specified in ServiceCoilData.ini.
No Evaluation for PL2 PR2@1 specified in ServiceCoilData.ini.
Ordered Series Loid #2:
Local 2.0.145221844
Series Loid for Evaluation 2:
Local 2.0.145221844
Number of images in series: 4
```

```
Evaluate image #1
Protocol 005 PAMatrix PL2 PR2 F Tra sn
Slice shift: 10.000000 (specified), -10.000000 (image)
No Evaluation for PL2 specified in ServiceCoilData.ini.
Slice shift: 10.000000 (specified), -10.000000 (image)
No Evaluation for PL2@1 specified in ServiceCoilData.ini.
Evaluate image #2
Protocol 005 PAMatrix PL2_PR2_F_Tra_sn
Slice shift: -10.000000 (specified), -10.000000 (image)
Evaluation for PR2 specified in ServiceCoilData.ini.
Evaluation for coil element: PR2.
SN evaluation
New Evaluation mode: 0x310 specified
S/N Results
- Brightness
                        = 1583.1 [Specification from 0.0 to 0.0]
- S/N Ratio
                        = 85.1 [Specification > 57.0]
Applet Info:
Title: Series: 2, Image 2/4 of protocol 005 PAMatrix PL2 PR2 F Tra sn.edb
Data type: short
Width: 256
Height: 256
Results of coil-element PR2 are in Specification!
Slice shift: -10.000000 (specified), -10.000000 (image)
No Evaluation for PR2@1 specified in ServiceCoilData.ini.
Evaluate image #3
Protocol 005 PAMatrix PL2 PR2 F Tra sn
Slice shift: 10.000000 (specified), 10.000000 (image)
Evaluation for PL2 specified in ServiceCoilData.ini.
Evaluation for coil element: PL2.
SN evaluation
New Evaluation mode: 0x310 specified
S/N Results
- Brightness
                         = 1366.9 [Specification from 0.0 to 0.0]
- S/N Ratio
                         = 85.1 [Specification > 57.0]
Applet Info:
Title: Series: 2, Image 3/4 of protocol 005 PAMatrix PL2 PR2 F Tra sn.edb
Data type:
             short
Width: 256
Height: 256
Results of coil-element PL2 are in Specification!
Slice shift: 10.000000 (specified), 10.000000 (image)
No Evaluation for PL2@1 specified in ServiceCoilData.ini.
Evaluate image #4
Protocol 005 PAMatrix PL2 PR2 F Tra sn
Slice shift: -10.000000 (specified), 10.000000 (image)
No Evaluation for PR2 specified in ServiceCoilData.ini.
Slice shift: -10.000000 (specified), 10.000000 (image)
No Evaluation for PR2@1 specified in ServiceCoilData.ini.
Detected return code: 123
Start Coil Check
_____
Performing Coil Check
_____
Measure Protocol: 005 PAMatrix PL3 PR3 F Tra sn.edb.
Measured Series Loid #1:
```

```
Local 2.0.145228079
Measured Series Loid #2:
Local 2.0.145223896
Ordered Series Loid #1:
Local 2.0.145228079
Series Loid for Evaluation 1:
Local 2.0.145228079
Number of images in series: 2
Evaluate image #1
Protocol 005 PAMatrix PL3 PR3 F Tra sn
No Evaluation for PL3 PR3 specified in ServiceCoilData.ini.
No Evaluation for PL3 PR3@1 specified in ServiceCoilData.ini.
Evaluate image #2
Protocol 005 PAMatrix PL3 PR3 F Tra sn
No Evaluation for PL3 PR3 specified in ServiceCoilData.ini.
No Evaluation for PL3 PR3@1 specified in ServiceCoilData.ini.
Ordered Series Loid #2:
Local 2.0.145223896
Series Loid for Evaluation 2:
Local 2.0.145223896
Number of images in series: 4
Evaluate image #1
Protocol 005 PAMatrix PL3 PR3 F Tra sn
Slice shift: 10.000000 (specified), -10.000000 (image)
No Evaluation for PL3 specified in ServiceCoilData.ini.
Slice shift: 10.000000 (specified), -10.000000 (image)
No Evaluation for PL3@1 specified in ServiceCoilData.ini.
Evaluate image #2
Protocol 005 PAMatrix PL3 PR3 F Tra sn
Slice shift: -10.000000 (specified), -10.000000 (image)
Evaluation for PR3 specified in ServiceCoilData.ini.
Evaluation for coil element: PR3.
SN evaluation
New Evaluation mode: 0x310 specified
S/N Results
                         = 1095.8 [Specification from 0.0 to 0.0]
- Brightness
- S/N Ratio
                         = 111.2 [Specification > 75.0]
Applet Info:
Title: Series: 2, Image 2/4 of protocol 005 PAMatrix PL3 PR3 F Tra sn.edb
Data type:
              short
Width: 256
Height: 256
Results of coil-element PR3 are in Specification!
Slice shift: -10.000000 (specified), -10.000000 (image)
No Evaluation for PR3@1 specified in ServiceCoilData.ini.
Evaluate image #3
Protocol 005_PAMatrix_PL3_PR3_F_Tra_sn
Slice shift: 10.000000 (specified), 10.000000 (image)
Evaluation for PL3 specified in ServiceCoilData.ini.
Evaluation for coil element: PL3.
SN evaluation
New Evaluation mode: 0x310 specified
S/N Results
- Brightness
                          = 1092.7 [Specification from
                                                         0.0 to 0.0]
- S/N Ratio
                         = 100.5 [Specification > 75.0]
Applet Info:
Title: Series: 2, Image 3/4 of protocol 005 PAMatrix PL3 PR3 F Tra sn.edb
Data type: short
Width: 256
```

```
Height: 256
Results of coil-element PL3 are in Specification!
Slice shift: 10.000000 (specified), 10.000000 (image)
No Evaluation for PL3@1 specified in ServiceCoilData.ini.
Evaluate image #4
Protocol 005 PAMatrix PL3 PR3 F Tra sn
Slice shift: -10.000000 (specified), 10.000000 (image)
No Evaluation for PR3 specified in ServiceCoilData.ini.
Slice shift: -10.000000 (specified), 10.000000 (image)
No Evaluation for PR3@1 specified in ServiceCoilData.ini.
Detected return code: 124
Start Coil Check
-----
Performing Coil Check
Measure Protocol: 005 PAMatrix PL4 PR4 F Tra sn.edb.
Measured Series Loid #1:
Local 2.0.145230131
Measured Series Loid #2:
Local 2.0.145225950
Ordered Series Loid #1:
Local 2.0.145230131
Series Loid for Evaluation 1:
Local 2.0.145230131
Number of images in series: 2
Evaluate image #1
Protocol 005 PAMatrix PL4 PR4 F Tra sn
No Evaluation for PL4 PR4 specified in ServiceCoilData.ini.
No Evaluation for PL4 PR4@1 specified in ServiceCoilData.ini.
Evaluate image #2
Protocol 005 PAMatrix PL4 PR4 F Tra sn
No Evaluation for PL4_PR4 specified in ServiceCoilData.ini.
No Evaluation for PL4 PR4@1 specified in ServiceCoilData.ini.
Ordered Series Loid #2:
Local 2.0.145225950
Series Loid for Evaluation 2:
Local 2.0.145225950
Number of images in series: 4
Evaluate image #1
Protocol 005 PAMatrix PL4 PR4 F Tra sn
Slice shift: 10.000000 (specified), -10.000000 (image)
No Evaluation for PL4 specified in ServiceCoilData.ini.
Slice shift: 10.000000 (specified), -10.000000 (image)
No Evaluation for PL4@1 specified in ServiceCoilData.ini.
Evaluate image #2
Protocol 005_PAMatrix_PL4 PR4 F Tra sn
Slice shift: -10.000000 (specified), -10.000000 (image)
Evaluation for PR4 specified in ServiceCoilData.ini.
Evaluation for coil element: PR4.
SN evaluation
New Evaluation mode: 0x310 specified
S/N Results
- Brightness
                         = 840.7 [Specification from
                                                         0.0 to
                                                                 0.01
- S/N Ratio
                          = 92.1 [Specification > 65.0]
Applet Info:
Title: Series: 2, Image 2/4 of protocol 005 PAMatrix PL4 PR4 F Tra sn.edb
```

Data type: short Width: 256 Height: 256 Results of coil-element PR4 are in Specification! Slice shift: -10.000000 (specified), -10.000000 (image) No Evaluation for PR4@1 specified in ServiceCoilData.ini. Evaluate image #3 Protocol 005 PAMatrix PL4 PR4 F Tra sn Slice shift: 10.000000 (specified), 10.000000 (image) Evaluation for PL4 specified in ServiceCoilData.ini. Evaluation for coil element: PL4. SN evaluation New Evaluation mode: 0x310 specified S/N Results - Brightness = 753.5 [Specification from 0.0 to 0.0] - S/N Ratio = 90.8 [Specification > Applet Info: Title: Series: 2, Image 3/4 of protocol 005 PAMatrix PL4 PR4 F Tra sn.edb Data type: short Width: 256 Height: 256 Results of coil-element PL4 are in Specification! Slice shift: 10.000000 (specified), 10.000000 (image) No Evaluation for PL4@1 specified in ServiceCoilData.ini. Evaluate image #4 Protocol 005 PAMatrix PL4 PR4 F Tra sn Slice shift: -10.000000 (specified), 10.000000 (image) No Evaluation for PR4 specified in ServiceCoilData.ini. Slice shift: -10.000000 (specified), 10.000000 (image) No Evaluation for PR4@1 specified in ServiceCoilData.ini. Results are in specification Program finished successfully