27641 QA

4Ch Shoulder Coil Check 2020-04-29 15:12:55

```
Detected return code: 121
Start Coil Check
Performing Coil Check
_____
Measure Protocol: 005 ShoulderArray all Tra sn.edb.
Measured Series Loid #1:
Local 2.0.145264022
Measured Series Loid #2:
Local 2.0.145258812
Ordered Series Loid #1:
Local 2.0.145264022
Series Loid for Evaluation 1:
Local 2.0.145264022
Number of images in series: 1
Evaluate image #1
Protocol 005 ShoulderArray all Tra sn
No Evaluation for SH1 SH2 SH3 SH4 specified in ServiceCoilData.ini.
No Evaluation for SH1 SH2 SH3 SH4@1 specified in ServiceCoilData.ini.
Ordered Series Loid #2:
Local 2.0.145258812
Series Loid for Evaluation 2:
Local 2.0.145258812
Number of images in series: 4
Evaluate image #1
Protocol 005 ShoulderArray_all_Tra_sn
Evaluation for SH1 specified in ServiceCoilData.ini.
Evaluation for coil element: SH1.
SN evaluation
New Evaluation mode: 0x1515 specified
S/N Results
- Brightness
                         = 903.4 [Specification from 350.0 to 1400.0]
- S/N Ratio
                            64.2 [Specification > 45.0]
Applet Info:
Title: Series: 2, Image 1/4 of protocol 005 ShoulderArray all Tra sn.edb
Data type:
            short
Width: 256
Height: 256
Results of coil-element SH1 are in Specification!
No Evaluation for SH1@1 specified in ServiceCoilData.ini.
Evaluate image #2
Protocol 005 ShoulderArray all Tra sn
Evaluation for SH2 specified in ServiceCoilData.ini.
Evaluation for coil element: SH2.
SN evaluation
New Evaluation mode: 0x1515 specified
S/N Results
- Brightness
                         = 968.5 [Specification from 0.0 to 0.0]
```

```
- S/N Ratio
                        = 67.3 [Specification > 40.0]
Applet Info:
Title: Series: 2, Image 2/4 of protocol 005 ShoulderArray all Tra sn.edb
Data type: short
Width: 256
Height: 256
Results of coil-element SH2 are in Specification!
No Evaluation for SH2@1 specified in ServiceCoilData.ini.
Evaluate image #3
Protocol 005 ShoulderArray all Tra sn
Evaluation for SH3 specified in ServiceCoilData.ini.
Evaluation for coil element: SH3.
SN evaluation
New Evaluation mode: 0x1515 specified
S/N Results
- Brightness
                        = 1215.7 [Specification from 0.0 to 0.0]
- S/N Ratio
                        = 81.1 [Specification > 45.0]
Applet Info:
Title: Series: 2, Image 3/4 of protocol 005 ShoulderArray all Tra sn.edb
Data type: short
Width: 256
Height: 256
Results of coil-element SH3 are in Specification!
No Evaluation for SH3@1 specified in ServiceCoilData.ini.
Evaluate image #4
Protocol 005 ShoulderArray_all_Tra_sn
Evaluation for SH4 specified in ServiceCoilData.ini.
Evaluation for coil element: SH4.
SN evaluation
New Evaluation mode: 0x310 specified
S/N Results
                         = 586.8 [Specification from 0.0 to 0.0]
- Brightness
- S/N Ratio
                         = 56.8 [Specification > 40.0]
Applet Info:
Title: Series: 2, Image 4/4 of protocol 005 ShoulderArray all Tra sn.edb
Data type:
             short
Width: 256
Height: 256
Results of coil-element SH4 are in Specification!
No Evaluation for SH4@1 specified in ServiceCoilData.ini.
Results are in specification
Program finished successfully
```