Detected return code: 121

27641 QA

Neck Matrix Coil Check 2020-04-29 16:10:06

```
Start Coil Check
Performing Coil Check
_____
Measure Protocol: 005 NeckMatrix all Tra sn.edb.
Measured Series Loid #1:
Local 2.0.145276320
Measured Series Loid #2:
Local 2.0.145272164
Ordered Series Loid #1:
Local 2.0.145276320
Series Loid for Evaluation 1:
Local 2.0.145276320
Number of images in series: 1
Evaluate image #1
Protocol 005 NeckMatrix all Tra sn
No Evaluation for NE1 NE2 specified in ServiceCoilData.ini.
No Evaluation for NE1 NE2@1 specified in ServiceCoilData.ini.
Ordered Series Loid #2:
Local 2.0.145272164
Series Loid for Evaluation 2:
Local 2.0.145272164
Number of images in series: 2
Evaluate image #1
Protocol 005 NeckMatrix all Tra sn
Evaluation for NE1 specified in ServiceCoilData.ini.
Evaluation for coil element: NE1.
SN evaluation
New Evaluation mode: 0x310 specified
S/N Results
- Brightness
                         = 1057.3 [Specification from 500.0 to 2000.0]
- S/N Ratio
                         = 70.5 [Specification > 60.0]
Applet Info:
Title: Series: 2, Image 1/2 of protocol 005 NeckMatrix all Tra sn.edb
Data type:
            short
Width: 256
Height: 256
Results of coil-element NE1 are in Specification!
No Evaluation for NE1@1 specified in ServiceCoilData.ini.
Evaluate image #2
Protocol 005 NeckMatrix all Tra sn
Evaluation for NE2 specified in ServiceCoilData.ini.
Evaluation for coil element: NE2.
SN evaluation
New Evaluation mode: 0x310 specified
S/N Results
                         = 907.7 [Specification from 0.0 to 0.0]
- Brightness
```

= 78.1 [Specification > 60.0] - S/N Ratio Applet Info:

Title: Series: 2, Image 2/2 of protocol 005_NeckMatrix_all_Tra_sn.edb

Data type: short

Width: 256 Height: 256

Results of coil-element NE2 are in Specification!

No Evaluation for NE2@1 specified in ServiceCoilData.ini.

Results are in specification Program finished successfully