Service Software Page 1 of 4

Quality Assurance (04-May-2020, 11:35:32, #141814)

Coil Check FlexLarge_4 Success (04-May-2020, 11:35:33 » 04-May-2020, 11:39:52)

Comments (0)

#	Timestamp	Comment
No comments for this function.		

Summary

Summary

	Status
098_FlexLarge_4_Tra	OK
Program Result	Success

Details


Protocol: 098_FlexLarge_4_Tra

Coil Info

Coil ID	Serial Number	Part Number
FlexLarge_4	32187	10185552

Coil: FL1

Signal



S/N

Parabola Fit	
Value Min	
30.0	23.0

Brightness

Service Software Page 2 of 4


Parabola Fit		
Value	Min	Max
325	125	500

Homogeneity and Transmitter Amplitude

Variable	Value	Unit
Transmitter Amplitude	289	V

Coil: FL2

Signal



S/N

Parabola Fit	
Value Min	
35.7	25.0

Brightness

Parabola Fit 375


Homogeneity and Transmitter Amplitude

Variable	Value	Unit
Transmitter Amplitude	289	V

Coil: FL3

Signal

Service Software Page 3 of 4



S/N

Parabola Fit	
Value	Min
29.7	25.0

Brightness


Parabola	Fit
;	328

Homogeneity and Transmitter Amplitude

Variable	Value	Unit
Transmitter Amplitude	289	V

Coil: FL4

Signal



S/N

Parabola Fit	
Value	Min
34.6	25.0

Service Software Page 4 of 4

Brightness

Parabola	Fit
3	868

Homogeneity and Transmitter Amplitude

Variable	Value	Unit
Transmitter Amplitude	289	V