Task name	Progress		10 Feb						1 / Feb	
○ Readme.md	Complete	Mon 2/ 10 Readme.md	Tue 2/ 11	Wed 2/ 12	Thu 2/ 13	Fri 2/ 14	Sat 2/ 15	Sun 2/ 16	Mon 2/ 17	Tue 2/ 18
○ Code.pdf	0%								Code.pdf	
⊡ 🖶 Program 1: FB-RUN	0%			Program 1: FB-					couc.pui	
	0%			main.c						
□ 💼 main.c				Timer.h						
◯ Timer.h	0%									
◯ Timer.c	0%			Timer.c						
○ GPIO.h	0%			GPIO.h						
◯ GPIO.c	0%			GPIO.c						
○ Create LED.c	0%			Create LED.c						
	0%			Create LED.h						
() makefile	0%			makefile						
□ 🖶 Program 2: FB-DEBUG	0%				Program 2: FB-					
□ 💼 main.c	33%				main.c					
Add Logging messa	0%				Add Logging me					
Add Logging messa	0%				Add Logging me					
Add Logging messa	0%				Add Logging me					
	0%				log.h					
○ log.c	0%				log.c					
🖃 💼 Program 3: PC-RUN	0%					Program 3: PC-				
	0%					makefile				
⊡ 💼 main.c	0%					main.c				
🕔 new task	0%					new task				
🕔 new task	0%					new task				
Create Timer.h	0%					Create Timer.h				
○ Create Timer.c	0%					Create Timer.c				
	0%					Create LED.h				
○ Create LED.c	0%					Create LED.c				
□ 🖶 Program 4: PC-DEBUG	0%								Program 4: PC	
⊟ 🖶 main.c	0%								main.c	
Add Logging messa	0%								Add Logging me	
Add Logging messa	0%								Add Logging me	
Add Logging messa	0%								Add Logging me	
⊙ log.c	0%								log.c	
◯ log.h	0%								log.h	
() makefile	0%								makefile	
Makelile	U%								такете	