

INSPECTION REPORT

Evaluated By: ALOK CHAUDHARY
Inspection Date: Wed Dec 03 2025

Reg. No. BHSHAN62727HSHE

Vehicle Details

Engine Info

Manufacturer:	HAHABBA
Chassis No.	BSNJA827JSJSHBHH
Chassis Number Embossing:	Repunched
Engine Number:	WBJ828
Engine CC:	250
Year Of Manufacturing:	2010
Car Type:	SEDAN
Model Name:	UAHAAH
Variant Name:	WUUSHAHAAH
Colour:	Non-Metallic
Paint Type:	Non-Metallic
Transmission:	Manual
Emission:	Euro 3
Date of Registration:	2018-12-03
Odometer Reading:	250
Fuel Type:	Petrol + CNG
External CNG/LPG Fitment:	No
No. of Owners:	1
Duplicate Key Available:	No
VIN Plate Available:	Yes
Jack & Toolkit Available:	No
Spare Wheel Available:	Yes
Insurance Type:	Third Party
Insurance Valid Upto:	2025-12-05

RC Details

Name on RC:	Bahgsgs
Phone Number:	9645458484
Address:	Bsbscsghsksk
Email ID:	Jsha@sns.sjs
Profession:	Proprietor / Business
RC Availability:	Duplicate
RC Condition:	Broken Chip
Mismatch on RC:	Details Mismatch

Registration Details

Registration State:	West Bengal
Registration City:	Calcutta
RC NOC Issued:	N/A
Registration Valid:	No
Road Tax Paid:	Limited Period
Commercial Vehicle:	No
Under Hypothecation:	Yes
RTO:	WB26

Engine Inspection Report

Working Condition

Engine:	No
Radiator:	No
Silencer:	No
Starter Motor:	Yes
Engine Oil Level:	No
Coolant Availability:	Yes
Engine Mounting:	No
Battery:	Yes

Noise/Leakage

Engine Oil Leakage:	Yes
Coolant Oil Leakage:	No
Abnormal Noise:	Yes
Black Smoke/White Smoke:	No
Defective Belts:	No
Highlight Positives:	
Other Comments:	

Functions

Is in proper condition?

Steering:	Yes
Suspension:	No
Brake:	No
Gear Shifting:	Yes
Drive Shaft/ Axle:	Yes
Clutch:	No

Noise/Leakage

Wheel Bearing Noise:	Yes
Gear Box Noise:	No
Differential Noise:	Yes
Transmission/ Differential Oil Leakage:	No

Positives:

Other Comments:

Frames

Any Damage In?

Front

Bonnet Support Member:	Yes
Cross Member:	No
Lamp Support:	Yes
Left Apron:	Yes
Right Apron:	Yes

Pillars

Left A-Pillar:	Yes
Left A-Pillar Details:	No
Left B-Pillar:	Yes
Left B-Pillar Details:	Already Repaired
Left C-Pillar:	Yes
Left C-Pillar Details:	Yes
Right A-Pillar:	No
Right A-Pillar Details:	Yes
Right B-Pillar:	No
Right B-Pillar Details:	No
Right C-Pillar:	No
Right C-Pillar Details:	No

Rear

Rear Left Quarter Panel:	No
Rear Left Quarter Panel Details:	Yes
Rear Right Quarter Panel:	To Be Repaired
Rear Right Quarter Panel Details:	Yes

Dickey:

Positives:

Other Comments:

Exterior

Tyre Thread Count

Front Right:	Average (2-6mm)
Front Left:	Bad (<2mm)
Rear Right:	Average (2-6mm)
Rear Left:	Average (2-6mm)
Spares:	Normal Rim
Wheel Type:	No
Repaint Done:	No

Interior Inspection

Available

Seat Cover:	No
Sun Roof:	Yes
Car Antenna:	No
No. of Power Windows:	2
No. of Airbags:	3

Working

Power Windows:	No
Air Bags:	Yes
Parking Brake Lever:	No
Horn:	Yes
Instrument Cluster:	No
Wiper:	Yes
Head Lamp:	Yes
Tail Lamp:	No
Fog Lamp:	Yes
Cabin Light:	Yes
Blinker Light:	Yes
Seat Belts:	Yes
AC Effectiveness:	Non-Effective
AC Grill Efficiency:	Average (7-14°C)
Climate Control AC:	No
Heater:	N/A
ORVM:	No
Steering Mounted Controls:	Yes
ABS:	Yes
Reverse Parking Sensors:	No
Reverse Camera:	No
Keyless/Center Locking:	N/A
Keyless/Center Locking Details:	Yes
Music System:	No
Music System Details:	Yes

Test Drive

Additional Remarks:
Drive Details
KM Driven:
Time Taken:
Driving Experience:
Incomplete Test Drive (Reason):

Average
Issue with vehicle

Problems

Engine
Gear Shifting

Refurbishment Cost Estimate

Engine Refurbishment Cost:	1250
Functions Refurbishment Cost:	120
Frames Refurbishment Cost:	0
Exterior Refurbishment Cost:	50
Tyre/Wheel Refurbishment Cost:	250
Interior Refurbishment Cost:	100

Documents Cost

Insurance Cost:	0
Pollution Cost:	0
Registration/ Doc Cost:	0

Other Refurbishment Cost

Spare Keys:	0
Interior Cleaning:	0
Accessories Repair:	0
Popular Work Demand:	100
Rubbing & Polishing:	0
Total RF Cost	1875

Interior & Odometer Images

Chassis

Insurance

RC Back

RC Front

Tax

Engine Image

Left Rear Edge (No Scratch)

Front Bumper (Minor Scratch)

Left Front Edge (No Scratch)

Roof Front (Major