
One dead sensor: filled = clean, open = mean over sensors, bar = worst sensor
T1 misalignment
T2 unbalance
T3 bearings
T4 ten states
C1 COMFAULDA
RF
RF robust (5b)
MLP
XGBoost
CNN (order spectra)
CNN robust (5b)
OS-FNO A (no speed)
OS-FNO B (speed in head)
OS-FNO E (physical speed)
0.4
0.6
0.8
0.2
macro-F1