

## **MEEG 311 – Lecture 25 Vibration and Control**

## Ioannis Poulakakis 29 November 2018

## Goals:

- Basic terms for sketching Bode (magnitude & phase) diagrams:
  - Pure gain
  - Pole at the origin (integrator) / zero at the origin (differentiator)
  - Real pole / real zero
  - Pair of complex poles / pair of complex zeros
- Example of sketching the Bode diagrams using asymptotes of the basic terms

