
PCB Layout, Bottom Layer 1:1



BE SURE TO PRINT AT 100% SCALE

Gnusbuino

Open Source USB Sensor Board by Michael Egger, [anyma] gnusb.sourceforge.net

Version 2013-12-03

Drills & Parts placement, solder side

Drills: 0.8mm unless otherwise noted

