201803010 Ahranet Cign Oden 7 # floor the Chain. h >
# floor the purity, NOPROTECT
# use dolay (clock = 4000000) unsigned intropy warme =0; # int - times 2 void tiner2-leasure () 3 Output-lou (pin-do); void main () Set\_ tris\_a(0x01); Set - tris d (0x00); Output - d (0x00); Stup-tiner 2 (To. DIV, By 16, 250, 1) enable-interrupts (int-timer 2); enable - interrupts (global) if (input ( Pin\_a0); 3 3