

OT Incident Triage Report

Alert	Modbus Replay Attack
Source	192.168.86.46
Destination	192.168.86.49
Protocol	Modbus TCP (port 502)
Function Code	05 (Write Single Coil)
Suspected Behavior	Unauthorized Message: Command Message (T1692.001)
Potential Operational Impact	Poses a risk to public health due to unsafe water
Recommended Response	Ask the operator or engineer to verify the state of the affected device. Once deemed safe to do, block traffic from source to destination, while preserving PCAPs and investigating source device.
Escalation Path	OT Analyst -> Senior OT Analyst -> OT Security Manager -> Control Systems Engineer -> CISO / Plant Manager