## .0 Introduction

While these have been used by the author and others extensively, it is expected that alternative approaches may prove very successful. Indeed, it is to be hoped that many new and significant advances in ECM process technology will be made in the next decade.

Some coverage, although in less depth, will also be given to other significant aspects of the process such as its fundamental theory, machinery and its installation, economics, electrochemistry, and so on. Again, the emphasis will be on only the information necessary for proper understanding and application of the process.

There are, of course, many specialized aspects of the process, and others of purely academic interest, that could provide absorbing reading; these are not included in this book. Such information would detract from the basic process technology, essential to successful physical handling of the process, and the basis for sound business judgement as to its use.

### CHAPTER

# Fundamental Principles of the Process

of negatively and positively charged ions may not necessarily be equal. The negative charges equal exactly the positive charges but the numbers atom or a group of atoms bearing one or more units of electrical charge throughout the solution. These are known as "ions" and may be a single positively and negatively charged particles which move independently solved in water. In the presence of water, salt crystals split into small Electrolytes may consist of acids or, more generally, of basic salts diselectrochemical machining, as precipitated solids of the metal hydroxide. body of the electrolyte as positive ions, or which is more normal in complex mechanism at the surface of the anode, can appear in the main detaches from the anode surface atom by atom, and after a somewhat the surface of the negative electrode, called the "cathode." The metaelectrodes, the greatest volume being hydrogen which is evolved from in the ECM process. Gases are also produced at the surfaces of the at the positive electrode, or "anode"; this is the basis of metal removal cally through the electrolyte and in so doing carry the current. The the material, "ions," electrically charged groups of atoms, migrate physitrical circuit and also brings about the phenomenon of metal dissolution transfer of electrons between the ions and electrodes completes the elecin a metal, in which only the electrons move through the structure of one electrode to the other. Unlike the conduction of an electric current immersed in an electrolyte, current flows through the electrolyte from When a voltage is applied between two metal electrodes which are

The application of a potential between immersed electrodes sets up an electric field that cause migration of the ions as shown in Figure




Figure 2.1 Simple electrolytic cell showing movement of ions

electrolysis of the water. In this reaction the water molecule gains elecof an applied electric field. The intense potential gradient between the hydroxyl ions. trons from the cathode so that it separates into free hydrogen gas and concentration of positive ions and the adjacent cathode surface causes 2.1. The circles represent the distribution of the ions under the influence

$$2H_2O + 2e \rightarrow H_2 + 2OH^-$$

by positive metal ions entering the electrolyte as the anode dissolves. The introduction of hydroxyl negative ions is electrically balanced

$$2\text{Fe} - 2e \rightarrow \text{Fe}^{2+}$$

used, but combine with the hydroxyl ions to form the metal hydroxide no longer affects the electrochemical reactions Since this is insoluble in water it appears as a solid precipitate and Metal ions do not remain in solution when neutral electrolytes are

$${\rm Fe^{2+} + 2H_2O \rightarrow Fe(OH)_2 + 2H^+}$$

been successfully put to work in industry in such familiar fields as elec-Faraday and obeying his famous laws of electrolysis.\* Electrolysis has fully in numerous other books, stemming out of the original work by troplating, electroforming, and electropolishing. The interest in the first This process is another aspect of electrochemistry, as explained more

electropolishing, it is the dissolution of metal from the anode surface etc.), while, in the second, the original cathode is dissolved away so very far short of ECM in both rate and control of the metal removal. smooth surface on the anode. This process has most in common with that is of interest and which, if properly controlled, leaves a bright that the plated shell of metal forms the final article. In the last process, ECM, since controlled metal removal is the important feature, but falls ions become captive and thus form a skin of new metal. The first is two is in the reaction which occurs at the cathode surface where metallic for decorative or corrosion protection purposes (car bumpers, table ware,

a tew amperes per square inch (psi) of electrode surface]; and metal facing the cathode, metal removal also occurs on its other surface. flow. While there is preferential metal removal from the anode surface removal or deposition is correspondingly small. In Figure 2.2 the lines widely spaced electrodes in tanks of almost static electrolyte. Electrojoining the remotely spaced electrodes indicate the distribution of current lytes are also of a specialized nature; small currents are used [only All these well-used processes, based on electrolysis, are operated using

is dependent upon the applied voltage which provides the motivating trode. The rate at which they can arrive at their respective electrodes tively charged ions are attracted to the positively charged anode eleccharged ions are attracted to the negatively charged cathode and negaions in the electrolyte will migrate towards the electrodes. Positively tion, and a potential of 20 V (volts) is applied between them. The remote from one another, are placed very close at about 0.020-in. separa-Consider, however, what happens if the two electrodes, instead of being




Figure 2.2 Simple electrolytic cell showing distribution of current flow.

<sup>\*</sup>The amount of chemical change produced by an electric current, that is, the amount of any substance deposited or dissolved is proportional to the quantity of current passed

of the electrolyte solution; and the length of the path that the ions spacing under consideration the potential gradient will be very high voltage gradient, hence the motivating forces. In the very small gap So that the smaller the distance between the electrodes, the greater the determined by the voltage gradient rather than just the applied voltage. must follow to reach the electrode. The motivating force is more precisely force; the number of ions present which increase with the concentration surface 0.010 to 0.100 in./min. current will be 100 to 1000 A/in.2 and metal removal from the anode and migration of the ions proportionately fast. The correspondingly high

electrodes, the shape produced resembles that of the cathode. anode after a period of ECM. It can be seen that, even with stationary and direction of current flow is indicated by lines joining the electrodes metal removal from the anode. The dotted line shows the shape of the The smaller the gap, the greater will be the current flow and rate of Electrodes in close proximity are shown in Figure 2.3. The density

be continuously and rigorously removed. This is achieved by circulating rates of metal removal, these products of the machining process must tain continuous rather than transient high current densities and high come a barrier to the electrolyzing current after a few seconds. To mainand gas bubbles in the small spacing between the electrodes. These be-The high current density promotes rapid generation of hydroxide solids




Figure 2.3 Distribution of current flow between closely spaced electrodes.




Figure 2.4 Fundamental elements of ECM.

of 25 to 500 psi to achieve suitable flow velocities. In practice the electrolyte is channeled into the gap at supply pressures electrolyte at a high velocity through the gap between the electrodes.

progressively attains a shape that is almost an exact replica of the will remain constant and current and metal removal rate will remain same rate at which the metal is being dissolved, then the gap spacing current falls as the gap, hence its electrical resistance, increases. An high. This is shown in Figure 2.4. As the cathode advances the anode initial high value. If the cathode is moved towards the anode at the additional variable is required to maintain the current density at its first but then at a progressively decreasing rate. This is because the removal from the anode. The original gap increases in size rapidly at The forced circulation of the electrolyte permits continued fast metal

í

cept of ECM. movement of one electrode towards the other. They form the basic conare forced high velocity circulation of the electrolyte and controlled Thus the two new concepts that make high metal removal rate possible

of the cathode towards the anode, ultimately the two surfaces will closely the rate of metal removal. It is evident that, with progressive movement of the electrodes, the higher will be the current density and greater smaller the gap spacing at various points between confronting surfaces the cathode electrode surface to all surfaces of the anode electrode. The of high metal removal rate. Current is conducted from all surfaces of ECM to machine a component accurately in addition to its capability At this point it is appropriate to consider the mechanism that permits




Figure 2.5 Electrochemical machine and auxiliary systems. (Courtesy of the Anocut Engineering Company.)

correspond. In fact, for reasons which will be explained more fully later, the surfaces differ by a small predictable amount that can be corrected by adjusting the cathode shape. What is important is that repeatable shapes are produced.

The process is really a very simple one, but requires specially engineered equipment for its use as a manufacturing tool. In broad categories, an EC machine consists of an electrolyte system which provides high velocity electrolyte flow between the electrodes; an electrical power system which supplies the electrolyzing current to the electrodes; and a mechanical structure which locates and provides movement of the electrodes. These systems are shown diagramatically in Figure 2.5. Aspects of their engineering, and the way in which these relate to the fundamental principles of ECM, will be discussed in the following sections.

# 2.1 THE ELECTROLYTE SYSTEM

High velocity electrolyte flow over the electrode surfaces is one of the key factors that separates ECM from other electrolytic processes. The high velocity limits ion concentration at the electrode surfaces and, in turn, permits passage of higher machining currents; an important

factor is dilution of the electrochemical reaction products, including heat dissipated by passage of the electrolyzing current. Velocities required are 100 to 200 ft/sec and so high pressures, 80 to 400 psi, are needed to force the electrolyte through the small machining gaps. Flow rates are dependent on the size of components to be machined, and so, pump capacities of 300 gal/min are not uncommon for machining components larger, for example, than a 12-in.-dia. turbine wheel. The electrolyte is circulated from the pump through the tooling, to exhaust into the work enclosure of the machine and then return, by gravity, to a storage tank.

clogged and restrict the flow of electrolyte to the tooling. any appreciable depth are not suitable, because they rapidly become do not readily become clogged with metal hydroxides. Filter media of corrosion resistant, and because of the short flow path through the mesh, a single weave of stainless steel (type 316) or monel wire. These are 0.010 in., is suitable for performing most work. The best are those of mately 0.0035 in.) filter, adequate for operation at gap sizes down to greater than one third the machining gap size. A 75- $\mu$  (micron) (approxivital feature of an EC machine. The filter prevents passage of particles wanted particles from reaching the tooling and therefore, is another tive. A wire mesh filter, placed in the supply pipe, prevents these unto both the tool and work surfaces. Thus electrolyte cleanliness is imperaparticles short circuit the electrolyzing current between the electrodes. cles carried by the electrolyte. Another problem occurs when metallic of the work. Such blockages in the gap are caused by nonmetallic partiand to control accuracy. This gap must always remain clear, however, The local heating and sparking that results can produce serious damage locally the flow velocity, a condition not conducive to smooth dissolution to allow smooth passage of the electrolyte. Any blockage will reduce The machining gap is small to obtain high rates of metal removal

i

Electrolyte properties also influence the size of the machining gap that, together with the tool shape, determine the geometry of the finally machined component. Variation of the electrolyte parameters—composition, concentration, pH (degree of alkalinity or acidity), temperature, and concentration of solids—will affect the accuracy of machining. Therefore, these are closely controlled. While a small quantity of metal hydroxides, introduced during machining, does not significantly affect the process, large proportions, if permitted to accumulate, do reduce efficiency and ultimately lead to process failure. Hydroxide in the electrolyte is limited by continuous removal using large settling tanks or centrifuges. Control of composition, concentration, and pH is achieved by adding either water or chemicals to the electrolyte, following periodic

analysis of check samples. These properties are important because they affect either the conductivity of the electrolyte, hence the electrical resistance within the machining gap, or the electrochemical reactions taking place at the electrode surfaces.

The electrolyte is also temperature controlled. The temperature affects the chemical activity and the electrical resistivity of the electrolyte. Both are factors in determining the machining gap, hence the final work contour.

# The Electrical Power System

Very large, direct currents are used in ECM. Current densities of 100 to 1500 A/in.² on the electrode surfaces are typical for industrial applications of the process, although much higher values, about 5000 A/in.², are sometimes used.\* Experimentally, currents of 50,000 A/in.² have been achieved. In terms of metal removal, 1 in.³ is removed by 10,000 A/min. This convenient relationship is surprisingly accurate for most metals. Potentials of 5 to 25 V, applied across the tool and work electrodes, are required to circulate these currents through the resistive machining gap. Voltage must also be closely controlled, since it is a factor in determining the size of the machining gap, hence the accuracy of the work contour.

Electrical power systems have DC outputs up to 40,000 A, but 10,000 A units are the popular size. These transform and rectify standard high voltage, 3-phase, AC supply to a smooth DC output at closely regulated voltage. The output may be set to any voltage, within the range of the machine, to suit a particular machining operation. Heavy cables or copper bus bars are used to carry the large machining current from the power unit to the work enclosure of the machine. The power system also includes protective devices to switch the power off in the event of process malfunction, and the electrical control circuits for all the equipment comprising the machine.

Strength and rigidity of ECM fixtures, tooling, and machines are comparative with machines used for mechanical metal removal. This is because high pressures are necessary to force the large volume flow of electrolyte through the small gap between the tool and work surfaces. Containment of the electrolyte, over the large working areas of tools, produces high separating forces. At a pressure of 300 psi, acting over 30 in.<sup>2</sup> (this is a typical area which might be machined on a 10,000-A

machine), the separating force is 9000 lb. Also, other nonoperative areas of the tooling may be subject to high electrolyte pressures. Even larger forces occur with tool vibration. This is because the momentary reduction in the machining gap throttles the flow, causing a large surge in pressure. This effect, often known as water hammer, produces self-excited vibration of the tooling. This leads to loss of process control and, more often, complete process failure. Strength and rigidity in the equipment best ensure against such a problem.

Smooth tool movement towards the work is also a requirement to maintain a stable machining gap. The process is slow to adjust following a sudden change in any of the controlling parameters, so that sudden or jerky movements of the tool cause sudden changes in the machining gap. Perhaps 10 sec or so will elapse while the gap adjusts back to its steady-state value. If a sudden movement closes the machining gap too much, process failure occurs.

For these reasons, EC machines are substantially constructed and have robust precision tool feed systems.

## 2.2 SUMMARY

The ECM facility comprises a rigid machine structure with means for smoothly moving the tools, DC power supply unit, electrolyte tanks, pump, filters, and electrolyte cleaning equipment. These are only the necessary pieces of equipment; their close control of the machining parameters, together with good tooling, and overall process planning, makes ECM an effective manufacturing process.

<sup>\*</sup>The amounts of different substances deposited or dissolved by the same quantity of electricity are proportional to their chemical equivalent weights.