

当前文件在印刷时是有效的。更新的版本可以在线获得。

WM 375855 更换自动变速箱油滤清器

更换自动变速箱油滤清器

更换自动变速箱油滤清器

- 1. 自动变速箱油滤清器只能与自动变速箱油底壳一起更换。 → 375519 拆卸和安装自动变速箱油底壳

982120, 982121, 982130, 982131, 982140, 982141, 982150, 982151, 982320, 982321, 982330, 982331, 982340, 982341, 982350, 982351

年款 起始时间 2017
C00, C02, C05, C06, C07, C08, C09, C10, C11, C12, C13, C14, C15, C16, C17, C18, C19, C20, C21, C22, C23, C24, C25, C26, C27, C28, C32, C33, C34, C35, C36, C37, C38, C39, C41, C45, C45, C46, C96, C97, C98, C99

baochi123D

baochimingcheservice@gmail.com

Aug 23, 2019

