

当前文件在印刷时是有效的。更新的版本可以在线获得。

WM 465402 检查后 PCCB 制动盘 (磨损评估)

检查后 PCCB 制动盘

检查后 PCCB 制动盘



信息

检查后制动盘的方法与前桥上使用的方法相同。

1. 检查 PCCB 制动盘。 → 465102 检查前 PCCB 制动盘 (磨损评估)

982120, 982121, 982130, 982131, 982140, 982141, 982150, 982151, 982320, 982321, 982330, 982331, 982340, 982341, 982350, 982351

年款 起始时间 2017

C00, C02, C05, C06, C07, C08, C09, C10, C11, C12, C13, C14, C15, C16, C17, C18, C19, C20, C21, C22, C23, C24, C25, C26, C27, C28, C32, C33, C34, C35, C36, C37, C38, C39, C41, C45, C45, C46, C96, C97, C98, C99

baochi123D

baochimingcheservice@gmail.com

Aug 23, 2019

