

当前文件在印刷时是有效的。更新的版本可以在线获得。

WM 5X00IN 空腔防腐


附加零件



信息

- 维修时，必须根据以下图示，对车身附件涂抹标准空腔防护材料。
- 在完成所需的装配工作前，请勿采用空腔防护。

车门



车门空腔防锈


未喷漆的车身壳体



信息


- 如下图所示，采用标准的空腔防护。
- 在修理接合区域也要采用空腔防护。
- 在完成所需的喷漆和装配工作前，请勿采用空腔防护。

上部车身前部




上部车身前部

汽车前端底部





侧梁




侧梁

后端底部



后端顶部



982120, 982121, 982130, 982131, 982140, 982141, 982150, 982151, 982320, 982321, 982330, 982331, 982340, 982341, 982350, 982351, 982510, 982511

年款 起始时间 2017
C00, C02, C05, C06, C07, C08, C09, C10, C11, C12, C13, C14, C15, C16, C17, C18, C19, C20, C21, C22, C23, C24, C25, C26, C27, C28, C32, C33, C34, C35, C36, C37, C38, C39, C41, C45, C45, C46, C96, C97, C98, C99