

当前文件在印刷时是有效的。更新的版本可以在线获得。

WM 921555 更换雨刷器电机

更换雨刷器电机

更换雨刷器电机



信息

目前，雨刷器电机不作为单个部件提供。它只能与雨刷器连杆一起更换。

1. 更换雨刷器连杆。 → 921919 *拆卸和安装雨刷器连杆*

982120, 982121, 982130, 982131, 982140, 982141, 982150, 982151, 982320, 982321, 982330, 982331, 982340, 982341, 982350, 982351, 982510, 982511, 982810, 982811

年款 起始时间 2017

C00, C02, C05, C06, C07, C08, C09, C10, C11, C12, C13, C14, C15, C16, C17, C18, C19, C20, C21, C22, C23, C24, C25, C26, C27, C28, C32, C33, C34, C35, C36, C37, C38, C39, C41, C45, C45, C46, C96, C97, C98, C99

baochi123D

baochimingcheservice@gmail.com

Aug 23, 2019

